Submit 3 Copies To Appropriate District	State of New 1	Mexico	Form C-103
Office District I	nergy, Minerals and N	atural Resources	Revised March 25, 1999
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.
District II	District II 11 South First, Artesia, NM 88210 OIL CONSERVATION DIVISION		30-025-24568
District III	1220 South St. Francis Dr.		5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410		•	STATE 🗆 FEE 🔀
District IV	Santa Fe, NM	8/303	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			
SUNDRY NOTIC	ES AND REPORTS ON WEL		7. Lease Name or Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSA DIFFERENT RESERVOIR. USE "APPLICA"	LS TO DRILL OR TO DEEPEN OR TION FOR PERMIT" (FORM C-101	PLUG BACK TO A VEOR SUCH	
PROPOSALS.)	TION FOR FERMIT (FORWIC-10)	TOR SCEN	Downes D
1. Type of Well:			
Oil Well 🖾 Gas Well 🗀	Other		
2. Name of Operator			8. Well No. #4
The Wiser Oil Company			
3. Address of Operator			9. Pool name or Wildcat
8115 Preston Rd., Suite 400, Dallas,	TX 75225		Tubb
4. Well Location			
Unit Letter M_:	660feet from theSo	uth line and	810feet from theWestline
	m 1: 01	D	PTE NIMBNA Lee Country
Section 32	Township 215		NMPM Lea County
	10. Elevation (Show whether	DR, KKB, KI, GK, etc	2.)
	3464'	Natura of Nation	Domant on Other Date
	propriate Box to Indicate		
NOTICE OF <u>IN</u> T		i i	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR	K \square ALTERING CASING \square
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DR	ILLING OPNS. PLUG AND ABANDONMENT
		CACINIC TEST A	
DULL OR ALTER CASING	MILITIPIE	LASING IPSTA	
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TEST A	
PULL OR ALTER CASING	MULTIPLE LJ COMPLETION	CEMENT JOB	_
PULL OR ALTER CASING OTHER:		•	_
OTHER:	COMPLETION	OTHER: Plugbac	ck 🗵
OTHER: 12. Describe proposed or completed	COMPLETION I operations. (Clearly state all	OTHER: Plugbace	ck give pertinent dates, including estimated date
OTHER: 12. Describe proposed or completed of starting any proposed work).	COMPLETION I operations. (Clearly state all	OTHER: Plugbace	ck 🗵
OTHER: 12. Describe proposed or completed	COMPLETION I operations. (Clearly state all	OTHER: Plugbace	ck give pertinent dates, including estimated date
OTHER: 12. Describe proposed or completed of starting any proposed work).	COMPLETION I operations. (Clearly state all SEE RULE 1103. For Multip	OTHER: Plugbace	ck give pertinent dates, including estimated date
OTHER: 12. Describe proposed or completed of starting any proposed work). or recompletion.	COMPLETION I operations. (Clearly state all SEE RULE 1103. For Multip	OTHER: Plugbace	ck give pertinent dates, including estimated date
OTHER: 12. Describe proposed or completed of starting any proposed work). or recompletion. 8/27/90 – Perforate Tubb f/ 6161-624 9/4/90 – Pull rods and tubing	COMPLETION I operations. (Clearly state all SEE RULE 1103. For Multip	CEMENT JOB OTHER: Plugbac pertinent details, and g e Completions: Attac	ck give pertinent dates, including estimated date h wellbore diagram of proposed completion
OTHER: 12. Describe proposed or completed of starting any proposed work). or recompletion. 8/27/90 – Perforate Tubb f/ 6161-624 9/4/90 – Pull rods and tubing	COMPLETION I operations. (Clearly state all SEE RULE 1103. For Multip	CEMENT JOB OTHER: Plugbac pertinent details, and g e Completions: Attac	ck give pertinent dates, including estimated date
OTHER: 12. Describe proposed or completed of starting any proposed work). or recompletion. 8/27/90 – Perforate Tubb f/ 6161-624 9/4/90 – Pull rods and tubing 9/6/90 – Set CIBP @ 6360' w/ 35' c.	COMPLETION I operations. (Clearly state all SEE RULE 1103. For Multip 18') ement to plug off Drinkard. Pl	CEMENT JOB OTHER: Plugbac pertinent details, and ge Completions: Attack BTD = 6325.' Acidize	ck give pertinent dates, including estimated date h wellbore diagram of proposed completion
OTHER: 12. Describe proposed or completed of starting any proposed work). or recompletion. 8/27/90 – Perforate Tubb f/ 6161-624 9/4/90 – Pull rods and tubing 9/6/90 – Set CIBP @ 6360' w/ 35' consealers.	COMPLETION I operations. (Clearly state all SEE RULE 1103. For Multip 18') ement to plug off Drinkard. Pl	CEMENT JOB OTHER: Plugbac pertinent details, and ge Completions: Attack BTD = 6325.' Acidize	ck give pertinent dates, including estimated date h wellbore diagram of proposed completion
OTHER: 12. Describe proposed or completed of starting any proposed work). or recompletion. 8/27/90 – Perforate Tubb f/ 6161-624 9/4/90 – Pull rods and tubing 9/6/90 – Set CIBP @ 6360' w/ 35' consealers. 9/7/90 – Frac Tubb w/ 83,000# 20/46	COMPLETION I operations. (Clearly state all SEE RULE 1103. For Multip 48') ement to plug off Drinkard. Plus and and 86 tons CO ₂ @ 18 b	CEMENT JOB OTHER: Plugbac pertinent details, and ge Completions: Attack BTD = 6325.' Acidize	ck give pertinent dates, including estimated date h wellbore diagram of proposed completion
OTHER: 12. Describe proposed or completed of starting any proposed work). or recompletion. 8/27/90 – Perforate Tubb f/ 6161-624 9/4/90 – Pull rods and tubing 9/6/90 – Set CIBP @ 6360' w/ 35' consealers. 9/7/90 – Frac Tubb w/ 83,000# 20/40 9/13/90 – Hang well on pump.	COMPLETION I operations. (Clearly state all SEE RULE 1103. For Multip 48') ement to plug off Drinkard. Plus and and 86 tons CO ₂ @ 18 b	CEMENT JOB OTHER: Plugbac pertinent details, and ge Completions: Attack BTD = 6325.' Acidize	ck give pertinent dates, including estimated date h wellbore diagram of proposed completion
OTHER: 12. Describe proposed or completed of starting any proposed work). or recompletion. 8/27/90 – Perforate Tubb f/ 6161-624 9/4/90 – Pull rods and tubing 9/6/90 – Set CIBP @ 6360' w/ 35' consealers. 9/7/90 – Frac Tubb w/ 83,000# 20/40 9/13/90 – Hang well on pump. Well producing out of Tubb zone on	COMPLETION I operations. (Clearly state all SEE RULE 1103. For Multip 18') ement to plug off Drinkard. Plus and and 86 tons CO ₂ @ 18 by as of 9/13/90.	CEMENT JOB OTHER: Plugbace pertinent details, and ge Completions: Attace BTD = 6325.' Acidize pm, 4953-5850#	give pertinent dates, including estimated date h wellbore diagram of proposed completion Tubb w/ 4000 gals 15% NEFE and 60 ball
OTHER: 12. Describe proposed or completed of starting any proposed work). or recompletion. 8/27/90 – Perforate Tubb f/ 6161-624 9/4/90 – Pull rods and tubing 9/6/90 – Set CIBP @ 6360' w/ 35' consealers. 9/7/90 – Frac Tubb w/ 83,000# 20/40 9/13/90 – Hang well on pump.	COMPLETION I operations. (Clearly state all SEE RULE 1103. For Multip 18') ement to plug off Drinkard. Plus and and 86 tons CO ₂ @ 18 by as of 9/13/90.	CEMENT JOB OTHER: Plugbace pertinent details, and ge Completions: Attace BTD = 6325.' Acidize pm, 4953-5850#	give pertinent dates, including estimated date h wellbore diagram of proposed completion Tubb w/ 4000 gals 15% NEFE and 60 ball
OTHER: 12. Describe proposed or completed of starting any proposed work). or recompletion. 8/27/90 – Perforate Tubb f/ 6161-624 9/4/90 – Pull rods and tubing 9/6/90 – Set CIBP @ 6360' w/ 35' consealers. 9/7/90 – Frac Tubb w/ 83,000# 20/40 9/13/90 – Hang well on pump. Well producing out of Tubb zone on	I operations. (Clearly state all SEE RULE 1103. For Multip 188') ement to plug off Drinkard. Plus and and 86 tons CO ₂ @ 18 blue as of 9/13/90.	CEMENT JOB OTHER: Plugbace pertinent details, and ge Completions: Attace BTD = 6325.' Acidize pm, 4953-5850#	give pertinent dates, including estimated date h wellbore diagram of proposed completion Tubb w/ 4000 gals 15% NEFE and 60 ball lige and belief.
OTHER: 12. Describe proposed or completed of starting any proposed work). or recompletion. 8/27/90 – Perforate Tubb f/ 6161-624 9/4/90 – Pull rods and tubing 9/6/90 – Set CIBP @ 6360' w/ 35' consealers. 9/7/90 – Frac Tubb w/ 83,000# 20/40 9/13/90 – Hang well on pump. Well producing out of Tubb zone on	I operations. (Clearly state all SEE RULE 1103. For Multip 188') ement to plug off Drinkard. Plus and and 86 tons CO ₂ @ 18 blue as of 9/13/90.	CEMENT JOB OTHER: Plugbac pertinent details, and ge Completions: Attace BTD = 6325.' Acidize pm, 4953-5850#	give pertinent dates, including estimated date h wellbore diagram of proposed completion Tubb w/ 4000 gals 15% NEFE and 60 ball lige and belief.
OTHER: 12. Describe proposed or completed of starting any proposed work). or recompletion. 8/27/90 – Perforate Tubb f/ 6161-624 9/4/90 – Pull rods and tubing 9/6/90 – Set CIBP @ 6360' w/ 35' consealers. 9/7/90 – Frac Tubb w/ 83,000# 20/46 9/13/90 – Hang well on pump. Well producing out of Tubb zone on SIGNATURE	d operations. (Clearly state all SEE RULE 1103. For Multip 188.) ement to plug off Drinkard. Plus and and 86 tons CO ₂ @ 18 blus as of 9/13/90.	CEMENT JOB OTHER: Plugbace pertinent details, and ge Completions: Attace BTD = 6325.' Acidize pm, 4953-5850#	give pertinent dates, including estimated date h wellbore diagram of proposed completion Tubb w/ 4000 gals 15% NEFE and 60 ball lige and belief.
OTHER: 12. Describe proposed or completed of starting any proposed work). or recompletion. 8/27/90 – Perforate Tubb f/ 6161-624 9/4/90 – Pull rods and tubing 9/6/90 – Set CIBP @ 6360' w/ 35' consealers. 9/7/90 – Frac Tubb w/ 83,000# 20/40 9/13/90 – Hang well on pump. Well producing out of Tubb zone on I hereby certify that the information SIGNATURE Type or print name Catherine A	d operations. (Clearly state all SEE RULE 1103. For Multip 188') ement to plug off Drinkard. Plus and and 86 tons CO ₂ @ 18 blus as of 9/13/90. Above is true and complete to the TITL Aniello	CEMENT JOB OTHER: Plugbace pertinent details, and get Completions: Attace BTD = 6325.' Acidize pm, 4953-5850# he best of my knowled ERegulatory Sp	give pertinent dates, including estimated date h wellbore diagram of proposed completion Tubb w/ 4000 gals 15% NEFE and 60 ball dge and belief. Ecialist DATE // 2/ Telephone No. (214) 360-3592
OTHER: 12. Describe proposed or completed of starting any proposed work). or recompletion. 8/27/90 – Perforate Tubb f/ 6161-624 9/4/90 – Pull rods and tubing 9/6/90 – Set CIBP @ 6360' w/ 35' consealers. 9/7/90 – Frac Tubb w/ 83,000# 20/46 9/13/90 – Hang well on pump. Well producing out of Tubb zone on SIGNATURE	d operations. (Clearly state all SEE RULE 1103. For Multip 188') ement to plug off Drinkard. Plus and and 86 tons CO ₂ @ 18 blus as of 9/13/90. Above is true and complete to the TITL Aniello	CEMENT JOB OTHER: Plugbace pertinent details, and get Completions: Attace BTD = 6325.' Acidize pm, 4953-5850# he best of my knowled ERegulatory Sp	give pertinent dates, including estimated date h wellbore diagram of proposed completion Tubb w/ 4000 gals 15% NEFE and 60 ball dge and belief. Ecialist DATE // 21 Telephone No. (214) 360-3592
OTHER: 12. Describe proposed or completed of starting any proposed work). or recompletion. 8/27/90 – Perforate Tubb f/ 6161-624 9/4/90 – Pull rods and tubing 9/6/90 – Set CIBP @ 6360' w/ 35' consealers. 9/7/90 – Frac Tubb w/ 83,000# 20/40 9/13/90 – Hang well on pump. Well producing out of Tubb zone on I hereby certify that the information SIGNATURE Type or print name Catherine A	d operations. (Clearly state all SEE RULE 1103. For Multip 188') ement to plug off Drinkard. Plus and and 86 tons CO ₂ @ 18 blus as of 9/13/90. Above is true and complete to the TITL Aniello	CEMENT JOB OTHER: Plugbace pertinent details, and get Completions: Attack BTD = 6325.' Acidize pm, 4953-5850# he best of my knowled ERegulatory Sp	give pertinent dates, including estimated date h wellbore diagram of proposed completion Tubb w/ 4000 gals 15% NEFE and 60 ball dge and belief. Ecialist DATE // 2/ Telephone No. (214) 360-3592