Form 3160-5			
	U! ED STATES N たらこ MENT OF THE INTERIOR OF LAND MANAGEMENT	FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31,1993 .5. Lease Designation and Serial No. LC 031695B	
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals		6. If Indian, Allotee or Tribe Name	
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation	
1. Type of Well		Warren Unit Blin/Tubb WF	
Oil Gas Weil Weil Other		8. Well Name and No.	
2. Name of Operator		Well #31	
Conoco, Inc. 3. Address and Telephone No.		9. API Well No.	
10 Desta Drive Ste. 100W, Midland, Tx. 79705-4500 (915) 686-5580/684-6381		30-025-24781 10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T. R. M. or Survey Description)		Warren Blinebry Tubb O & G	
660'		11. County or Parish, State	
1980 FSL & 1980' EWL FEL See 27 T205 B22E KG			
S	Sec 27, T20S, R38E_K Ø	Lea, N.M.	
12. CHECK APPROPRIATE B	BOX(s) TO INDICATE NATURE OF NOTICE, R	EPORT, OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF AC		
Notice of Intent	Abandonment	Change of Plans	
		New Construction	
Subsequent Report	Plugging Back	Non-Routine Fracturing	
Final Abandonment Notice	Casing Repair	Water Shut-Off	
	Other replaced tbg string	Dispose Water Note: Report results of multiple completion on We	
	state all pertinent details, and give pertinent dates, including estimated date of	Completion or Recompletion Report and Log form.	
give subsurface locations and measured and true 3-26-99: MIRU, worked pump free, 3-29-99: Finish laying down tubing, r 3-30-99 Open up well, rIH w/pump, j unseat pump, unseat pump, POOH w 3-31-99: Unflanged well, went to rele collar, RDBOP, set TAC, flanged we 4-1-99: Open up well, pump 150 bls so pump sticking, work pump loose, hur 4-5-99: Get pumping status, rigged do	POOH laying down rods & pump, NDWH, NUBOP, t rack & tally tubing, NDBOP, NUWH. SION. picking up rods, seat pump, load & test to 500#, long s r/rods & pump. SION. ease TAC, tbg unscrewed, RUBOP, screwed onto tbg, l ell. SION. soap & water down tubing, RIH w/pump & rods, seat p ng well on let well pump, left well tagging. SD.	Completion or Recompletion Report and Log form. of starting any proposed work. If well is directionally drill ag for fill @6680', POOH w/tbg. SION. troke pump did not pump, worked to POOH w/tbg, loose connection, changed	
give subsurface locations and measured and true 3-26-99: MIRU, worked pump free, 3-29-99: Finish laying down tubing, r 3-30-99 Open up well, rIH w/pump, j unseat pump, unseat pump, POOH w 3-31-99: Unflanged well, went to rele collar, RDBOP, set TAC, flanged we 4-1-99: Open up well, pump 150 bls so pump sticking, work pump loose, hur 4-5-99: Get pumping status, rigged do	POOH laying down rods & pump, NDWH, NUBOP, t rack & tally tubing, NDBOP, NUWH. SION. picking up rods, seat pump, load & test to 500#, long s //rods & pump. SION. ease TAC, tbg unscrewed, RUBOP, screwed onto tbg, l ell. SION. soap & water down tubing, RIH w/pump & rods, seat p ng well on let well pump, left well tagging. SD. lown. Cleaned location.	Completion or Recompletion Report and Log form. of starting any proposed work. If well is directionally drille ag for fill @6680', POOH w/tbg. SION. troke pump did not pump, worked to POOH w/tbg, loose connection, changed	
give subsurface locations and measured and true 3-26-99: MIRU, worked pump free, 3-29-99: Finish laying down tubing, r 3-30-99 Open up well, rIH w/pump, j unseat pump, unseat pump, POOH w 3-31-99: Unflanged well, went to rele collar, RDBOP, set TAC, flanged we 4-1-99: Open up well, pump 150 bls so pump sticking, work pump loose, hur 4-5-99: Get pumping status, rigged do	POOH laying down rods & pump, NDWH, NUBOP, t rack & tally tubing, NDBOP, NUWH. SION. picking up rods, seat pump, load & test to 500#, long s //rods & pump. SION. ease TAC, tbg unscrewed, RUBOP, screwed onto tbg, l ell. SION. soap & water down tubing, RIH w/pump & rods, seat p ng well on let well pump, left well tagging. SD. lown. Cleaned location.	Completion or Recompletion Report and Log form.) of starting any proposed work. If well is directionally drille ag for fill @6680', POOH w/tbg. SION. troke pump did not pump, worked to POOH w/tbg, loose connection, changed ump, load & test to 500#, long stroke	
give subsurface locations and measured and true 3-26-99: MIRU, worked pump free, 3-29-99: Finish laying down tubing, r 3-30-99 Open up well, rIH w/pump, j unseat pump, unseat pump, POOH w 3-31-99: Unflanged well, went to rele collar, RDBOP, set TAC, flanged we 4-1-99: Open up well, pump 150 bls so pump sticking, work pump loose, hur 4-5-99: Get pumping status, rigged do	POOH laying down rods & pump, NDWH, NUBOP, t rack & tally tubing, NDBOP, NUWH. SION. picking up rods, seat pump, load & test to 500#, long s //rods & pump. SION. ease TAC, tbg unscrewed, RUBOP, screwed onto tbg, I ell. SION. coap & water down tubing, RIH w/pump & rods, seat p ng well on let well pump, left well tagging. SD. lown. Cleaned location. , ran back in w/6658 2 3/8" tubing, SN @ 6668'. Ann E. Ritchie Title Regulatory Agent	Completion or Recompletion Report and Log form. of starting any proposed work. If well is directionally drille ag for fill @6680', POOH w/tbg. SION. troke pump did not pump, worked to POOH w/tbg, loose connection, changed ump, load & test to 500#, long stroke	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its junsdiction.

Ć

5