

UNITED STATES DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT  
HOBBS, NEW MEXICO 88240

SUBMIT IN TRIPI  
(Other instructions  
reverse side)

TE-  
re-

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

LC-063458

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Warren Unit

9. WELL NO.

48 R-9467 3/1/91

10. FIELD AND POOL OR SUBSIDY  
Blaine Oil & Gas Warren Tubb

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 26-20S-38E

12. COUNTY OR PARISH

Lea

13. STATE

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT-" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

CONOCO INC.

3. ADDRESS OF OPERATOR

P. O. Box 460, Hobbs, N.M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)

At surface Unit F

14. PERMIT NO.

30-025-25851

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

2030' FNL & 1980' FWL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON\* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☒

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT\* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

- ① MIRU on 7-29-86. POOH w/ pump. Ran scraper to 3750'
- ② Set RBP @ 6732' and pkr @ 6435'. Acidized Tubb perms, w/ 52 bbls 75% acid / 25% xylene mix, flushed w/ 50 bbls TFW. Swabbed
- ③ Reset RBP @ 6435' & pkr @ 5730'. Acidized Blaine perms w/ 40 bbls 75% acid / 25% xylene mix, flushed w/ 50 bbls TFW. Swabbed
- ④ Rel RBP & pkr. POOH. Hang well on and rig down.
- ⑤ Test pumped 42 BO, 23 BW & 220 MCF on 8-11-86.

ACCEPTED FOR RECORD

*SWD*  
SEP 26 1986

CARLSBAD, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED *[Signature]*

TITLE Administrative Supervisor

DATE 9-18-86

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side