Dec. 1973	UNITE STA	COPY TO O. C. C	Budget Bureau No. 42–R1424
	DEPARTMENT OF TH		5. LEA.
	GEOLOGICAL S		LC-031736 (b) 6. IF INDIAN, ALLOTTLE OR TRIBE NAME
			-
SUNDR	Y NOTICES AND R	EPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this	form for proposals to drill or to	o deepen or plug back to a different	
reservoir. Use f	orm 9-331-C for such proposals.)	8. FARM OR LEASE NAME
1. oil well	gas 🕅 other		Gillully B Federal R/A A 9. WELL NO.
	F OPERATOR		20
	Production Company	/	10. FIELD OR WILDCAT NAME
3. ADDRESS	S OF OPERATOR		Eunice Monument GSA
	Drawer "A", Levella		11. SEC., T., R., M., OR BLK. AND SURVEY O AREA
4. LOCATIO below.)		TION CLEARLY. See space 17	21-20-37
AT SURF	ACE: 1990' FTE & 76()' FEL, Sec 21	12. COUNTY OR PARISH 13. STATE
ΑΤ ΤΟΡ	PROD. INTERVAL: (IInj	t H, SE/4, NE/4)	Lea NM
	L DEPTH:		14. API NO.
	APPROPRIATE BOX TO INE OR OTHER DATA	DICATE NATURE OF NOTICE,	
Ker on t	ON OTHER DAIN		15. ELEVATIONS (SHOW DF, KDB, AND WE 3553 RDB
REQUEST FO	R APPROVAL TO: S	UBSEQUENT REPORT OF:	<u>3553 KUB</u>
TEST WATER			
FRACTURE T			
REPAIR WELL			C (NOTE: Report results of multiple completion or zor change on Form 9–330.)
PULL OR AL			6 19/9 change on Form 9-330.)
MULTIPLE CO CHANGE ZON			GICAL SURVEY
ABANDON*	Blank Perts		IEW MEXICO
(other)			
including	estimated date of starting	any proposed work. If well is c	te all pertinent details, and give pertinent date directionally drilled, give subsurface locations an
measure Propos rods,	d and true vertical depths fo se to seal off perf	rallmarkers and zones pertiner Forations at 3854'-60 Run cast iron bridge	directionally drilled, give subsurface locations an nt to this work.)*
measure Propos rods,	d and true vertical depths fo se to seal off perf pump, and tubing.	rallmarkers and zones pertiner Forations at 3854'-60 Run cast iron bridge	directionally drilled, give subsurface locations an nt to this work.)* ', 3865'-70'. Kill well and pul
measure Propos rods,	d and true vertical depths fo se to seal off perf pump, and tubing.	rallmarkers and zones pertiner Forations at 3854'-60 Run cast iron bridge	directionally drilled, give subsurface locations an nt to this work.)* ', 3865'-70'. Kill well and pul
measure Propos rods,	d and true vertical depths fo se to seal off perf pump, and tubing.	rallmarkers and zones pertiner Forations at 3854'-60 Run cast iron bridge	directionally drilled, give subsurface locations an nt to this work.)* ', 3865'-70'. Kill well and pul
measure Propos rods,	d and true vertical depths fo se to seal off perf pump, and tubing.	rallmarkers and zones pertiner Forations at 3854'-60 Run cast iron bridge	directionally drilled, give subsurface locations an nt to this work.)* ', 3865'-70'. Kill well and pul
measure Propos rods,	d and true vertical depths fo se to seal off perf pump, and tubing.	rallmarkers and zones pertiner Forations at 3854'-60 Run cast iron bridge	directionally drilled, give subsurface locations an nt to this work.)* ', 3865'-70'. Kill well and pul
measure Propos rods,	d and true vertical depths fo se to seal off perf pump, and tubing.	rallmarkers and zones pertiner Forations at 3854'-60 Run cast iron bridge	directionally drilled, give subsurface locations an nt to this work.)* ', 3865'-70'. Kill well and pul
measure Propos rods, well a	d and true vertical depths fo se to seal off perf pump, and tubing.	rallmarkers and zones pertiner Forations at 3854'-60 Run cast iron bridge	directionally drilled, give subsurface locations an nt to this work.)* ', 3865'-70'. Kill well and pul
measure Propos rods, well a	d and true vertical depths fo se to seal off perf pump, and tubing. and return to produ	orations at 3854'-60 Run cast iron bridge	directionally drilled, give subsurface locations an nt to this work.)* ', 3865'-70'. Kill well and pul e plug and set at 3800'. Swab
measure Propos rods, well a	d and true vertical depths fo se to seal off perf pump, and tubing. and return to produ	orations at 3854'-60 Run cast iron bridge	', 3865'-70'. Kill well and pul
measure Propos rods, well a Subsurface S	d and true vertical depths fo se to seal off perf pump, and tubing. and return to produ afety Valve: Manu. and Type certify that the foregoing is t	r all markers and zones pertinen orations at 3854'-60 Run cast iron bridge action.	directionally drilled, give subsurface locations an nt to this work.)* ', 3865'-70'. Kill well and pul e plug and set at 3800'. Swab Set @F
measure Propos rods, well a Subsurface S	d and true vertical depths fo se to seal off perf pump, and tubing. and return to produ afety Valve: Manu. and Type certify that the foregoing is t	r all markers and zones pertinen orations at 3854'-60 Run cast iron bridge action.	directionally drilled, give subsurface locations an nt to this work.)* ', 3865'-70'. Kill well and pul e plug and set at 3800'. Swab
measure Propos rods, well a Subsurface S 18. Thereby o	d and true vertical depths fo se to seal off perf pump, and tubing. and return to produ afety Valve: Manu. and Type certify that the foregoing is t	r all markers and zones pertiner orations at 3854'-60 Run cast iron bridge iction. rue and correct Admin. Superv	<pre>directionally drilled, give subsurface locations an nt to this work.)* ', 3865'-70'. Kill well and pul e plug and set at 3800'. Swab Set @F visor DATE March 23, 1979</pre>
measured Propos rods, well a Subsurface S 18. Thereby of SIGNED	d and true vertical depths fo se to seal off perf pump, and tubing. and return to produ afety Valve: Manu. and Type certify that the foregoing is t	r all markers and zones pertiner orations at 3854'-60 Run cast iron bridge iction. rue and correct Admin. Superv	<pre>directionally drilled, give subsurface locations an nt to this work.)* ', 3865'-70'. Kill well and pul e plug and set at 3800'. Swab Set @F visor DATE March 23, 1979</pre>
measured Propos rods, well a Subsurface S 18. Thereby of SIGNED APPROVED BY	d and true vertical depths fo se to seal off perf pump, and tubing. and return to produ afety Valve: Manu. and Type certify that the foregoing is t	r all markers and zones pertiner orations at 3854'-60 Run cast iron bridge iction. rue and correct Admin. Superv	<pre>directionally drilled, give subsurface locations an nt to this work.)* ', 3865'-70'. Kill well and pul e plug and set at 3800'. Swab Set @F visor DATE March 23, 1979</pre>
measured Propos rods, well a Subsurface S 18. Thereby of SIGNED APPROVED BY	d and true vertical depths fo se to seal off perf pump, and tubing. and return to produ afety Valve: Manu. and Type certify that the foregoing is t	r all markers and zones pertiner orations at 3854'-60 Run cast iron bridge iction. rue and correct Admin. Superv	<pre>directionally drilled, give subsurface locations an nt to this work.)* ', 3865'-70'. Kill well and pul e plug and set at 3800'. Swab Set @F visor DATE March 23, 1979</pre>
measured Propos rods, well a Subsurface S 18. Thereby of SIGNED APPROVED BY CONDITIONS OF 0+4-US 1-Su	d and true vertical depths fo se to seal off perf pump, and tubing. and return to produ afety Valve: Manu. and Type certify that the foregoing is t hay be performed. IF ANY: GS, H ISP	r all markers and zones pertiner orations at 3854'-60 Run cast iron bridge iction. rue and correct Admin. Superv	<pre>directionally drilled, give subsurface locations an nt to this work.)* ', 3865'-70'. Kill well and pul e plug and set at 3800'. Swab Set @F visor DATE March 23, 1979</pre>
Measured Propos rods, well a Subsurface S 18. Thereby of SIGNED APPROVED BY CONDITIONS OF 0+4-US 1-Su 1-Ho	afety Valve: Manu. and Type certify that the foregoing is t May Office APPROVAL, IF ANY: GS, H ISP DUSTON	r all markers and zones pertiner orations at 3854'-60 Run cast iron bridge iction. rue and correct Admin. Superv	<pre>directionally drilled, give subsurface locations an nt to this work.)* ', 3865'-70'. Kill well and pul e plug and set at 3800'. Swab Set @F visor_DATE March 23, 1979</pre>
measured Propos rods, well a Subsurface S 18. Thereby of SIGNED APPROVED BY CONDITIONS OF 0+4-US 1-Su	afety Valve: Manu. and Type certify that the foregoing is t May Office APPROVAL, IF ANY: GS, H ISP DUSTON	r all markers and zones pertiner orations at 3854'-60 Run cast iron bridge iction. rue and correct Admin. Superv	<pre>directionally drilled, give subsurface locations an nt to this work.)* ', 3865'-70'. Kill well and pul e plug and set at 3800'. Swab Set @F visor_DATE March 23, 1979</pre>
Measured Propos rods, well a Subsurface S 18. Thereby of SIGNED APPROVED BY CONDITIONS OF 0+4-US 1-Su 1-Ho	afety Valve: Manu. and Type certify that the foregoing is t May Office APPROVAL, IF ANY: GS, H ISP DUSTON	r all markers and zones pertiner orations at 3854'-60 Run cast iron bridge iction. rue and correct Admin. Superv	directionally drilled, give subsurface locations an nt to this work.)* ', 3865'-70'. Kill well and pul e plug and set at 3800'. Swab Set @F visor DATE March 23, 1979 fice use) MAR 2 6 1979

۴

¥daria de la constanta Altanta de Co



.