Form 9-331 (May 1963) UNITED STATES SUBMIT IN TRIPLICATES DEPARTMENT OF THE INTERIOR Verse slide) GEOLOG AL SURVEY				Form approved. Budget Bureau No. 42 R1424. 5. LEASE DESIGNATION AND SERIAL NO LC-031737 (b)				
	Y NOTICES A	ND REPORTS C	N WELLS ck to a different reservoir. posads.)	$\begin{bmatrix} EC - U3 + 737 & (D) \\ \hline \\ 6 \end{bmatrix}  fr indian, all ottree on true in the instance of the formula of the indian of$				
<ol> <li>OIL WELL X WELL OTHER</li> <li>NAME OF OPERATOR AMOCO Production Company</li> <li>ADDRESS OF OPERATOR P.O. Drawer A, Levelland, Texas 79336</li> <li>LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface</li> <li>T980' FNL &amp; 760' FEL Sec 21 (Unit H SE<sup>1</sup>/<sub>4</sub>, NE<sup>1</sup>/<sub>4</sub>)</li> </ol>				7. UNIT AGREEMENT NAME				
				8. FARM OR LEASE NAME Gillully B Federal R/A A 9. WELL NO. 20				
						10. FIELD AND FOOL, OR WIEDCAT Monument Tubb		
						11. SEC., T., R., M., OR BLK. AND SUBVEY OR AREA 21-20-37		
				14. PERMIT NO.	IT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)		RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
						3513.5 GR		Lea NM
16.	Check Appropriate	Box To Indicate No	ature of Notice, Report, or (	Other Data				
NOTIC	CE OF INTENTION TO :		SUBSEC	UENT REPORT OF:				
TEST WATER SHUT-OFF	PULL OR ALT		WATER SHUT-OFF	REPAIRING WELL				
FRACTURE TREAT	MULTIPLE C	OMPLETE Y	FRACTURE TREATMENT	ALTERING CASING				
SHOOT OR ACIDIZE REPAIR WELL	ABANDON*	$\frac{\lambda}{\chi}$	(Other) Testing Ca	ABANDONMENT*				
(Note: Report result.				s of multiple completion on Well detion Report and Log form.)				
<ol> <li>DESCRIBE PROPOSED OR COM proposed work. If well nent to this work.)*</li> </ol>	PLETED OPERATIONS (C) is directionally drilled	learly state all pertinent d, give subsurface location		a, including estimated date of starting any cal depths for all markers and zones perti-				
set at 7755'. to 7675. Press swab and swab	Spot acid acr sure up on csg dry. Recovere	ross perfs and g w/800# and ac ed no gas or oi	wash and soak. Rais idize down tbg w/10 1. Swab test and co	nd 2 3/8" tubing w/tailpip e tailpipe to 7735' and pk 00 gal 15% NE acid. Ran ntinued to swab dry.				
Tubb zone 6396	6'-6404', 6505	5'-6510', 6660'		cap w/35' cement. Perfora , 6760'-6764', 6798'-6802' id and evaluate.				
				○○○○○○○○○○○○○○○○○○○○○○○○○○○○○○○○○○○○				
				D E E E E E E E E E E E E E E E E E E E				
			-	U. S. LEE LOGICAL SURVEY				
signed Rac	p. W. Cox	-	inistrative Supervi	ULS DE LOGICAL SURVEY Holes new Mexico				
the second se	p. W. Cox	-	inistrative Supervi	ULS DE LOGICAL SURVEY Hoefs NEW MEXICO				
(This space for Federal (This space for Federal APPROVED BY CONDITIONS OF APPRO 0+4-USGS-H	r State office use)	-	inistrative Supervi	U. S. GET LOGICAL SURVEY HOLES NEW MEXICO				
SIGNED (This space for Federal of APPROVED BY CONDITIONS OF APPRO	r State office use)	TITLE Adm		U. S. GET LOGICAL SURVEY HOLES NEW MEXICO SOR DATE JULY 11, 1978				



RTENED UL I 8 1978