

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLIC.
(Other instructions on
reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. UNIT AGREEMENT NAME NMFU
2. NAME OF OPERATOR CONOCO INC.	8. FARM OR LEASE NAME Warren Unit
3. ADDRESS OF OPERATOR P. O. Box 460, Hobbs, N.M. 88240	9. WELL NO. 62
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit P	10. FIELD AND POOL, OR WILDCAT Blinebry oil & Gas / Tubbs
14. PERMIT NO. 660' FSL & 660' FEL 30-025-26204	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 20-205-38E
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH Lea
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other) !

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

MIRV. POOH w/ Blinebry pump & rods. POOH w/ Tubbs pump & rods. POOH w/ Blinebry +bg. Release long string & POOH (Tubbs). Mill pkr to 6352' in 5 hrs. Cont milling on pkr @ 6352'. POOH w/ pkr. WIH w/ +bg and pkr, set pkr @ 6390'. scale sqz Tubbs perfs (6495'-6662'). Flush w/ 20 bbls 2% KCL TFW. Release pkr. GIH w/ production +bg. and place on production. Test pumped 36 BO, 34 BW, and 58 MCF.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Administrative Supervisor

DATE 9-11-85

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

SEP 16 1985

*See Instructions on Reverse Side