

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-025-27261
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name William Turner
8. Well No. 4
9. Pool name or Wildcat Blinebry & Wantz; Abo - DHC #1961
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GL 3488' KB 3474'

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

Marathon Oil Company

3. Address of Operator

P.O. Box 2409 Hobbs, NM 88240

4. Well Location

Unit Letter **J** : **1980** Feet From The **South** Line and **1980** Feet From The **East** Line

Section **29** Township **21-S** Range **37-E** NMPM **Lea** County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

GL 3488' KB 3474'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: **DHC Blinebry 0 & G and Wantz; Abo pools** ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6/9 MIRU PU. ND wellhead. POOH w/pump & rods. ND wellhead. NU BOPE. POOH w/2 3/8" prod tbg.

6/12 RIH, tag fill at 6692'. Clean out to RBP at 6700'. Latch onto RBP. Release and POOH w/RBP. Clean out to 7195', PBD. Circ hole clean.

6/17 RIH w/2 3/8" tbg, ND BOPE. NU wellhead. RIH w/pump & rods. RD PU. Weak pump action. RU PU. POOH pump & rods. ND wellhead. NU BOPE. POOH w/tbg. RIH w/wireline, parted going in hole.

6/23 Could not recover fish. Sinker bar and slickline left in hole at 7095'. RIH w/2 3/8" prod tbg. ND BOPE. NU wellhead. RIH w/pump & rods. RD PU.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Kelly Cook

TITLE

Records Processor

DATE

6/30/98

TYPE OR PRINT NAME

Kelly Cook

TELEPHONE NO.

393-7106

(This space for State Use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

