

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-8077	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator ARCO Oil and Gas Company
Division of Atlantic Richfield Company

Address of Operator
P. O. Box 1710, Hobbs, New Mexico 88240

Location of Well

UNIT LETTER L 1980 FEET FROM THE South LINE AND 660 FEET FROM
THE West LINE, SECTION 25 TOWNSHIP 22S RANGE 35E N.M.P.M.

15. Elevation (Show whether DF, RT, GR, etc.)

3562.2' GR

7. Unit Agreement Name
8. Farm or Lease Name State 731
9. Well No. 1
10. Field and Pool, or Wildcat Jalmat Yates Oil
12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER Add Perfs, Acidize, Frac <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up, kill well, install BOP. POH w/compl assy.
2. Perforate additional Yates 7R Queen @ 3768, 71, 74, 77, 82, 85, 92, 95, 3810, 13, 18, 22, 25, 28, 3831'.
3. Set RBP @ 3850', spot acid across perf'd interval, set pkr @ 3650' & break down perfs.
4. Acidize perfs 3768-3831' w/2500 gals 15% NEA-FE, swab test. If necessary frac in the following manner.
5. POH w/pkr & RBP. RIH w/2-3/8" tbg w/SN set @ approx 3600' & frac perfs 3768-3831' & 3859-3878' w/20,000 gals cross-linked frac gel w/additives and 49,750# sd.
5. Swab back load & test, clean out & return to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Elizabeth L. Bush

TITLE Drilling Eng.

DATE 5/14/82

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

MAY 20 1982