

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-6347
7. Unit Agreement Name
8. Farm or Lease Name State 35
9. Well No. 1
10. Field and Pool, or Wildcat South Cass Strawn / South Skaggs Abo
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- temp. shut-in
2. Name of Operator CONOCO INC.
3. Address of Operator P. O. Box 460, Hobbs, N.M. 88240
4. Location of Well UNIT LETTER P 660 FEET FROM THE South LINE AND 660 FEET FROM THE East LINE, SECTION 35 TOWNSHIP 20S RANGE 37E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- ① MIRU. Retrieve RBP @ 6880'. Set CIBP @ 7595'.
- ② Set CIBP @ 6930'. Reverse circ. pkr fluid out of hole w/ mud (9.5 ppg brine water mixed @ 25 sxs gel/100 bbls 9.5 ppg brine). Spot 20 sxs Class "c" on top of CIBP @ 6930'.
- ④ Spot 25 sxs Class "c" Neat from 3740'-3640'. Spot 33 sxs Class "c" Neat from 1365'-1265'. WOC for 3 hrs. Tag TOC when cmt has set.
- ⑤ Spot 16 sxs Class "c" Neat from 50' to surface. Cut off wellhead and install P & A marker. Rig down.
- ⑥ A proposed P & A sketch is attached.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *John L. Vogel* TITLE Administrative Supervisor DATE 7-28-86

ORIGINAL SIGNED BY JERRY SEXTON
APPROVED BY DISTRICT I SUPERVISOR
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

JUL 30 1986

NMOC-Hobbs
File