

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-77

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Texaco Producing Inc.	8. Farm or Lease Name M. B. Weir "B"
3. Address of Operator PO Box 728, Hobbs, New Mexico 88240	9. Well No. 13V
4. Location of Well UNIT LETTER <u>O</u> , <u>690</u> FEET FROM THE <u>South</u> LINE AND <u>1850</u> FEET FROM THE <u>East</u> LINE, SECTION <u>12</u> TOWNSHIP <u>20S</u> RANGE <u>37E</u> N.M.P.M.	10. Field and Pool, or Wildcat Skaggs Drinkard
15. Elevation (Show whether DF, RT, GR, etc.) 3553' GL	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☒
CASING TEST AND CEMENT JOBS ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spud 20" hole at 12:00 Noon, 10/25/87
Ran 9 jts. (338'), 16", 65#, H-40, ST & C casing,
set at 350'.

- 1) Ran 34 jts. (1430') 11 3/4", 42#, H-40, ST & C casing, set at 1442'.
- 2) Cement with 1000 sxs. Class "H" with 2% CaCl and 1/4# Cello-seal. Circulated 260 sxs.
- 3) Test 11 3/4" casing to 800# from 12:30 PM to 1:00 PM, held ok.
- 4) Ran 96 jts. (3938') 3 5/8", 32#, J-55, ST & C casing, set at 4000'.
- 5) Cement with 1300 sxs. LW 15# salt, 1/4# Celloseal. Tail with 200 sxs. 1/4# Celloseal and CaCl. Circulated 80 sxs. Inflate ECP and shut off flow.
- 6) Test 3 5/8" casing to 1000# for 30 minutes, from 4:30 AM to 5:00 AM, 10/5/87. Held ok.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

397-3571

SIGNED J. A. Sexton

TITLE Hobbs Area Superint.

DATE 10/30/87

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT SUPERVISOR

TITLE

DATE NOV 17 1987

CONDITIONS OF APPROVAL, IF ANY:

NOV 16 1967
OCC
HOBBS OFFICE