Submit 3 Copies

to Appropriate

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revisied 1-1-89

X

District Office	OIL CON	SERVATION DIV	ISION				
		P.O. Box 2088					
DISTRICT I	Sant	a Fe, New Mexico 8	7504-2088				
P.O. Box 1980, Hobbs, NM 88240							
DISTRICT II				API NO. (essigned	by OCD on New W	-U-I	
P.O. Drawer Dd, Artesia, NM 88210				30-025-313		6113)	
DISTRICT III				5. Indicate Type			
1000 Rio Brazos Rd., Aztec, Nm 87410	0			o. marcate Type	_	X FEE	
				6. State Oil & G	es Lease No		
				N/A	- Cuase No.		
S	SUNDRY NOTICES AND	REPORTS ON WELLS		William I		,,,,,,,,,,,	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
	S FORM FOR PROPOSALS TO		UG BACK TO A				
D	DIFFERENT RESERVOIR. USE	APPLICATION FOR PERMIT	OG BAGK 10 A		Unit Agreement Na D GRAYBUR		
	(FORM C-101) FOR SUCH			AMOVILA	ONA TOUR	G ONI	
1. Type of Well:	· · · · · · · · · · · · · · · · · · ·			-			
OIL	GAS						
WELL	WELL OTHER	INJECTOR					
2. Name of Operator							
CHEVRON U.S.	.A. INC.			8. Well No.			
3. Address of Operator				203			
P.O. BOX 1150 MIDLAND	, TX 79702 ATTN: P.R	MATTHEWS		9. Pool name or V			
4. Well Location		· · · · · · · · · · · · · · · · · · ·		ARROWHEA	D GRAYBURG	G SA	
Unit Letter	: 1980 F	eet From The SO	UTH Line and	635	Feet From The	EAST	
Section	12	ownship 22S	Range	36E	NMPM	LEA	Line
		10. Elevation(Show whether DF, F			WINNIN	LEA //////////	County
		3457.9 GE					
11	Check Appropriate Box to In		ort or Other Data				
NOTICE OF INT	ENTION TO:		UBSEQUENT RE	BORT OF			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	1 1	POSEGOEM! VE	PORT OF:		_	
TEMPORARILY ABANDON	╡	REMEDIAL WORK	<u></u>	1	ALTER CASING		
<u>_</u>	CHANGE PLANS	COMMENCE DRILL	ING OPNS.		PLUG AND ABAN.	Ī	7
PULL OR ALTER CASING	j	CASING TEST AND	CMT JOB	7		L	
OTHER:	Г	¬		_			_

OTHER:

DRILLING SUMMARY

12. Describe Proposed or Completed Operations/Clearly state all pertinent details, and give pertinent dates, including esticated date of starting any proposed work) SEE RULE 1103.

MOVE IN RIG AND SPUD ON 10-07-91.

DRILL AND SURVEY 12 1/4" HOLE FROM 0'-1140'.

SET 8 5/8" CSG TO 1140, PUMP 700 SXS CMT, CIRC 85 SXS.

WOC 12 HRS.

DRILL OUT SHOE AND CONTINUE TO DRILL FORMATION.

reby certify that	it the information abo	ove provide and con	nplete to the best of my know	wledge and belief. TECH. ASSISTANT	DATE:	10-10-91
E OR PRINT NA	AME	P.R. MAT	THEWS		TELEPHONE NO.	
	7 P (#)		50 (MM)			
	9 %	>	TITLE			