Submit 3 Copies to Appropriate District Office

State of New Mexico Energ linerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I

OII CONSEDVATION DIVISION

Santa Fe, NM 87505 Santa F	P.O. Box 1980, Hobbs, NM 88240	2040 Pachec		WELL API NO.	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DOLL OR TO DEEPEN OR PLUS BACK TO A DIFFERENCE OR PROPOSALS TO DOLL OR TO DEEPEN OR PLUS BACK TO A DIFFERENCE OR TO THE PROPOSALS. 1. Type of Wal.	DISTRICT II	_ -			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSOBALS TO DRILL OR TO DEEPER ON PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C. 101) FOR SUCH PROPOSALS.) 1. Type of Well:				5. Indicate Type of Lease STATE X	FEF
CDONOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUS BACK TO A DIFFERENT RESERVOR. USE "APPLICATION FOR FEMITY" DIFFERENT RESERVOR. USE "APPLICATION FOR FEMITY" DIFFERENT RESERVOR. USE "APPLICATION FOR FEMITY" State P.C.	1000 Rio Brazos Rd., Aziec, NM 87410				
DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT" (FORMC-101) FOR SUCH PROPOSALS) 1. Type of Well: Out Out Out Out	SUNDRY NOT	TCES AND REPORTS ON W	/ELLS		
2. Name of Operator Will will Costude Shell Western E & P Co. 3. Address of Operator Will Costude Unit Letter 0 : 1000 Feet From The South Line and 2370 Feet From The East Line Section 32 Township 20S Range 37E NMTM Lea County 10. Elevation (Show whether DF, RES. RT, GR, ac.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK NATURE ANADON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON PLUG AND ABANDON OTHER: COMMENCE DRILLING OPNS. PLUG AND ABANDON OTHER: 12. Describe Proposed or Completed Operations (Clearly state all perinent details, including estimated date of starting any proposed world St. Ref. St. 8174-84, 8196-8201, 8224-35, 8248-55, 8266-76. Swabbed. 3/6/97 - Actidize 5000 G, 15% NeFe 3/10/97 - CHEP at 8100' capped with 35' cement - test to 500 psi. 3/11/97 - Perforate Tubb 2 JSPF: 6606-28, 6630-34, 6639-59, 6680-96, 6712-38, 6764-69, 6779-96, 6828-36, 6877-92. 3/12/97 - Actidize with 15,000 G, 15% NeFe 3/13/18/97 - Swabbed Perfs. 4/1/97 - Set RBP at 6500. Shut Well in. 10. Thereby cently use the integrating spice is triple and planning to the basis. 11. Agent Date (1259-600-03)	DIFFERENT RESE	RVOIR. USE "APPLICATION FOR	PEN OR PLUG BACK TO A PERMIT		
2. Name of Operator Shell Western E & P Co. 3. Additions of Operator Will Location Unit Letter O: 1000 Feet From The South Line and 2370 Feet From The East Line Section 32 Township 20S Range 37E NMPM Lea County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PLUG AND ABANDONMENT CASING TEMPORARILY ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent datas, including estimated date of starting any proposed work) SEE RULE 1103. 3/3,4/97 - Perforate Wolf camp 2JSPF: 8146-58, 8174-84, 8196-8201, 8224-35, 8248-55, 8266-76. Swabbed. 3/6/97 - Aciditze 5000 G. 15% NeFe 3/7-9/97 - Swabbed perfs. 3/10/97 - CIBP at 8100' capped with 35' cement - test to 500 psi. 3/11/97 - Perforate Tubb 2 JSPF: 6606-28, 6630-34, 6639-59, 6680-96, 6712-38, 6764-69, 6779-96, 6828-36, 6877-92. 3/13-18/97 - Swabbed Perfs. 3/13-18/97 - Swabbed Perfs. 4/1/97 - Set RBP at 6500. Shut Well In. 1 Agent Date 8-12-98 THEPROME NO. 505-390-034	OE GAS -	OTTER .		_ State P.C.	
4. Well Location Unit Letter 0: 1000 Feet From The South Line and 2370 Feet From The East Line Section 32 Township 20S Range 37E NMPM Lea County 10. Elevation (Show whether DF, RKB, RT, CR, etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB 20THER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including astimated date of starting any proposed works SEE RULE 1103. 3/3,4/97 - Perforate Wolfcamp 2JSPF: 8146-58, 8174-84, 8196-8201, 8224-35, 8248-55, 8266-76. Swabbed. 3/6/97 - Acidize 5000 G. 15% NeFe 3/7-9/97 - Swabbed perfs. 3/10/97 - CTBP at 8100' capped with 35' cement - test to 500 psi. 3/11/97 - Perforate Tubb 2 JSPF: 6606-28, 6630-34, 6639-59, 6680-96, 6712-38, 6764-69, 6779-96, 6828-36, 6877-92. 3/12/97 - Acidize with 15,000 G. 15% NeFe 3/13-18/97 - Swabbed Perfs. 4/1/97 - Set RBP at 6500. Shut Well :n. Agent DATE 8-12-98 TITLE Agent TERPENDRINAME Ralph C. Bruton TERPENDRINAME Ralph C. Bruton TERPENDRINAME RAlph C. Bruton	2. Name of Operator				
Wildcat Wildcat Wildcat Wildcat Wildcat Wildcat Wildcat Wildcat Wildcat Line and 2370 Feet From The East Line Section 32 Township 20S Range 37E NMPM Lea County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT OTHER: 12. Describe Proposed or Completed Operations (Clearly state all persisens details, and give persisens dates, including estimated date of starting any proposed world SEE RULE 1103. 3/3,4/97 - Perforate Wolfcamp 2JSPF: 8146-58, 8174-84, 8196-8201, 8224-35, 8248-55, 8266-76. Swabbed. 3/6/97 - Acidize 5000 G. 15% NeFe 3/7-9/97 - Swabbed perfs. 3/10/97 - CIBP at 8100' capped with 35' cement - test to 500 psi. 3/11/97 - Perforate Tubb 2 JSPF: 66006-28, 6630-34, 6639-59, 6680-96, 6712-38, 6764-69, 6779-96, 6828-36, 6877-92. 3/12/97 - Acidize with 15,000 G. 15% NeFe 3/13-18/97 - Swabbed Perfs. 4/1/97 - Set RBP at 6500. Shut Well :n. Three or report NAME Ralph C. Bruton TITLE Agent TITLE Ag	3. Address of Operator	n E & P Co.			
Unit Letter 0: 1000 Feet From The South Line and 2370 Feet From The East Line Section 32 Township 20S Runge 37E NMPM Lea County 10. Elevation (Show whether DF, RKB, KT, GR, etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING CHANGE PLANS CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT OF HERE 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of stating any proposed work) SER RULE 1103. 3/3,4/97 - Perforate Wolfcamp 2JSPF: 8146-58, 8174-84, 8196-8201, 8224-35, 8248-55, 8266-76. Swabbed. 3/6/97 - Acidize 5000 G. 15% NeFe 3/7-9/97 - Swabbed perfs. 3/10/97 - CIBP at 8100' capped with 35' cement - test to 500 psi. 3/11/97 - Perforate Tubb 2 JSPF: 6606-28, 6630-34, 6639-59, 6680-96, 6712-38, 6764-69, 6779-96, 6828-36, 6877-92. 3/12/97 - Acidize with 15,000 G. 15% NeFe 3/13-18/97 - Swabbed Perfs. 4/1/97 - Set RBP at 6500. Shut Well :n. 1 Introductive the transfer of the state of the proposed of the state of the sta	4 Well Location			i	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT DULL OR ALTER CASING CASING TEST AND CEMENT JOB OTHER: OT	·-	00 Feet From The South	Line and 237	O Frank	
10. Elevation (Show whether DF, RKB, RT. GR, etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT OTHER: OTHE				rea from the East	Line
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 3/3,4/97 - Perforate Wolfcamp 2JSPF: 8146-58, 8174-84, 8196-8201, 8224-35, 8248-55, 8266-76. Swabbed. 3/6/97 - Acidize 5000 G. 15% NeFe 3/7-9/97 - Swabbed perfs. 3/10/97 - CIBP at 8100' capped with 35' cement - test to 500 psi. 3/11/97 - Perforate Tubb 2 JSPF: 6606-28, 6630-34, 6639-59, 6680-96, 6712-38, 6764-69, 6779-96, 6828-36, 6877-92. 3/13-18/97 - Swabbed Perfs. 4/1/97 - Set RBP at 6500. Shut Well in.	Section 32		Range 37E her DF, RKB, RT, GR, etc.)	NMPM Lea	County
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent datasits, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 3/3,4/97 - Perforate Wolfcamp 2JSPF: 8146-58, 8174-84, 8196-8201, 8224-35, 8248-55, 8266-76. Swabbed. 3/6/97 - Acidize 5000 G. 15% NeFe 3/7-9/97 - Swabbed perfs. 3/10/97 - CIBP at 8100' capped with 35' cement - test to 500 psi. 3/11/97 - Perforate Tubb 2 JSPF: 6606-28, 6630-34, 6639-59, 6680-96, 6712-38, 676-69, 6779-96, 6828-36, 6877-92. 3/12/97 - Acidize with 15,000 G. 15% NeFe 3/13-18/97 - Swabbed Perfs. 4/1/97 - Set RBP at 6500. Shut Well in. Thereby certify that the integration of the start of					
PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: OTHER: OT	11. Check	Appropriate Box to Indicat	e Nature of Notice, F	Report, or Other Data	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PLUG AND ABANDONMENT COMMENCE DRILLING OPNS PLUG AND ABANDONMENT OTHER: CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: OT	NOTICE OF IN	FENTION TO:	SUE	SSEQUENT REPORT OF:	
COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING CASING TEST AND CEMENT JOB OTHER: CASING TEST AND CEMENT JOB OTHER: OTHE	PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	X ALTERING CASING	
CASING TEST AND CEMENT JOB OTHER: DTHER:	TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLIN		WENT
OTHER:	PULL OR ALTER CASING				MENI
12. Describe Proposed or Completed Operations (Clearly state all persinent details, and give persinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 3/3,4/97 - Perforate Wolfcamp 2JSPF: 8146-58, 8174-84, 8196-8201, 8224-35, 8248-55, 8266-76. Swabbed. 3/6/97 - Acidize 5000 G. 15% NeFe 3/7-9/97 - Swabbed perfs. 3/10/97 - CIBP at 8100' capped with 35' cement - test to 500 psi. 3/11/97 - Perforate Tubb 2 JSPF: 6606-28, 6630-34, 6639-59, 6680-96, 6712-38, 6764-69, 6779-96, 6828-36, 6877-92. 3/12/97 - Acidize with 15,000 G. 15% NeFe 3/13-18/97 - Swabbed Perfs. 4/1/97 - Set RBP at 6500. Shut Well in.	OTHER:	Г	٦	EMENT JOB	
3/3,4/97 - Perforate Wolfcamp 2JSPF: 8146-58, 8174-84, 8196-8201, 8224-35, 8248-55, 8266-76. Swabbed. 3/6/97 - Acidize 5000 G. 15% NeFe 3/7-9/97 - Swabbed perfs. 3/10/97 - CIBP at 8100' capped with 35' cement - test to 500 psi. 3/11/97 - Perforate Tubb 2 JSPF: 6606-28, 6630-34, 6639-59, 6680-96, 6712-38, 6764-69, 6779-96, 6828-36, 6877-92. 3/12/97 - Acidize with 15,000 G. 15% NeFe 3/13-18/97 - Swabbed Perfs. 4/1/97 - Set RBP at 6500. Shut Well in.					
8248-55, 8266-76. Swabbed. 3/6/97 - Acidize 5000 G. 15% NeFe 3/7-9/97 - Swabbed perfs. 3/10/97 - CIBP at 8100' capped with 35' cement - test to 500 psi. 3/11/97 - Perforate Tubb 2 JSPF: 6606-28, 6630-34, 6639-59, 6680-96, 6712-38, 6764-69, 6779-96, 6828-36, 6877-92. 3/12/97 - Acidize with 15,000 G. 15% NeFe 3/13-18/97 - Swabbed Perfs. 4/1/97 - Set RBP at 6500. Shut Well in.	work) SEE RULE 1103.	tions (Clearly state all pertinent details,	, and give pertinent dates, incli	iding estimated date of starting any proposed	
8248-55, 8266-76. Swabbed. 3/6/97 - Acidize 5000 G. 15% NeFe 3/7-9/97 - Swabbed perfs. 3/10/97 - CIBP at 8100' capped with 35' cement - test to 500 psi. 3/11/97 - Perforate Tubb 2 JSPF: 6606-28, 6630-34, 6639-59, 6680-96, 6712-38, 6764-69, 6779-96, 6828-36, 6877-92. 3/12/97 - Acidize with 15,000 G. 15% NeFe 3/13-18/97 - Swabbed Perfs. 4/1/97 - Set RBP at 6500. Shut Well in.	3/3,4/97 - Perforate	e Wolfcamp 2JSPF : 814	6-58, 8174-84, 8	196-8201, 8224-35,	
3/7-9/97 - Swabbed perfs. 3/10/97 - CIBP at 8100' capped with 35' cement - test to 500 psi. 3/11/97 - Perforate Tubb 2 JSPF: 6606-28, 6630-34, 6639-59, 6680-96, 6712-38, 6764-69, 6779-96, 6828-36, 6877-92. 3/12/97 - Acidize with 15,000 G. 15% NeFe 3/13-18/97 - Swabbed Perfs. 4/1/97 - Set RBP at 6500. Shut Well in.	8248-55,	8266-76. Swabbed.		, , , , , , , , , , , , , , , , , , , ,	
3/10/97 - CIBP at 8100' capped with 35' cement - test to 500 psi. 3/11/97 - Perforate Tubb 2 JSPF : 6606-28, 6630-34, 6639-59, 6680-96, 6712-38, 6764-69, 6779-96, 6828-36, 6877-92. 3/12/97 - Acidize with 15,000 G. 15% NeFe 3/13-18/97 - Swabbed Perfs. 4/1/97 - Set RBP at 6500. Shut Well in.					
3/11/97 - Perforate Tubb 2 JSPF: 6606-28, 6630-34, 6639-59, 6680-96, 6712-38, 6764-69, 6779-96, 6828-36, 6877-92. 3/12/97 - Acidize with 15,000 G. 15% NeFe 3/13-18/97 - Swabbed Perfs. 4/1/97 - Set RBP at 6500. Shut Well in. I hereby certify that the information before is the form the best of my knowledge and belief. SIONATURE			cement - test to	500 pai	
3/12/97 - Acidize with 15,000 G. 15% NeFe 3/13-18/97 - Swabbed Perfs. 4/1/97 - Set RBP at 6500. Shut Well in. I hereby certify that the infernation above is the and purpose for the Best of my knowledge and belief. SIGNATURE	3/11/97 - Perforate	Tubb 2 JSPF : 6606-2	28, 6630-34, 6639	-59, 6680-96, 6712-38	
3/13-18/97 - Swabbed Perfs. 4/1/97 - Set RBP at 6500. Shut Well in. I hereby certify that the information above us to and formplay to the Best of my knowledge and belief. SKONATURE	6/64-69,	6779-96, 6828-36, 687	77-92.	33, 3333 30, 3712 30,	
4/1/97 - Set RBP at 6500. Shut Well in. I hereby certify that the information shows us trult and complete to the best of my knowledge and belief. SIGNATURE			⁷ e		
I hereby certify that the information above us trys and complete to the best of my knowledge and belief. SIGNATURE					
SIGNATURE Agent DATE 8-12-98 TYPE OR FRINT NAME Ralph C. Bruton TELEPHONE NO. 505-390-036	4/1/9/ - Set RBP a	it 6500. Shut Well in.			
SIGNATURE Agent DATE 8-12-98 TYPE OR FRINT NAME Ralph C. Bruton TELEPHONE NO. 505-390-036					
SIGNATURE Agent DATE 8-12-98 TYPE OR FRINT NAME Ralph C. Bruton TELEPHONE NO. 505-390-036					
SIONATURE Agent DATE 8-12-98 TYPE OR FRINT NAME Ralph C. Bruton TELEPHONE NO. 505-390-036	I hereby certify that the information shows is true	and complete to the Best of my knowledge a	nd belief.		
IELEMANE NO. 909 370 050	// Val-/	Mulon		DATE 8-12-98	
	TYPE OR PRINT NAME Ralph C. H	ruton			-390 - 036
	(This space for State Line)				

-- TITLE --

CONDITIONS OF AFFROVAL, IF ANY: