2400 5		N.M. Oil	COUR
orm 3160-5	UNITED STATES		1980 FORM APPROVED
une 1990)	DEPARTMENT OF THE INTERIOR		Budget Bureau No 1004-01.55
	BUREAU OF LAND MANAGEMEN	HODDS, N	5. Lease Designation and Senal No.
			LC 063458
	SUNDRY NOTICES AND REPORTS ON	WELLS	6. If Indian, Allottee or Tribe Name
To not use this form for propos	sals to drill or to deepen or reentry to a di		
	FOR PERMIT " for such proposals		/. If Unit or CA, Agreement Designation
	SUBMIT IN TRIPLICATE		
Type of Well	NJECTION		
Well Othe			Warren Unit Blin/Tubb WF
Hame of Operator			Well #213
CONOCO, INC.			9. /
		694 6291	30 025 33917 10 Field and Pool, or Exploratory Area
10 Desta Dr., Suite IUUW, Midla Location of Well (Footage, Sec., T., R.		684-6381	Warren Blinebry Tubb Oil & Gas
Surface: 13/0' ENL & IO' EV	NI		11. County or Parish, State
Surface: I3I0' FNL & I0' FWL TD: Sec 34, T20S, R38E, Unit Letter M			
			Lea, NM
CHECK APPROPRIA	TE BOX(s) TO INDICATE NATURE C	OF NOTICE, REPO	RT, OR OTHER DATA
TYPE OF SUBMISS		TYPE OF AC	
Notice of Intent		Abandonment	Change of Plans
ليبي		Recompletion	New Construction
X Subsequent Report		Plugging Back	Non-Routine Fracturing
		Casing Repair	Water Shut-Off
Final Abandonment	t Notice	Altering Casing	Conversion to Injection
kare at	X	Clean out fill	Dispose Water
			(Note: Report results of multiple completion on Weit
3. Describé Proposed or Completed Or directionally dinied, give subsurfa	perations (Clearly state all pertinent octails, and give pert ace locations and measured and true vertical depths for	inent dates, including estimat all markers and zones pertine	Completion or Recompletion Report and Log form.) ted date of starting any proposed work if well is mit to this work.)"
directionally dulled, give subsurfa 10-30-97: Rigged up - anchor, pull IC 10-3I-97: Swab fluid le RIH w/SN & tl 11-3-97: Continue in bo	jarred on pump, wouldn't come loose 5 stands to fluid. SION. 2 vel down, POOH w/tbg, RIH w/ clean-	. Backed off ords, F -out bailer, clean ou . ND BOP, set tbg a	ted date of starting any proposed work. If well is ent to this work.)* POOH, NDBOP, unset It to 6700', POOH, unchor, NU wellhead,
directionally diffed, give subsurfa 10-30-97: Rigged up - anchor, pull 10 10-31-97: Swab fluid le RIH w/SN & tl 11-3-97: Continue in bo	jarred on pump, wouldn't come loose o stands to fluid. SION. evel down, POOH w/tbg, RIH w/ clean- bg, SION.	. Backed off ords, F -out bailer, clean ou , ND BOP, set tbg a Rigged down. Well j	ted date of starting any proposed work. If well is POOH, NDBOP, unset It to 6700', POOH, Inchor, NU wellhead, put back on production.
directionally dinlied, give subsurfa 10-30-97: Rigged up - anchor, pull 10 10-31-97: Swab fluid le RIH w/SN & tl 11-3-97: Continue in bo	jarred on pump, wouldn't come loose 0 stands to fluid. SION. evel down, POOH w/tbg, RIH w/ clean- bg, SION. ole with tubing, pump wt. on backside, ump & rods & loaded & tested - held. F	Backed off ords, F -out bailer, clean ou ND BOP, set tbg a Rigged down. Well	ed date of starting any proposed work. If well is POOH, NDBOP, unset It to 6700', POOH, unchor, NU wellhead, put back on production.
directionally diffed, give subsurfa 10-30-97: Rigged up - anchor, pull IC 10-3I-97: Swab fluid le RIH w/SN & tl 11-3-97: Continue in ho RIH w/new pu 14 Thereby certify that the toregoing is Signed Mig un	ace locations and measured and true vertical depths for jarred on pump, wouldn't come loose 0 stands to fluid. SION. Evel down, POOH w/tbg, RIH w/ clean- bg, SION. ole with tubing, pump wt. on backside, ump & rods & loaded & tested - held. F true and correct Ann E Ritchie Title REGULATORY /	Backed off ords, F -out bailer, clean ou ND BOP, set tbg a Rigged down. Well	ted date of starting any proposed work. If well is POOH, NDBOP, unset In to 6700', POOH, Inchor, NU wellhead, put back on production.
directionally diffed, give subsurfa 10-30-97: Rigged up - anchor, pull IC 10-3I-97: Swab fluid le RIH w/SN & tl 11-3-97: Continue in ho RIH w/new pu 14 Thereby certify that the toregoing is	ace locations and measured and true vertical depths for jarred on pump, wouldn't come loose 0 stands to fluid. SION. Evel down, POOH w/tbg, RIH w/ clean- bg, SION. ole with tubing, pump wt. on backside, ump & rods & loaded & tested - held. F true and correct Ann E Ritchie Title REGULATORY /	Backed off ords, F -out bailer, clean ou ND BOP, set tbg a Rigged down. Well	ed date of starting any proposed work. If well is POOH, NDBOP, unset It to 6700', POOH, unchor, NU wellhead, put back on production.
directionally diffed, give subsurfa 10-30-97: Rigged up - anchor, pull IC 10-3I-97: Swab fluid le RIH w/SN & tl 11-3-97: Continue in ho RIH w/new pu 14 Thereby certify that the foregoid, is Signed (This space for Federal or State offic Approved by Conditions of approval. If any	ace locations and measured and true vertical depths for any person knowingly and wilffully to make to	Backed off ords, F out bailer, clean ou ND BOP, set tbg a Rigged down. Well f	Date

.