

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO.	30-025-34336
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	
Hare, JG	
8. Well No.	10
9. Pool name or Wildcat	Wildcat; Eunice-San Andres

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Collins & Ware, Inc.
3. Address of Operator 508 West Wall, Suite 1200, Midland, Texas 79701	4. Well Location Unit Letter <u>L</u> : <u>2083</u> Feet From The <u>South</u> Line and <u>716</u> Feet From The <u>West</u> Line Section <u>33</u> Township <u>21S</u> Range <u>37E</u> NMPM <u>Lea</u> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>3451 GL</u> <u>3465 KB</u> <u>3464 DF</u>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS <input type="checkbox"/>
OTHER <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <u>Perforate</u> <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3/24/98 Tag PBTD at 3916'. Pull GR/CCL from 3916 to 2400. Perforate San Andres from 3903 - 3907 with 5 shots. Acidize perms 3903 - 3907 with 500 gals 15% Ferchek acid.

3/27/98 Set CIBP at 3900'. Perforate San Andres from 3889 - 3894 with 1 JSPF (6 holes).

3/28/98 Perforate 1 JSPF 3860 - 61 and 3871 - 73 (5 holes). Set RBP at 3886 and tested to 1000#. Held okay. Acidize with 300 gals acid.

4/07/98 Release RBP. Go in hole and set CIBP at 3840'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Production Administrator DATE 4/15/98

TYPE OR PRINT NAME Dianne Sumrall TELEPHONE NO. (915)687-3435

(This space for State Use)

APPROVED BY Paul Krutz TITLE APR 21 1998 DATE APR 21 1998

CONDITIONS OF APPROVAL IF ANY