

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO.	30-025-34336
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	
Hare, JG	
8. Well No.	10
9. Pool name or Wildcat	Penrose Skelly Grayburg

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3451 GL 3465 KB 3464 DF

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Collins & Ware, Inc.
3. Address of Operator 508 West Wall, Suite 1200, Midland, Texas 79701	4. Well Location Unit Letter <u>L</u> : <u>2083</u> Feet From The <u>South</u> Line and <u>716</u> Feet From The <u>West</u> Line Section <u>33</u> Township <u>21S</u> Range <u>37E</u> NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3451 GL 3465 KB 3464 DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3/06/98 Spud 12 1/4" hole.

3/07/98 Run 8 5/8, 24# casing to 356'. Mix and pump 230 sx Premium plus with additives. Circulate 10 sx of cement to reserve pit.

3/08/98 Weld on wellhead. Test blinds and BOP. Start drilling 7 7/8" hole.

3/12/98 TD at 3950'. Run logs.

3/13/98 Run 5 1/2", 15.5# casing to 3950'. Mix and pump 650 sx Halliburton light Premium plus followed by 250 sx Howco Premium plus with additives. Circulate 130 sx light cement.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Dianne Sumrall TITLE Production Administrator DATE 4/15/98

TYPE OR PRINT NAME Dianne Sumrall TELEPHONE NO. (915)687-3435

(This space for State Use)

Original signed by
Paul Kautz
Geologist

APR 21 1998

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY