GAUCHO UNIT No. 3 Multi-Point Surface Use and Operations Plan Page 3

and other material not needed for further operations will be removed. The location will be cleared of all trash and junk, to leave the wellsite in as aesthetically pleasing a condition as possible.

- B. Unguarded pits, if any, containing fluid will be fenced until they have been filled.
- C. If the proposed well is non-productive, all rehabilitation and/or vegetation requirements of the Bureau of Land Management and the United States Geological Survey will be complied with and will be accomplished as expeditiously as possible. All pits will be filled and levelled within 300 days after abandonment.

11. TOPOGRAPHY

- A. The wellsite and access route are located in a relatively flat area.
- B. The top soil at the wellsite and access route is sandy.
- C. The vegetation cover at the wellsite is moderately sparse, with prairie grasses, some mesquite bushes, and shinnery oak.
- D. No wildlife was observed but it is likely that deer, rabbits, coyotes, and rodents traverse the area.

12. OPERATOR'S REPRESENTATIVES

A. The field representatives responsible for assuring compliance with the approved surface use plan are:

Michael R. Burton Division Operations Manager Santa Fe Energy Resouces, Inc. 550 W. Texas, Suite 1330 Midland, Texas 79701 915-686-6616 - office 915-556-7063 - cellular