District Office	Ene. Minera	State of New Me Is and Natural Re	esources Department	t	Form (Revise	d 1-1-89
<u>DISTRICT I</u> P.O. Box 1980, Hobbs, NM 88240		SERVATIC	ON DIVISION	WELL API NO.		
		anta Fe, NM 87	7505	30-025-34857		
P.O. Drawer DD, Artesia, NM 88210 <u>DISTRICT III</u> 1000 Rio Brazos Rd., Aztec, NM 87410				sIndicate Type of Lease STATE FEE State Oil & Gas Lease No. N/A 'Lease Name or Unit Agreement Name Dreessen		
1 Type of Well: OIL GAS WELL WELL		OTHER				
Name of Operator Trilogy Operating, Inc		· · · · · · · · · · · · · · · · · · ·		⊮Welt No. 1		
Address of Operator P.O. Box 7606, Midland, Texas 79708				Pool name or Wildcat House: San Andres		
•Well Location Unit Letter <u>G</u> : 19	80 Feet From The	North	Line and 1980	Feet From The	East	Line
Section	1 Township		Range38E	NMPM		County
-	₀Elevation 3587 GI	n (Show whether DF, R	RKB, RT, GR, etc.)			
11 Chec	k Appropriate Box	to Indicate Na	ature of Notice, R	eport, or Other I	Data	
NOTICE OF	FINTENTION TO	:	SUE	BSEQUENT RE	EPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND AB	BANDON X	REMEDIAL WORK		ALTERING CASIN	IG
EMPORARILY ABANDON	CHANGE PLA	NS	COMMENCE DRILLING	OPNS.	PLUG AND ANBAN	DONMEN
PULL OR ALTER CASING			CASING TEST AND CE	MENT JOB		
OTHER:						
			OTHER:			
12Describe Proposed or Completed Opwork) SEE RULE 1103.	erations (Clearly state all perti	inent details, and give		estimated date of starting	g any proposed	
 Describe Proposed or Completed Opwork) SEE RULE 1103. PLUGGING & ABANDONM 1) Set CIBP @ 3000' and cap 2) Set 75 sx cement plug acro 3) Set 10 sx surface plug from 4) No Capitain Reef is in this w 5) Install Dry Hole Marker 6) Clean Location and remove 	ENT WORKSHEET EN off w/ 25 sx of cement ss 8 5/8" csg shoe from 0' - 10' vell	CLOSED	e pertinent dates, including		g any proposed	· · ·
 work) SEE RULE 1103. PLUGGING & ABANDONM 1) Set CIBP @ 3000' and cap 2) Set 75 sx cement plug acro 3) Set 10 sx surface plug from 4) No Capitain Reef is in this w 5) Install Dry Hole Marker 	ENT WORKSHEET EN off w/ 25 sx of cement ss 8 5/8" csg shoe from 0' - 10' vell e equipment THE HOU PLIC	ICLOSED 1620' - 1720' -(COMMISSION JRS PRIOR TO	e pertinent dates, including	covered)	FLCT FLODS OCD	· · · · ·
 work) SEE RULE 1103. PLUGGING & ABANDONM 1) Set CIBP @ 3000' and cap 2) Set 75 sx cement plug acro 3) Set 10 sx surface plug from 4) No Capitain Reef is in this w 5) Install Dry Hole Marker 	ENT WORKSHEET EN off w/ 25 sx of cement ss 8 5/8" csg shoe from 0' - 10' vell e equipment THE HOC PLUC TO E	ICLOSED 1620' - 1720' -(1620' - 1720' -(SOMMISSION JRS PRIOR FO SOMMISSION JRS PRIOR FO	MUST RENOTIFIES THE BLOINNING VIONS FOR HEIC	covered)		
 Work) SEE RULE 1103. PLUGGING & ABANDONM 1) Set CIBP @ 3000' and cap 2) Set 75 sx cement plug acro 3) Set 10 sx surface plug from 4) No Capitain Reef is in this w 5) Install Dry Hole Marker 6) Clean Location and remove 	ENT WORKSHEET EN off w/ 25 sx of cement ss 8 5/8" csg shoe from 0' - 10' vell e equipment THE HOL PLIC TO S	ICLOSED 1620' - 1720' -(1620' - 1720' -(URS PRIOR FO 30' NG OPERA 50' NG OPERA 50' NG OPERA 50' NG OPERA	MUST RENOTIFIES THE BLOINNING VIONS FOR HEIC	2 24 OF 3 23	FLCT FLODS OCD	01
 work) SEE RULE 1103. PLUGGING & ABANDONM 1) Set CIBP @ 3000' and cap 2) Set 75 sx cement plug acro 3) Set 10 sx surface plug from 4) No Capitain Reef is in this w 5) Install Dry Hole Marker 6) Clean Location and remove 	ENT WORKSHEET EN off w/ 25 sx of cement ss 8 5/8" csg shoe from 0' - 10' vell e equipment THE HOL PUIC TO S THE HOL PUIC	ICLOSED 1620' - 1720' -(1620' - 1720' -(URS PRIOR FO 30' NG OPERA 50' NG OPERA 50' NG OPERA 50' NG OPERA	AUST RENOTIFIES THE BUONN NG UONS FOR HELO	2 24 OF 3 23	F.C. ED F.C.S. CCD	
 Work) SEE RULE 1103. PLUGGING & ABANDONM 1) Set CIBP @ 3000' and cap 2) Set 75 sx cement plug acro 3) Set 10 sx surface plug from 4) No Capitain Reef is in this w 5) Install Dry Hole Marker 6) Clean Location and remove 	ENT WORKSHEET EN off w/ 25 sx of cement ss 8 5/8" csg shoe from 0' - 10' vell e equipment THE HOL PUIC TO S THE HOL PUIC	ICLOSED 1620' - 1720' -(1620' - 1720' -(URS PRIOR FO 30' NG OPERA 50' NG OPERA 50' NG OPERA 50' NG OPERA	AUST RENOTIFIES THE BUONN NG UONS FOR HELO	2 24 OF 3 23	F. 255 000 DATE 11-23-	
 Work) SEE RULE 1103. PLUGGING & ABANDONM 1) Set CIBP @ 3000' and cap 2) Set 75 sx cement plug acro 3) Set 10 sx surface plug from 4) No Capitain Reef is in this w 5) Install Dry Hole Marker 6) Clean Location and remove I hereby certify that the information ab SIGNATURE Marker TYPE OR PRINT NAME Michael G. N 	ENT WORKSHEET EN off w/ 25 sx of cement ss 8 5/8" csg shoe from 0' - 10' vell e equipment THE HOL PUIC TO S THE HOL PUIC	ICLOSED 1620' - 1720' -(COMMISSION JRS PRIOR TO BOING COBRA E APPROABC Rebest of my knowled	AUSTRENOTIFIES THE BUONN NG UONSTORENOTIFIES	2 24 OF 3 23	F. 255 000 DATE 11-23-	

٩...