Submit 3 Copies To Appropriate District Office	State of New	Mexico		Form C-103
District I	Energy, Minerals and N	Natural Resources		May 27, 2004
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-025-02577	
District III	1220 South St. Francis Dr.		5. Indicate Type of Lease	rr 🗆
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505		STATE X F	EE 🗌
1220 S. St. Francis Dr., Santa Fe, NM		. -	E-1830	10.
87505	ES AND REPORTS ON WE	IIC		
(DO NOT USE THIS FORM FOR PROPOSA	ES AND REPORTS ON WE. LS TO DRILL OR TO DEEPEN OF	LLS R PLUG BACK TO A	7. Lease Name or Unit Ag	reement Name
DIFFERENT RESERVOIR. USE "APPLICA"	TION FOR PERMIT" (FORM C-10	1) FOR SUCH	Wilson State	
PROPOSALS.) 1. Type of Well: Oil Well G	as Well 🛛 Other Inje	ction	8. Well Number 2	
2. Name of Operator Hal J. Rasmussen Operating, Inc.			9. OGRID Number	
	iting, Inc.			
3. Address of Operator		_	10. Pool name or Wildcat	
550 W. Texas, Ste. 200	, Midland, TX 7970	1	Wilson Yates 7 RVI	RS
4. Well Location	2210	1. 0	2210	_
Omi Letter	2310 feet from the Sou			East line
Section 23	Township 21S	Range 34E	NMPM County	Lea
	11. Elevation (Show whether 3662'		2.)	
Pit or Below-grade Tank Application 🔲 or C	3002	GK		
		esh water well Di	istance from nearest surface water_	
Pit Liner Thickness: mil	Below-Grade Tank: Volume		Construction Material	· · · · · · · · · · · · · · · · · · ·
12. Check Ap	propriate Box to Indicat	e nature of notice	, Report of Other Data	
TEMPORARILY ABANDON	PLUG AND ABANDON [X] CHANGE PLANS [] MULTIPLE COMPL []		RILLING OPNS. P AND A	NG CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DE CASING/CEMEN	RILLING OPNS. P AND A	
OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. MIRU P&A Unit.	CHANGE PLANS MULTIPLE COMPL ced operations. (Clearly state 3. SEE RULE 1103. For Mu	COMMENCE DE CASING/CEMEN OTHER: all pertinent details, ar	RILLING OPNS. PAND A	ing estimated date
TEMPORARILY ABANDON DULL OR ALTER CASING DULL OF STATE	CHANGE PLANS MULTIPLE COMPL ced operations. (Clearly state 3. SEE RULE 1103. For Mu	COMMENCE DE CASING/CEMEN OTHER: all pertinent details, ar	RILLING OPNS. PAND A	ing estimated date
TEMPORARILY ABANDON DULL OR ALTER CASING DULL OF STATE	CHANGE PLANS MULTIPLE COMPL ed operations. (Clearly state). SEE RULE 1103. For Mu WOC & tag.	COMMENCE DE CASING/CEMEN OTHER: all pertinent details, ar	RILLING OPNS. PAND A	ing estimated date
TEMPORARILY ABANDON DULL OR ALTER CASING DULL OF STATE	CHANGE PLANS MULTIPLE COMPL ed operations. (Clearly state). SEE RULE 1103. For Mu WOC & tag.	COMMENCE DE CASING/CEMEN OTHER: all pertinent details, ar	RILLING OPNS. PAND A	ing estimated date
TEMPORARILY ABANDON DULL OR ALTER CASING DULL OF STATE OF THE CASING DULL OF THE CASING DULL OF THE CASING DULL OF THE CASING DULL OR ALTER CASING DULL OR A	CHANGE PLANS MULTIPLE COMPL ed operations. (Clearly state). SEE RULE 1103. For Mu WOC & tag. WOC & tag.	COMMENCE DE CASING/CEMEN OTHER: all pertinent details, auditiple Completions: A	RILLING OPNS. PAND A NT JOB Ind give pertinent dates, include Attach wellbore diagram of pro	ing estimated date
TEMPORARILY ABANDON DULL OR ALTER CASING DULL OF STATE	CHANGE PLANS MULTIPLE COMPL ed operations. (Clearly state). SEE RULE 1103. For Mu WOC & tag. WOC & tag. & circ. to surface	COMMENCE DE CASING/CEMEN OTHER: all pertinent details, an altiple Completions: A	RILLING OPNS. PAND A NT JOB Ind give pertinent dates, include Attach wellbore diagram of pro	ing estimated date
TEMPORARILY ABANDON DULL OR ALTER CASING DULL OF STATE	CHANGE PLANS MULTIPLE COMPL ed operations. (Clearly state). SEE RULE 1103. For Mu WOC & tag. WOC & tag. & circ. to surface	COMMENCE DE CASING/CEMEN OTHER: all pertinent details, an altiple Completions: A	RILLING OPNS. PAND A NT JOB Ind give pertinent dates, including the control of pro 6" & leave cmt. at clean location.	ing estimated date posed completion
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. MIRU P&A Unit. Spot 35 sx 3600-3500', Circulate hole w/ MLF. Spot 30 sx 1800-1700', Perf. 7" csg. @ 266'. Sqz. perfs. w/ 240 sx	CHANGE PLANS MULTIPLE COMPL ed operations. (Clearly state). SEE RULE 1103. For Mu WOC & tag. WOC & tag. & circ. to surface hors. Install dry	COMMENCE DE CASING/CEMEN OTHER: all pertinent details, au litiple Completions: A	RILLING OPNS. PAND A NT JOB PAND A nd give pertinent dates, include Attach wellbore diagram of pro	ing estimated date posed completion
TEMPORARILY ABANDON DULL OR ALTER CASING DULL OF STATE	CHANGE PLANS MULTIPLE COMPL ed operations. (Clearly state). SEE RULE 1103. For Mu WOC & tag. WOC & tag. & circ. to surface hors. Install dry	COMMENCE DE CASING/CEMEN OTHER: all pertinent details, au litiple Completions: A	RILLING OPNS. PAND A NT JOB PAND A nd give pertinent dates, include Attach wellbore diagram of pro	ing estimated date posed completion
TEMPORARILY ABANDON DULL OR ALTER CASING DULL OF STATE	CHANGE PLANS MULTIPLE COMPL ed operations. (Clearly state). SEE RULE 1103. For Mu WOC & tag. WOC & tag. & circ. to surface hors. Install dry	COMMENCE DE CASING/CEMEN OTHER: all pertinent details, au litiple Completions: A	RILLING OPNS. PAND A NT JOB PAND A nd give pertinent dates, include Attach wellbore diagram of pro	ing estimated date posed completion
TEMPORARILY ABANDON DULL OR ALTER CASING DULL OF STATE	CHANGE PLANS MULTIPLE COMPL ed operations. (Clearly state). SEE RULE 1103. For Mu WOC & tag. WOC & tag. & circ. to surface hors. Install dry	COMMENCE DE CASING/CEMEN OTHER: all pertinent details, au litiple Completions: A	RILLING OPNS. PAND A NT JOB PAND A nd give pertinent dates, include Attach wellbore diagram of pro	ing estimated date posed completion
TEMPORARILY ABANDON DULL OR ALTER CASING DULL OF STATE	CHANGE PLANS MULTIPLE COMPL ed operations. (Clearly state). SEE RULE 1103. For Mu WOC & tag. WOC & tag. & circ. to surface hors. Install dry	COMMENCE DE CASING/CEMEN OTHER: all pertinent details, au litiple Completions: A	RILLING OPNS. PAND A NT JOB PAND A nd give pertinent dates, include Attach wellbore diagram of pro	ing estimated date posed completion
TEMPORARILY ABANDON DULL OR ALTER CASING DULL OF STATE	CHANGE PLANS MULTIPLE COMPL ed operations. (Clearly state). SEE RULE 1103. For Mu WOC & tag. WOC & tag. & circ. to surface hors. Install dry	COMMENCE DE CASING/CEMEN OTHER: all pertinent details, au litiple Completions: A	RILLING OPNS. PAND A NT JOB PAND A nd give pertinent dates, include Attach wellbore diagram of pro	ing estimated date posed completion
TEMPORARILY ABANDON DULL OR ALTER CASING DULL OF STATE	CHANGE PLANS MULTIPLE COMPL ed operations. (Clearly state). SEE RULE 1103. For Mu WOC & tag. WOC & tag. & circ. to surface hors. Install dry	on the 7" X 1 hole marker & THE OIL CON BENOTIFIED BEGINNING	RILLING OPNS. PAND A NT JOB PAND A nd give pertinent dates, include Attach wellbore diagram of pro 6" & leave cmt. at clean location. SERVATION DIVISION D 24 HOURS PRIOR OF PLUGGING OPER	ing estimated date posed completion surface N MUST TO THE RATIONS.
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. MIRU P&A Unit. Spot 35 sx 3600-3500', Circulate hole w/ MLF. Spot 30 sx 1800-1700', Perf. 7" csg. @ 266'. Sqz. perfs. w/ 240 sx on the inside. RDMO. Cut off WH & anc	CHANGE PLANS MULTIPLE COMPL ed operations. (Clearly state). SEE RULE 1103. For Mu WOC & tag. WOC & tag. & circ. to surface hors. Install dry ove is true and complete to the	OTHER: all pertinent details, are altiple Completions: A string on the 7" X 1 hole marker & THE OIL CON BE NOTIFIED BEGINNING (Co.)	RILLING OPNS. PAND A NT JOB PAND A Ind give pertinent dates, include Attach wellbore diagram of pro 6" & leave cmt. at clean location. SERVATION DIVISION D 24 HOURS PRION OF PLUGGING OPER	ing estimated date posed completion surface N MUST TO THE RATIONS.
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. MIRU P&A Unit. Spot 35 sx 3600-3500', Circulate hole w/ MLF. Spot 30 sx 1800-1700', Perf. 7" csg. @ 266'. Sqz. perfs. w/ 240 sx on the inside. RDMO. Cut off WH & ance of the starting and the constructed or clo	CHANGE PLANS MULTIPLE COMPL ed operations. (Clearly state). SEE RULE 1103. For Mu WOC & tag. WOC & tag. & circ. to surface hors. Install dry ove is true and complete to a seed according to NMOCD guideling ove is true and complete to a seed according to NMOCD guideling over its true and complete to a seed according to NMOCD guideling over its true and complete to a seed according to NMOCD guideling	OTHER: all pertinent details, are altiple Completions: A string on the 7" X 1 hole marker & THE OIL CON BE NOTIFIED BEGINNING (Co.)	RILLING OPNS. PAND A NT JOB PAND A Ind give pertinent dates, include Attach wellbore diagram of pro 6" & leave cmt. at clean location. SERVATION DIVISION D 24 HOURS PRION OF PLUGGING OPER	ing estimated date posed completion surface N MUST TO THE RATIONS.
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. MIRU P&A Unit. Spot 35 sx 3600-3500', Circulate hole w/ MLF. Spot 30 sx 1800-1700', Perf. 7" csg. @ 266'. Sqz. perfs. w/ 240 sx on the inside. RDMO. Cut off WH & ance of the starting and the constructed or clo	CHANGE PLANS MULTIPLE COMPL ed operations. (Clearly state). SEE RULE 1103. For Mu WOC & tag. WOC & tag. & circ. to surface hors. Install dry ove is true and complete to the	OTHER: all pertinent details, are altiple Completions: A string on the 7" X 1 hole marker & THE OIL CON BE NOTIFIED BEGINNING (Co.)	RILLING OPNS. PAND A NT JOB PAND A Ind give pertinent dates, include Attach wellbore diagram of pro 6" & leave cmt. at clean location. SERVATION DIVISION D 24 HOURS PRION OF PLUGGING OPER	ing estimated date posed completion surface N MUST TO THE RATIONS.
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. MIRU P&A Unit. Spot 35 sx 3600-3500', Circulate hole w/ MLF. Spot 30 sx 1800-1700', Perf. 7" csg. @ 266'. Sqz. perfs. w/ 240 sx on the inside. RDMO. Cut off WH & anc	CHANGE PLANS MULTIPLE COMPL ed operations. (Clearly state). SEE RULE 1103. For Mu WOC & tag. WOC & tag. & circ. to surface hors. Install dry ove is true and complete to be sed according to MOCD guideling The second of t	on the 7" X 1 hole marker & THE OIL CON BENOTIFIED BENOTIFIED Construction of the state of th	RILLING OPNS. PAND A NT JOB PAND A Ind give pertinent dates, include Attach wellbore diagram of pro 6" & leave cmt. at clean location. SERVATION DIVISION D 24 HOURS PRION OF PLUGGING OPE ge and belief. I further certify the or an (attached) alternative OCD DATE	ing estimated date posed completion surface N MUST TO THE ATIONS. at any pit or belowapproved plan
TEMPORARILY ABANDON DULL OR ALTER CASING DULL OF STATE	CHANGE PLANS MULTIPLE COMPL ed operations. (Clearly state). SEE RULE 1103. For Mu WOC & tag. WOC & tag. & circ. to surface hors. Install dry ove is true and complete to be sed according to MOCD guideling The second of t	on the 7" X 1 hole marker & THE OIL CON BENOTIFIED BENOTIFIED Construction of the state of th	RILLING OPNS. PAND A NT JOB PAND A Ind give pertinent dates, include Attach wellbore diagram of pro 6" & leave cmt. at clean location. SERVATION DIVISION D 24 HOURS PRION OF PLUGGING OPE ge and belief. I further certify the or an (attached) alternative OCD DATE	ing estimated date posed completion surface N MUST TO THE ATIONS. at any pit or belowapproved plan
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. MIRU P&A Unit. Spot 35 sx 3600-3500', Circulate hole w/ MLF. Spot 30 sx 1800-1700', Perf. 7" csg. @ 266'. Sqz. perfs. w/ 240 sx on the inside. RDMO. Cut off WH & anc Type or print name For State Use Only ROSE TO STATE Use Only	CHANGE PLANS MULTIPLE COMPL ed operations. (Clearly state). SEE RULE 1103. For Mu WOC & tag. WOC & tag. & circ. to surface hors. Install dry ove is true and complete to be sed according to MOCD guideling The second of t	on the 7" X 1 hole marker & THE OIL CON BENOTIFIED BENOTIFIED Construction of the state of th	RILLING OPNS. PAND A NT JOB PAND A Ind give pertinent dates, include Attach wellbore diagram of pro 6" & leave cmt. at clean location. SERVATION DIVISION D 24 HOURS PRION OF PLUGGING OPE ge and belief. I further certify the or an (attached) alternative OCD DATE	ing estimated date posed completion surface N MUST TO THE ATIONS. at any pit or belowapproved plan
TEMPORARILY ABANDON DULL OR ALTER CASING DULL OF STATE DULL OR ALTER CASING DULL OF STATE DULL OR ALTER CASING DUL	CHANGE PLANS MULTIPLE COMPL ed operations. (Clearly state). SEE RULE 1103. For Mu WOC & tag. WOC & tag. & circ. to surface hors. Install dry ove is true and complete to be sed according to MOCD guideling The second of t	OTHER: all pertinent details, an altiple Completions: A substitute of the completions of the completion o	RILLING OPNS. PAND A NT JOB PAND A Ind give pertinent dates, include Attach wellbore diagram of pro 6" & leave cmt. at clean location. SERVATION DIVISION D 24 HOURS PRIOR OF PLUGGING OPER ge and belief. I further certify the or an (attached) alternative OCD-	ing estimated date posed completion surface N MUST TO THE ATIONS. at any pit or belowapproved plan
TEMPORARILY ABANDON DULL OR ALTER CASING DULL OF Starting any proposed work or recompletion. MIRU P&A Unit. Spot 35 sx 3600-3500', Circulate hole w/ MLF. Spot 30 sx 1800-1700', Perf. 7" csg. @ 266'. Sqz. perfs. w/ 240 sx on the inside. RDMO. Cut off WH & ance are constructed or closured tank has been/will be constructed to c	CHANGE PLANS MULTIPLE COMPL ed operations. (Clearly state). SEE RULE 1103. For Mu WOC & tag. WOC & tag. & circ. to surface thors. Install dry ove is true and complete to Page 1 according to MOCD guideling	OTHER: all pertinent details, an altiple Completions: A substitute of the completions of the completion o	RILLING OPNS. PAND A NT JOB PAND A Ind give pertinent dates, include Attach wellbore diagram of pro 6" & leave cmt. at clean location. SERVATION DIVISION D 24 HOURS PRION OF PLUGGING OPE ge and belief. I further certify the or an (attached) alternative OCD DATE	ing estimated date posed completion surface N MUST TO THE ATIONS. at any pit or belowapproved plan
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. MIRU P&A Unit. Spot 35 sx 3600-3500', Circulate hole w/ MLF. Spot 30 sx 1800-1700', Perf. 7" csg. @ 266'. Sqz. perfs. w/ 240 sx on the inside. RDMO. Cut off WH & ance of the start of	CHANGE PLANS MULTIPLE COMPL ed operations. (Clearly state). SEE RULE 1103. For Mu WOC & tag. WOC & tag. & circ. to surface thors. Install dry ove is true and complete to Page 1 according to MOCD guideling	OTHER: all pertinent details, an altiple Completions: A substitute of the completions of the completion o	RILLING OPNS. PAND A NT JOB PAND A Ind give pertinent dates, include Attach wellbore diagram of pro 6" & leave cmt. at clean location. SERVATION DIVISION D 24 HOURS PRION OF PLUGGING OPE ge and belief. I further certify the or an (attached) alternative OCD DATE	ing estimated date posed completion surface N MUST TO THE ATIONS. at any pit or belowapproved plan

PLUGGING & ABANDONMENT WORKSHEET (2 STRING CSNG) OPERATOR Hal 3 Rasmusson State LEASENAME Wilson WELL 23 TWN 2/5 RNG 34 E SECT 2310 BWL 2310 NOL **FROM** FORMATION @ TO 3815 TO: FORMATION @ PBTD PBTD: 3748,5 TOC DETERMINED BY TOC perforate SET @ SIZE cm+4/250 5x 216 76 Circ SURFACE @ 266 INTMED 1 INTMED 2 1500 cala 3612 PROD BOT TOC DETERMINED BY SIZE TOP 30 LINER 1 1800 LINER 2 10 TOP - BOTTOM CUT & PULL @ 1700 PERFS INTMED 1 INTMED 2 OPENHOLE PROD 355F *REQUIRED PLUGS DISTRICT I DEPTH PLUG TYPE SACKS RUSTLER (ANHYD) 3600' CMNT PLUG TATES fo EXAMPLES 1500 3500 OUEEN 35 36003500 TAG CMT PLUG#1 GRAYEUKG cint PLUO#2 AN ANDRES 240 266. 5UM C MAY E* DULTS PLUGE APITAN REEF PLUG#4 PLUG#5 MANABE FLUG 4 6 BELL CARTON PLUO 41 CHEERY CANYON PLUG# 2 BELLETY CANYON PLUG 61 1010E SP2.040 ATHEROLE 9 EXLL9 LINEBRY PLU0## DRINGKARO PCUD44 PCLUG # 10 PLUGS PLUDS PEKK ITRAWN ATOKA **WORROW** TD 3815 DEVOIDAN

Current

WILSON STATE #2 (OLD #21)

2310' FSL & 2310' FEL Sec 23, T-21S, R-34E Lea County, NM 30-025-02577

B-11610 16" 70# @216' W/250 SX (CIRC)

TON Suf 1745

Probable casing part @ about 8 jts down

Could not get b
Taysed @ 7 It Down w TUBING

Cal Tol

1500 Was converted to disposal in 1969

7" @ 3612 W/ 350sx

TD: 3815 PBTD: 3748.5?