

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
<b>B-163</b>

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>B. N. Muncy, Jr.</b>	8. Farm or Lease Name <b>Lea State</b>
3. Address of Operator <b>P. O. Box 196 Artesia, New Mexico 88210</b>	9. Well No. <b>2</b>
4. Location of Well UNIT LETTER <b>H</b> , <b>2311</b> FEET FROM THE <b>North</b> LINE AND <b>990</b> FEET FROM THE <b>East</b> LINE, SECTION <b>2</b> TOWNSHIP <b>21 S</b> RANGE <b>33 E</b> NMPM.	10. Field and Pool, or Wildcat <b>Lynch (Y,SR)</b>
15. Elevation (Show whether DF, RT, GR, etc.)	12. County <b>Lea</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Intend to plug and abandon well as follows:

1. Set 25 sack cement plug over perforation
2. Heavy mud to surface
3. Set 10 Sacks cement plug at Surface
4. Set dry hole marker
5. Clean up location

25 sacks @ top set 1800-1900'  
24 hr. no fire

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED B. N. Muncy, Jr. TITLE Operator DATE 9/10/73

APPROVED BY Joe D. Ramey TITLE Dist. I, Supv. DATE 9/10/73  
CONDITIONS OF APPROVAL, IF ANY: