DISTRIBUTION SANTA FE		Supersedes Old
SANTAFE	-1	C-102 and C-103
	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
FILE		
U.S.G.S.		5a. Indicate Type of Lease
LAND OFFICE	- 41 · · · · · · · · · · · · · · · · · ·	State Fee.
OPERATOR		5. State Oil & Gas Lease No.
OT ENAY ON	<u>.</u>	E-393-2
CLUMPI	CV NOTICES IN DEPOSIT OF THE CO.	mmmmmm
SUNDS	RY NOTICES AND REPORTS ON WELLS OPOSALS TO BRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. FION FOR PERMIT —" (FORM C-101) FOR SUCH PROPOSALS.)	
	TION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
l. OIL TO GAS		7. Unit Agreement Name
WELL WELL	OTHER-	
2. Name of Operator		8. Farm or Lease Name
Morris R. Ant	MAIT	Amerada State
3. Address of Operator		9. Well No.
Box 2010, Hob	bs, New Mexico 88240	3
4. Location of Well		10. Field and Pool, or Wildcat
n	660 North 990	_ '
UNIT LETTER,	660 FEET FROM THE North LINE AND 990 FEET FR	Eumont
	01 0 05 7	
THE West LINE, SECT	TOWNSHIP 21-S RANGE 35-E NAME	
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	3572' GL	Lea
16.		
	Appropriate Box To Indicate Nature of Notice, Report or 6	Other Data
NOTICE OF I	NTENTION TO: SUBSEQUE	NT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
	COMMENCE DRILLING OPNS.	X
TEMPORARILY ABANDON		
TEMPORARILY ABANDON		PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	PLUG AND ABANDONMENT
F==1		PLUG AND ABANDONMENT
F==1	CHANGE PLANS CASING TEST AND CEMENT JOB	PLUG AND ABANDONMENT
OTHER	CHANGE PLANS CASING TEST AND CEMENT JOB OTHER	
other	CHANGE PLANS OTHER OTHER Perations (Clearly state all pertinent details, and give pertinent dates, include	ing estimated date of starting any propose
other 17. Describe Proposed or Completed Owork) SEE RULE 1103. Well plugged 1. Spotte 2. Loaded 3. Cut an 4. Spotte 5. Spotte 6. Spotte	CHANGE PLANS CASING TEST AND CEMENT JOB OTHER	ing estimated date of starting any propose -3847'. stub @ 1000'.
other 17. Describe Proposed or Completed Owork) SEE RULE 1103. Well plugged 1. Spotte 2. Loaded 3. Cut and 4. Spotte 5. Spotte 6. Spotte Plugged and a	perations (Clearly state all pertinent details, and give pertinent dates, included and abandoned as follows: and abandoned as follows: and 25 sx cement plug across perfs 3673' hole with mud-laden fluid. and pulled 1000' of 6" casing. and 25 sx. cement plug across 6" casing and 30 sx. cement plug across 10-3/4" cased 10 sx surface plug with marker. abandoned 18 October, 1969.	-3847'.
other 17. Describe Proposed or Completed Owork) SEE RULE 1103. Well plugged 1. Spotte 2. Loaded 3. Cut an 4. Spotte 5. Spotte 6. Spotte Plugged and a	change plans casing test and cement Job other perations (Clearly state all pertinent details, and give pertinent dates, included and abandoned as follows: and abandoned as follows: and 25 sx cement plug across perfs 3673' and pulled 1000' of 6" casing. and 25 sx. cement plug across 6" casing and 30 sx. cement plug across 10-3/4" cased 10 sx surface plug with marker. Abandoned 18 October, 1969.	-3847'. Btub @ 1000'. Bing shoe @ 302'.
other 17. Describe Proposed or Completed Owork) SEE RULE 1103. Well plugged 1. Spotte 2. Loaded 3. Cut an 4. Spotte 5. Spotte 6. Spotte Plugged and a	change plans casing test and cement Job other perations (Clearly state all pertinent details, and give pertinent dates, included and abandoned as follows: and abandoned as follows: and 25 sx cement plug across perfs 3673' and pulled 1000' of 6" casing. and 25 sx. cement plug across 6" casing and 30 sx. cement plug across 10-3/4" cased 10 sx surface plug with marker. Abandoned 18 October, 1969.	-3847'. Btub @ 1000'. Bing shoe @ 302'.