

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
B-1671

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Atlantic Richfield Company	8. Farm or Lease Name Atlantic State
3. Address of Operator P. O. Box 1710, Hobbs, New Mexico 88240	9. Well No. 1
4. Location of Well UNIT LETTER <u>P</u> <u>330</u> FEET FROM THE <u>East</u> LINE AND <u>990</u> FEET FROM THE <u>South</u> LINE, SECTION <u>25</u> TOWNSHIP <u>21S</u> RANGE <u>35E</u> NMPM.	10. Field and Pool, or Wildcat Eumont Gas
15. Elevation (Show whether DF, RT, GR, etc.) 3630' DF	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:


SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 4530', PBD 3763'. Presently completed in Eumont Gas perms 3588-3747'. Well is shut in.
9-5/8" OD 32# csg set @ 298' & cmtd w/225 sx.
5-1/2" OD 14# csg set @ 4518' & cmtd w/400 sx.
This well was unsuccessfully recompleted in the Eumont gas zone 3588-3747'. No other zones of interest to test. Propose to plug & abandon in the following manner:
1. Rig up, install BOP. POH w/completion assembly.
2. Run 5 1/2" CIBP & set @ approx 3580'. Spot 35' cmt plug on top.
3. Fill hole w/heavy gelled mud between all plugs.
4. Cut & pull 5 1/2" OD csg as indicated by free pt. (approx 2000').
5. Spot 100' cmt plug across 5 1/2" OD cst stub.
6. Spot 100' cmt plug across top of salt section @ 1625'.
7. Spot 100' cmt plug across 9-5/8" OD csg shoe @ 298'.
8. Spot 10 sk cmt plug @ surface, install regulation dry hole marker, clean & level location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED 	TITLE <u>Dist. Drlg. Supv.</u>	DATE <u>6/17/75</u>
APPROVED BY <u>John R. Ryan</u> Geologist	TITLE <u>Geologist</u>	DATE <u>6/17/75</u>
CONDITIONS OF APPROVAL, IF ANY:		