

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	B-1535

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- INJECTION WELL	7. Unit Agreement Name Eumont Hardy Unit
2. Name of Operator CONTINENTAL Oil Company	8. Farm or Lease Name Eumont Hardy Unit
3. Address of Operator Box 460 Lords, N.M. 88240	9. Well No. 31
4. Location of Well UNIT LETTER A, 660 FEET FROM THE NORTH LINE AND 600 660 FEET FROM THE E LINE, SECTION 1 TOWNSHIP 21-S RANGE 36-E N.M.P.M.	10. Field and Pool, or Wildcat EUMONT GATES TRURS
15. Elevation (Show whether DF, RT, GR, etc.) 3496 BHF	12. County LEA

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Clean-out & acidize.

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

SUBJECT well WAS WORKED OVER AS FOLLOWS:

- rig up, pull in j. eqpt.
- RUN 4 3/4" bit AND CLEANOUT FROM 3723'-3780'
- CIRC. HOLE TO CLEAN.
- RUN RET. PKR ON 2" TBG TO 3440'
- ACIDIZE w/ 3000 gals total, mod 202 acid w/ additive.
- divert between each of 3 stages w/ 1000# rock salt & gelled brine.
- pull work string & pk.
- RAN PKR on CMT. LINED TBG,
- rel. rig & place well on injection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W. A. Butterfield TITLE Admin. Supr. DATE 8-7-78

APPROVED BY Jerry Seaton TITLE Dist. 1, Supv. DATE AUG 9 1978

CONDITIONS OF APPROVAL, IF ANY: