lovember 1983) 'c-merly 9331)	BUREAL	IE. OF TH	NAGEMENT	2 July 10 July	*	5. LEASE DESIGNATION	VAND BREIAL NO.
SUNDI (Do not use this for	RY NOT	CES AND RE	PORTS O	N WELLS		6. IF INDIAN, ALLOTTI	E OR TRIBE NAME
		5				7. UNIT AGREEMENT N	
OIL CAN WELL	OTHER IT	njector				Eunice Monume	
Chevron U.S.A.	Inc						
ADDRESS OF OPERATOR		NM 88240 ·				9. WELL NO. 259	
P. O. Box 670, Hobbs, NM 88240 Locarion or well (Report location clearly and in accordance with any State requirements." See also space 17 below.) At surface						10. FIELD AND FOOL, OR WILDCAT Eunice Monument	
		Landon and Anna and A Anna an Anna an Anna an Anna an			F	11. SBC., T., E., M., OR SUEVEY OR ARE	RLK. AND
Unit V 660' FSI	L & 1980	' FŴL	•		2 9	Sec 4, T21S,	R36E
. PERMIT NO.		15. ELEVATIONS (SE 3582 GL	low whither DF, 1	tT, R , etc.)		12. COUNTY OF PARIS Lea	H 18. STATE NM
· · · · · · · · · · · · · · · · · · ·	Check App	propriate Box Ta	Indicate No	iture of Notice, Rep	port, or Ot	her Data	
NOT	ICE OF INTENT	10N TO:				NT EMPORT OF:	
TEST WATER SHUT-OFF	P0	CLL OR ALTER CASIN	o	WATER SHUT-OFF		REPAIRING	WELL
FRACTURE TREAT Shoot of Acidize		ULTIPLE COMPLETE		FRACTURE TREATM		ALTERING (
REPAIR WELL		HANGE PLANS		(Other)			
		HANGE PLANS		(01461)			
(Other) CONVERT	to Injec	tor ATIONE (Clearly sta ally drilled, give an 3900'. Run	logs fron	(Norm: Rep Completion details, and give pertin ons and measured and to n 3000' to TD.	or Recomplet nent dates, in true vertical Evalua	depths for all marke	orm.) ite of starting an rs and sones pert etermine
(Other) COnvert DESCRIBE PROPOSED OR CO proposed work. If we nent to this work.)* Clean out well	to Injec NPLETED OPER HI is direction to TD @ al Grayb	tor ATIONS (Clearly sta ally drilled, give an 3900'. Run urg perforat	logs from	(Norm: Rep Completion details, and give pertin ns and measured and to n 3000 ¹ to TD. needed. Perfe	or Recomplet nent dates, is true vertical Evalua Orate, i	tion Beport and Log for neluding estimated da depths for all marked ate logs to di f necessary,	orm.} the of starting an rs and sones pert etermine from logs
(Other) Convert DESCRIBE PROPOSED OR CO proposed work. If ment to this work.)* Clean out well if any addition Acidize as nece	to Injec MPLETED OPER HI is direction to TD @ al Grayb ssary.	tor ATIONS (Clearly sta ally drilled, give an 3900'. Run urg perforat	logs from tions are njection.	(Norm: Rep Completion details, and give pertin ins and measured and to a 3000' to TD. needed. Perfu Test casing,	or Recomplet nent dates, is true vertical Evalua Orate, i	tion Beport and Log for neluding estimated da depths for all marked ate logs to di f necessary,	orm.} the of starting an rs and sones pert etermine from logs
(Other) Convert DESCRIBE PROPOSED OR CO proposed work. If ment to this work.)* Clean out well if any addition Acidize as nece	to Injec MPLETED OPER HI is direction to TD @ al Grayb ssary.	tor ATTONE (Clearly sta ally drilled, give an 3900'. Run urg perforat Equip for in	logs from tions are njection.	(Norm: Rep Completion details, and give pertin ins and measured and to a 3000' to TD. needed. Perfu Test casing,	or Recomplet nent dates, is true vertical Evalua Orate, i	tion Beport and Log for neluding estimated da depths for all marked ate logs to di f necessary,	orm.} the of starting an rs and sones pert etermine from logs
(Other) Convert DESCRIBE PROPOSED OR CO proposed work. If nent to this work.)* Clean out well if any addition Acidize as nece	to Injec MPLETED OPER HI is direction to TD @ al Grayb ssary.	tor ATTONE (Clearly sta ally drilled, give an 3900'. Run urg perforat Equip for in	logs from tions are njection.	(Norm: Rep Completion details, and give pertin ins and measured and to a 3000' to TD. needed. Perfu Test casing,	or Recomplet nent dates, is true vertical Evalua Orate, i	tion Beport and Log for neluding estimated da depths for all marked ate logs to di f necessary,	orm.} the of starting an rs and sones pert etermine from logs
(Other) Convert DESCRIBE PROPOSED OR CO proposed work. If nent to this work.)* Clean out well if any addition Acidize as nece	to Injec MPLETED OPER HI is direction to TD @ al Grayb ssary.	tor ATTONE (Clearly sta ally drilled, give an 3900'. Run urg perforat Equip for in	logs from tions are njection.	(Norm: Rep Completion details, and give pertin ins and measured and to a 3000' to TD. needed. Perfu Test casing,	or Recomplet nent dates, is true vertical Evalua Orate, i	tion Beport and Log for neluding estimated da depths for all marked ate logs to di f necessary,	orm.} the of starting an rs and sones pert etermine from logs
(Other) Convert DESCRIBE PROPOSED OR CO proposed work. If ment to this work.)* Clean out well if any addition Acidize as nece	to Injec MPLETED OPER HI is direction to TD @ al Grayb ssary.	tor ATTONE (Clearly sta ally drilled, give an 3900'. Run urg perforat Equip for in	logs from tions are njection.	(Norm: Rep Completion details, and give pertin ins and measured and to a 3000' to TD. needed. Perfu Test casing,	or Recomplet nent dates, is true vertical Evalua Orate, i	tion Beport and Log for neluding estimated da depths for all marked ate logs to di f necessary,	orm.} the of starting an rs and sones pert etermine from logs
(Other) Convert DESCRIBE PROPOSED OR CO proposed work. If ment to this work.)* Clean out well if any addition Acidize as nece	to Injec MPLETED OPER HI is direction to TD @ al Grayb ssary.	tor ATTONE (Clearly sta ally drilled, give an 3900'. Run urg perforat Equip for in	logs from tions are njection.	(Norm: Rep Completion details, and give pertin ins and measured and to a 3000' to TD. needed. Perfu Test casing,	or Recomplet nent dates, is true vertical Evalua Orate, i	tion Beport and Log for neluding estimated da depths for all marked ate logs to di f necessary,	orm.} the of starting an rs and sones pert etermine from logs
(Other) Convert DESCRIBE PROPOSED OR CO proposed work. If ment to this work.)* Clean out well if any addition Acidize as nece	to Injec MPLETED OPER HI is direction to TD @ al Grayb ssary.	tor ATTONE (Clearly sta ally drilled, give an 3900'. Run urg perforat Equip for in	logs from tions are njection.	(Norm: Rep Completion details, and give pertin ins and measured and to a 3000' to TD. needed. Perfu Test casing,	or Recomplet nent dates, is true vertical Evalua Orate, i	tion Beport and Log for neluding estimated da depths for all marked ate logs to di f necessary,	orm.} the of starting an rs and sones pert etermine from logs
(Other) Convert DESCRIBE (MOPOSED OR CO proposed work. If we nent to this work.)* Clean out well if any addition Acidize as nece 30 minutes. Re	to Injec MPLETED OPER to TD @ al Grayb ssary. turn wel	tor ATIONE (Clearly sta ally drilled, give an Urg perforat Equip for in 1 to product	logs from tions are njection.	(Norm: Rep Completion details, and give pertin ins and measured and to a 3000' to TD. needed. Perfu Test casing,	or Recomplet nent dates, is true vertical Evalua Orate, i	tion Beport and Log for neluding estimated da depths for all marked ate logs to di f necessary,	orm.} the of starting an rs and sones pert etermine from logs
(Other) Convert DESCRIBE PROPOSED OR CO proposed work. If ment to this work.)* Clean out well if any addition Acidize as nece	to Injec MPLETED OPER to TD @ al Grayb ssary. turn wel	tor ATIONE (Clearly sta ally drilled, give an Urg perforat Equip for in 1 to product	logs from tions are njection. tion as ar	(Norm: Rep Completion details, and give pertin ins and measured and to a 3000' to TD. needed. Perfu Test casing,	or Recomplet ment dates, in Evalua orate, i packer,	ton Beport and Log for including estimated da depths for all marke if necessary, , and tubing	orm.} the of starting an rs and sones pert etermine from logs
(Other) Convert DESCRIBE (MOPOSED OR CO proposed work. If we nent to this work.)* Clean out well if any addition Acidize as nece 30 minutes. Re 1 hereby certify that the 	to Injec MPLETED OPER HI is direction to TD @ al Grayb ssary. turn wel foregoing is foregoing is foregoing is	tor ATIONE (Clearly sta ally drilled, give an 3900'. Run urg perforat Equip for in 1 to product true and correct CCY use)	logs from tions are njection. tion as ar	(Norr: Rep Completion details, and give pertin- ns and measured and in n 3000' to TD. needed. Perfu Test casing, n injector.	or Recomplet ment dates, in Evalua orate, i packer,	ncluding estimated da depths for all marked if necessary, , and tubing	etermine from logs to 500 psi
(Other) CONVERT DESCRIBE (MOPOSED OR CO proposed work. If we nent to this work.)* Clean out well if any addition Acidize as nece 30 minutes. Re 30 minutes. Re I hereby certify that the SIGNED	to Injec MPLETED OPER HI is direction to TD @ al Grayb ssary. turn wel foregoing is foregoing is for State office OVAL, IF AN	tor ATIONE (Clearly sta ally drilled, give an 3900'. Run urg perforat Equip for in 1 to product trye and correct CCY use)	logs from tions are njection. tion as ar	(Norr: Rep Completion details, and give pertin- ns and measured and in n 3000' to TD. needed. Perfu Test casing, n injector.	or Recomplet ment dates, in Evalua orate, i packer,	ton Beport and Log for including estimated da depths for all marke if necessary, , and tubing	etermine from logs to 500 psi

Title 1805. States in 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.