(Formerly 9–331) DEPARTMENT OF TH BUREAU OF LAND MA		Budget Bureau No. 1004-0135 Expires August 31, 1985 5. LEASE DESIGNATION AND SERIAL NO. LC 031740 B
SUNDRY NOTICES AND R (Do not use this form for proposals to drill or to de Use "APPLICATION FOR PERMIT	EPORTS ON WELLS repen or plug back to a different reservoir. "" for such proposais.)	6. IF INDIAN, ALLOTTEE OR TRISE NAME
OIL GAS OTHER 2. NAME OF OPERATOR		7. UNIT AGREEMENT NAME Eunice Monument South Unit
Chevron U.S.A. Inc.		S. FARM OR LEASE NAME
P.O. Box 670, Hobbs, New Mexico 8824 Location of well (Report location clearly and in according See also space 17 below.) At surface	O sace with any State requirements.	9. WELL NO. 180 10. FIELD AND FOOL, OR WILDCAT Eunice Monument G/SA
		11. SEC., T., R., M., OR REX. AND SURVEY OR AREA
Unit A, 627 FNL & 660 FEL 14. PERMIT NO. 15. ELEVATIONS (SI	now whether DF, RT, GR, etc.)	Sec. 4, T21S, R36E .
3522 GL		Lea NM
Check Appropriate Box To	Indicate Nature of Notice, Report, or O	ther Data
PCLL OR ALTER CASIN PRACTURE TREAT BHOOT OR ACIDIZB REPAIR WELL (Other) Deepen Add Perforations Aci	FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) (NOTE: Report results of	ALTERING CARING ABANDONMENT*
17. DESCRIBE PROPOSED OR COMPLETED OPSRATIONS (Clearly star proposed work. If well is directionally drilled, give at ment to this work.) *	te all pertinent details, and give pertinent dates, i ibsurface locations and measured and true vertical	ueptus for all markers and tones perti-
Clean out to TD @ 3825 . Deepen fr logs indicate. Acidize as necessary	te all pertinent details, and give pertinent dates, in the surface locations and measured and true vertical com 3825 to 3871 Log well	nciuding estimated date of starting any depths for all markers and sones perti-
Clean out to TD @ 3825 . Deepen fr	te all pertinent details, and give pertinent dates, in the surface locations and measured and true vertical com 3825 to 3871 Log well	nciuding estimated date of starting any depths for all markers and sones perti-
Clean out to TD @ 3825 . Deepen fr	te all pertinent details, and give pertinent dates, in the surface locations and measured and true vertical com 3825 to 3871 Log well	nciuding estimated date of starting any depths for all markers and sones perti-
Clean out to TD @ 3825 . Deepen fr	te all pertinent details, and give pertinent dates, in the surface locations and measured and true vertical com 3825 to 3871 Log well	nciuding estimated date of starting any depths for all markers and sones perti-
Clean out to TD @ 3825 . Deepen fr logs indicate. Acidize as necessary	te all pertinent details, and give pertinent dates, in the surface locations and measured and true vertical com 3825 to 3871 Log well	nciuding estimated date of starting any depths for all markers and sones perti-
Clean out to TD @ 3825. Deepen fr logs indicate. Acidize as necessary	te all pertinent details, and give pertinent dates, in the surface locations and measured and true vertical com 3825 to 3871 Log well	nciuding estimated date of starting any depths for all markers and sones perti-