STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

	T	
DISTRIBUTION		Π
BANTA FE		
FILE		·
U.S.G.S.		
LAND OFFICE		
OPERATOR	7-	

APPROVED BY DISTRICT I SUPERVIECE

CONDITIONS OF APPROVAL, IF ANY:

OIL CONSERVATION DIVISION

DISTRIBUTION	OLE CONSERVATION DIVISION	
BANTA FE	P. O. BOX 2088	Form C-103 Revised 10-1-78
FILE	SANTA FE, NEW MEXICO 87501	KE41250 (U-1-/
		5a. Indicate Type of Lease
U.S.G.S.	-	State X Fee
OPERATOR .		
GERATOR		5. State Oil & Gas Lease No.
SUNDR	Y NOTICES AND REPORTS ON WELLS POSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVE ON FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
USE "APPLICATI	POSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVI ON FOR PERMIT \rightarrow " (FORM C-101) FOR SUCH PROPOSALS.)	OIR. (
1.		7. Unit Agreement Name
WELL GAS WELL	OTHER Injector	Eunice Monument South L
2. Name of Operator	111,100 001	8. Farm or Lease Name
Chevron U.S.A. Inc.		
3. Address of Operator		9. Well No.
•	NM 00040	
P.O. Box 670 Hobbs	, NM 80240	283
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER B 6	60 FEET FROM THE North LINE AND 1980	Eunice Monument G/SA
	LINE AND	PEET FROM CITTURE TO WOOD
_ East	N 3 TOWNSHIP 21S RANGE 36E	
THE LINE, SECTIO	N TOWNSHIP RANGE	мерм. (
	(1)	
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	3579' GL	Lea
Check A	appropriate Box To Indicate Nature of Notice, Rep	oors or Other Dasa
NOTICE OF IN		
1101102 01 111	12.11.01.10.	SSEQUENT REPORT OF:
	<u></u>	_
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT I	JOB .
Deepen and convert	to injector	
OTHER	TX	
 Describe Proposed or Completed Operator workj SEE RULE 1103. 	erations (Clearly state all pertinent details, and give pertinent date	es, including estimated date of starting any proposed
Bury See Roce 1103.		•
Deepen from 3910' t	o 4060'. Log well. Acidize as necessary	/ Fauin for injection
Tost casing packer	, and tubing to 500 psi for 30 minutes.	Detume to enduction
	, and cubing to 500 psi for 50 minutes.	Return to production
as an injector.		
	• •	
•		•
•		
8. I hereby certify that the information a	bove is true and complete to the best of my knowledge and belief.	
	// /	
15HED T. KI. KI.	Division Drilling Ma	nager 7-10-1986
:=	TITLE:	DATE
	<u> </u>	
ORIGINAL SIGNED BY JER	RY SEXTON	III 4 4 1000
PPROVED BY - DISTRICT : SUPPLY	FOR YITLE	0.176 JUL 1 4 1300