STATE OF NEW MEXICO  ERGY AND MINERALS DEPARTMENT	1 =		
	OIL CONSERVA	TION DIVISION	•
DISTRIBUTION			
SANTA FE			Form C-103 · Revised 10-1-78
SANTA FE, NEW MEXICO 87501			
U.S.G.S.			5a. Indicate Type of Lease
LAND OFFICE		•	State X
OPERATOR	• .	•	5. State Oil & Gas Lease No.
SUNDRY NO	TICES AND REPORTS ON	WELLS  ACK TO A DIFFERENT RESERVOIR.  HOROGRALS.)	
ett			7. Unit Agreement Name
			Eunice Monument South U
			8. Farm or Lease Hame
Chevron U.S.A. Inc.			o. I dim or Lease Hame
P.O. Box 670 Hobbs, i	NM 88240		9. Well No. 358
xation of Well			10. Field and Pool, or Wildcat
UNIT LETTER B 660	PEET FROM THE North	LINE AND	Eunice Monument G/SA
THE East LINE, SECTION 1	5	36E - W	Men.
15. Elevation (Show whether DF, RT, GR, etc.)			
	13. Elevation (Snow whether	3575' GL	Lea (12. County
Check Appro NOTICE OF INTEN	priate Box To Indicate N	ature of Notice, Report or subsequ	Other Data ENT REPORT OF:
PORARILY ASANDON	PLUG AND ABANDON	REMEDIAL WORK C	ALTERING CASING PLUG AND ABANDONMENT
OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	<del>.</del>
Deepen and convert to	injection X	OTHER	
Describe Proposed or Completed Operation work) SEE RULE 1103.	s (Clearly state all pertinent deta	ils, and give pertinent dates, inclu	aing estimated date of starting any proposed

Clean out to TD 0  $\underline{3865}$ . Deepen well from  $\underline{3865}$  to  $\underline{3955}$ . Log well. Add additional Grayburg perforations as logs indicate. Acidize as necessary. Equip for injection. Test casing, packer, and tubing to 500 psi for 30 minutes. Return to production as an injector.

ORIGINAL SIGNED BY JERRY-SEXTON

DISTRICT I SUPERVISOR

TITLE

Staff Drilling Engineer

OATE

OATE

OATE

OATE

OATE

OATE