Office Energy Minorals and Natural Description	Form C-10
Office Energy, Minerals and Natural Resources 1625 N. French Pr., Hobbs, NM 87240	Revised March 25, 19 WELL API NO.
District II OII CONSEDIVATION DIVISION	30-025-04744
811 South First, Artesia, NM 87210  District III  2040 South Pacheco	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505	STATE 😿 FEE 🗌
District IV 2040 South Pacheco, Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name:
PROPOSALS.)  1. Type of Well:  Oil Well	EUNICE MONUMENT SOUTH UNIT
2. Name of Operator	8. Well No.
Chevron U.S.A. Inc.	453
3. Address of Operator	9. Pool name or Wildcat
P.O. Box 1150 Midland, TX 79702  4. Well Location	EUNICE MONUMENT; GRAYBURG-SAN ANDRES
Unit Letter I : 1980 feet from the SOUTH line and	660 feet from the FAST line
Section 21 Township 21S Range 36E	NB 450
10. Elevation (Show whether DR, RKB, RT, GR,	NMPM County LEA etc.)
11. Check Appropriate Box to Indicate Nature of Notic	e, Report, or Other Data
NOTICE OF INTENTION TO:	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK	☐ ALTERING CASING
TEMPORARILY ABANDON	LING OPNS. The PLUG AND
PULL OR ALTER CASING MULTIPLE CASING TEST AN COMPLETION CEMENT JOB	ABANDONMENT
TOZMENT GOB	
)THEB:	
OTHER:  OTHER:  OTHER:  OTHER:	give portinger datas in the form of
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attac or recompilation.  TAGGED CIBP @ 3695' - PPD 25 SX CMT ON TOP; TAGGED @ 3441'. PPD 110 TAGGED @ 1510'. TSTD CSG TO 500#-OK (PER BUDDY HILL). CIRC CMT 372	ch wellbore diagram of proposed completion
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attacor recompilation.  TAGGED CIBP @ 3695' - PPD 25 SX CMT ON TOP; TAGGED @ 3441'. PPD 110	ch wellbore diagram of proposed completion
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attacor recompilation.  TAGGED CIBP @ 3695' - PPD 25 SX CMT ON TOP; TAGGED @ 3441'. PPD 110 TAGGED @ 1510'. TSTD CSG TO 500#-OK (PER BUDDY HILL). CIRC CMT 372 5-1/2". SET MARKER, CLEANED LOCATION.	ch wellbore diagram of proposed completion
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attacor recompilation.  TAGGED CIBP @ 3695' - PPD 25 SX CMT ON TOP; TAGGED @ 3441'. PPD 110 TAGGED @ 1510'. TSTD CSG TO 500#-OK (PER BUDDY HILL). CIRC CMT 372 5-1/2". SET MARKER, CLEANED LOCATION.	ch wellbore diagram of proposed completion
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attacor recompilation.  TAGGED CIBP @ 3695' - PPD 25 SX CMT ON TOP; TAGGED @ 3441'. PPD 110 TAGGED @ 1510'. TSTD CSG TO 500#-OK (PER BUDDY HILL). CIRC CMT 372 5-1/2". SET MARKER, CLEANED LOCATION.	ch wellbore diagram of proposed completion
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attacor recompilation.  TAGGED CIBP @ 3695' - PPD 25 SX CMT ON TOP; TAGGED @ 3441'. PPD 110 TAGGED @ 1510'. TSTD CSG TO 500#-OK (PER BUDDY HILL). CIRC CMT 372 5-1/2". SET MARKER, CLEANED LOCATION.	ch wellbore diagram of proposed completion
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attacor recompilation.  TAGGED CIEP @ 3695' - PPD 25 SX CMT ON TOP; TAGGED @ 3441'. PPD 110 TAGGED @ 1510'. TSTD CSG TO 500#-OK (PER BUDDY HILL). CIRC CMT 372 5-1/2". SET MARKER, CLEANED LOCATION.  P&A'D 9/17/01	Ch wellbore diagram of proposed completion  O SX CMT @ 2450';  O' TO SURF IN
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attacor recompilation.  TAGGED CIBP @ 3695' - PPD 25 SX CMT ON TOP; TAGGED @ 3441'. PPD 110 TAGGED @ 1510'. TSTD CSG TO 500#-OK (PER BUDDY HILL). CIRC CMT 372 5-1/2". SET MARKER, CLEANED LOCATION.	Ch wellbore diagram of proposed completion  O SX CMT @ 2450';  O' TO SURF IN
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attacor recompilation.  TAGGED CIEP @ 3695' - PPD 25 SX CMT ON TOP; TAGGED @ 3441'. PPD 110 TAGGED @ 1510'. TSTD CSG TO 500#-OK (PER BUDDY HILL). CIRC CMT 372 5-1/2". SET MARKER, CLEANED LOCATION.  P&A'D 9/17/01	Ch wellbore diagram of proposed completion  O SX CMT @ 2450';  O' TO SURF IN
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attacor recompilation.  TAGGED CIEP @ 3695' - PPD 25 SX CMT ON TOP; TAGGED @ 3441'. PPD 110 TAGGED @ 1510'. TSTD CSG TO 500#-OK (PER BUDDY HILL). CIRC CMT 372 5-1/2". SET MARKER, CLEANED LOCATION.  P&A'D 9/17/01	ch wellbore diagram of proposed completion  D SK CMT @ 2450';  TO SURF IN  DATE
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attacor recompilation.  TAGGED CIBP @ 3695' - PPD 25 SX CMT ON TOP; TAGGED @ 3441'. PPD 110 TAGGED @ 1510'. TSTD CSG TO 500#-OK (PER BUDDY HILL). CIRC CMT 372 5-1/2". SET MARKER, CLEANED LOCATION.  P&A'D 9/17/01  ereby certify that the information above is true and complete to the best of my knowledge and believe the complete to the best of my knowledge and believe the complete to the complete	ch wellbore diagram of proposed completion  O SX CMT @ 2450';  O' TO SURF IN
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attacor recompilation.  TAGGED CIEP @ 3695' - PPD 25 SX CMT ON TOP; TAGGED @ 3441'. PPD 110 TAGGED @ 1510'. TSTD CSG TO 500#-OK (PER BUDDY HILL). CIRC CMT 372 5-1/2". SET MARKER, CLEANED LOCATION.  PGA'D 9/17/01  ereby certify that the information above is true and complete to the best of my knowledge and belief.  GNATURE J. L. REGULATORY O.A  pe or print name J. K. RIPLEY  his space for State use)	ch wellbore diagram of proposed completion  D SK CMT @ 2450';  TO SURF IN  DATE
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attacor recompilation.  TAGGED CIEP @ 3695' - PPD 25 SX CMT ON TOP; TAGGED @ 3441'. PPD 110 TAGGED @ 1510'. TSTD CSG TO 500#-OK (PER BUDDY HILL). CIRC CMT 372 5-1/2". SET MARKER, CLEANED LOCATION.  PEA'D 9/17/01  ereby certify that the information above is true and complete to the best of my knowledge and belief.  GNATURE J. K. RIPLEY  his space for State use)  PROCED DAY.	ch wellbore diagram of proposed completion  D SX CMT @ 2450';  TO SURF IN  DATE