## NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

## MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

	Indicate Nature of Notice by Ch	ecking Be	elow	
Notice of Intention o Change Plans	Notice of Intention to Temporarily Abandon Well		Notice of Intention to Drill Deeper	
Notice of Intention o Plug Well	Notice of Intention to Plug Back	x	Notice of Intention to Set Liner	
Notice of Intention to Squeeze	Notice of Intention to Acidize		Notice of Intention to Shoot (Nitro)	
JOTICE OF INTENTION O GUN PERFORATE	Notice of Intention (Other)		Notice of Intention (Other)	·
OIL CONSERVATION COMMISSIC SANTA FE, NEW MEXICO	ON <b>Bobbs, New M</b>	lexico	April 27,	1955
Gentlemen:	(2.1200)		(Date)	
Following is a Notice of Intention	to do certain work as described below at	the	Barry Legnard A	
Colf Cil Corporation (Company or Operator)			_	
enter	<b>22</b> , T. <b>21-5</b> , R. <b>36-8</b>			(Onn)
(40-acre subdivision)			•	
(FOL	FULL DETAILS OF PROPOSED LOW INSTRUCTIONS IN THE RUL	ES AND	REGULATIONS)	
In an effort to shut off  l. Pull reds and  2. Run radioacti 3. Plug back with	water the following is pro- tubing. Vity survey and caliper sur in hydromite to approximate the formation with 2500 gal	es and :	REGULATIONS)	
In an effort to shut off  l. Pull reds and  2. Run radioacti  3. Plug back with  4. Treatpapen he	tubing.  Veter the following is provided the subing.  Vity Survey and caliper auch hydromite to approximate the formation with 2500 galice.	es and :  opesed:  rvey.  ly 3876  lons 15	REGULATIONS)	
In an effort to shut off  1. Pull reds and 2. Run radioacti 3. Plug back with 4. Treatespen he 5. Swab and test	water the following is protein tubing.  Tubing.	es and preseductively. 19 3876 lone 15	Placed on survey.  NE acid.	
In an effort to shut off  1. Pull reds and 2. Run radioacti 3. Plug back with 4. Treatespen he 5. Swab and test	tubing.  Veter the following is provided the subing.  Vity Survey and caliper auch hydromite to approximate the formation with 2500 galice.	es and presed:  rvey. ly 3876 lone 15	based on survey.  NE acid.  Company or Operator	to:

Address Box 2167, Hebbs, N. M.