

RECEIVED		
SECTION		

NEW MEXICO OIL CONSERVATION COMMISSION

ILLEGIBLE

in C
 02 a
 02 b
 02 c
 02 d
 02 e
 02 f
 02 g
 02 h
 02 i
 02 j
 02 k
 02 l
 02 m
 02 n
 02 o
 02 p
 02 q
 02 r
 02 s
 02 t
 02 u
 02 v
 02 w
 02 x
 02 y
 02 z

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR
 USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

GAS
 WELL ☐

OTHER-

7. Agreement Name

8. Farm or Lease Name

New Mexico "C" State

9. Well No.

10. Name of Operator

Address of Operator

P. O. Box 2100, Hobbs, New Mexico 88240

11. Field and Subunit

12. County

13. Elevation (Show whether DF, RT, GR, etc.)

3545 GR

14. County

Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORATE ☒
 TEMPORARY ABANDON ☐
 PULL OUT Casing ☐

PLUG AND ABANDON ☐
 CHANGE PLANS ☐

REMEDIAL WORK ☐
 COMMENCE DRILLING OPNS. ☐
 CASING TEST AND CEMENT JOBS ☐

ALTERING ☐
 PLUG AND ABANDON ☐

OTHER

15. Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of completion.)

From oil well in the Queen to gas well in Yates. Run bridge plug on 2 1/2 inch tubing at 3270'. Dump one sack of quick setting cement on top. Perforate 5-1/2 inch casing at 3094' per foot and pip log from 3094 to 3122' and 3152 to 3176'. Run tubing with packer, spot acid around perforations from 3094 to 3176', then set packer at 3060' to isolate perfs from 3094 to 3122' down tubing-casing annulus with 1500 gallons of acid. Isolate perfs from 3152 to 3176' down 2-inch tubing with 1500 gallons of acid. Set packer and set at 3060', then swab well in and place on gas production.

I certify that the information above is true and complete to the best of my knowledge and belief.

TITLE Dist. Services Supvr.

DATE

John W. Runyan

TITLE

DATE

NOV 18 1970

APPROVAL, IF ANY:

RECEIVED

10 1970

OIL CONSERVATION COMM.
HOBBS, N. M.