

COPIES RECEIVED		
DISTRIBUTION		
SATISFACTION		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B-935	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator EXXON CORPORATION		8. Farm or Lease Name NEW MEXICO "G" STATE
3. Address of Operator P.O. Box 1600, MIDLAND, TEXAS 79701		9. Well No. 12
4. Location of Well UNIT LETTER K 1980 FEET FROM THE SOUTH LINE AND 1980 FEET FROM THE WEST LINE, SECTION 26 TOWNSHIP 21-S RANGE 36-E N.M.P.M.		10. Field and Pool, or Wildcat EUMONT VATES SEVEN RIVERS
15. Elevation (Show whether DF, RT, GR, etc.) EST 3543' D.F.		12. County LEA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-25-76, MIRU CSG. PULLERS. PULL RODS & TBG. OUT OF HOLE. RAN TBG. IN HOLE, SPOT 20 SX CUT PLUG @ 3835'. WOC. TAGGED PLUG AT 3625'. FOUND HOLE; W/BR MUD SPOT 15 SX CUT PLUG @ 2800'. WOC. TAGGED PLUG AT 2600'. SPOT 15 SX CUT PLUG @ 1500'. TAGGED PLUG @ 1315', SPOT 15 SX CUT PLUG @ 350'. TAGGED PLUG @ 180', SPOT 10 SX CUT PLUG @ SURFACE. REMOVE WELLHEAD, INSTALL DRY HOLE MARKER. FRW 6-25-76

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Amy Lat TITLE SECTION HEAD DATE 7-1-76

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: