(June 1990)	UNITED STATES		
	DEPARTMENT OF THE IN		FORM APPROVED Budget Bureau No. 1004-0135
	BUREAU OF LAND MANAG	EMENT P 1280	Expires March 31 1993
			5. Lease Designation and Senal No.
	SUNDRY NOTICES AND REPOR	Hobre NM 88941	NM 90162
Do not use this form for propos	sals to drill or to deepen or reentry to		6. If Indian, Allottee or Tribe Name
Use "APPLICATION	FOR PERMIT - " for such proposals		
	SUBMIT IN TRIPLICAT	E	7. If Unit or CA, Agreement Designation
Type of Well X OII Gas II			
Well Well Oth	NJECTION		
Name of Operator			Lockhart B 28
CONOCO, INC. Address and Telephone No			Well #2
Address and Telephone No			9 API Well No
10 Desta Dr., Suite ЮОW, Midia	30 025 048k0		
Construction of the rest of th			10 Field and Pool or Exploratory Area Eumont Yates 7 Rvrs Queen
Surface: 1980 FNL & 660 FWL Location: Sec 28, T2IS, R36E			11. County or Parish State
TD: Same			
			Lea County, NM
	E BOX(s) TO INDICATE NATUR	E OF NOTICE, REPORT, OR	OTHER DATA
	ON	TYPE OF ACTION	
Notice of Intent		Abandonment	Change of Plans
X Subsequent D		Recompletion	New Construction
X Subsequent Report		Plugging Back	Non-Routine Fracturing
 Final Abandonment N		Casing Repair	Water Shut-Off
		Altering Casing	Conversion to Injection
		X Other, Clean out, replace tubing	Dispose Water
Describe Promeet or Completed re-	1		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Lon form)
Describe Proposed or Completed Oper directionally drilled, give subsurface	rations (Clearly state all pertinent details and gr e locations and measured and true vertical deptr		Completion or Recompletion Report and Log form.)
5-29-97: Move in reverse to 3032' St. 5-30-97: Circulate down 6-2-97: Ran in hole with t	e unit, stuck pump, found bad join to 3796', circulate clean. tubing to 3715', SI	ve pertinent dates, including estimated date is for all markers and zones pertinent to this ts in tubing, ran in hole with tub	Completion or Recompletion Report and Log form.) of starting any proposed work. If well is work.)* ing
5-29-97: Move in reverse to 3032' SI. 5-30-97: Circulate down 6-2-97: Ran in hole with t	e unit, stuck pump, found bad join to 3796', circulate clean	ve pertinent dates, including estimated date is for all markers and zones pertinent to this ts in tubing, ran in hole with tub	Completion or Recompletion Report and Log form.) of starting any proposed work. If well is work.)*
5-29-97: Move in reverse to 3032' St. 5-30-97: Circulate down 6-2-97: Ran in hole with t	e unit, stuck pump, found bad join to 3796', circulate clean. tubing to 3715', SI	ve pertinent dates, including estimated date is for all markers and zones pertinent to this ts in tubing, ran in hole with tub	Completion or Recompletion Report and Log form.) of starting any proposed work. If well is work.)* ing
5-29-97: Move in reverse to 3032' St. 5-30-97: Circulate down 6-2-97: Ran in hole with t	e unit, stuck pump, found bad join to 3796', circulate clean. tubing to 3715', SI	ve pertinent dates, including estimated date is for all markers and zones pertinent to this ts in tubing, ran in hole with tub	Completion or Recompletion Report and Log form.) of starting any proposed work. If well is work.)* ing
5-29-97: Move in reverse to 3032' St. 5-30-97: Circulate down 6-2-97: Ran in hole with t	e unit, stuck pump, found bad join to 3796', circulate clean. tubing to 3715', SI	ve pertinent dates, including estimated date is for all markers and zones pertinent to this ts in tubing, ran in hole with tub	Completion or Recompletion Report and Log form.) of starting any proposed work. If well is work.)* ing
5-29-97: Move in reverse to 3032' St. 5-30-97: Circulate down 6-2-97: Ran in hole with t	e unit, stuck pump, found bad join to 3796', circulate clean. tubing to 3715', SI	ve pertinent dates, including estimated date is for all markers and zones pertinent to this ts in tubing, ran in hole with tub	Completion or Recompletion Report and Log form.) of starting any proposed work. If well is work.)* ing
5-29-97: Move in reverse to 3032' St. 5-30-97: Circulate down 6-2-97: Ran in hole with t 6-3-97: Ran 2 3/8" tubing	e unit, stuck pump, found bad join to 3796', circulate clean. tubing to 37l5'. SI. t bottom of SN @ 3664'. Retrieva	ve pertinent dates, including estimated date is for all markers and zones pertinent to this ts in tubing, ran in hole with tub	Completion or Recompletion Report and Log form.) of starting any proposed work. If well is work.)* ing
5-29-97: Move in reverse to 3032' St. 5-30-97: Circulate down 6-2-97: Ran in hole with t 6-3-97: Ran 2 3/8" tubing	e unit, stuck pump, found bad join to 3796', circulate clean. tubing to 3715', SI	ve pertinent dates, including estimated date is for all markers and zones pertinent to this ts in tubing, ran in hole with tub	Completion or Recompletion Report and Log form.) of starting any proposed work. If well is work.)* ing C C C C C C C C C C C C C
5-29-97: Move in reverse to 3032' St. 5-30-97: Circulate down 6-2-97: Ran in hole with t 6-3-97: Ran 2 3/8" tubing	e unit, stuck pump, found bad join to 3796', circulate clean. tubing to 37I5'. SI. bottom of SN @ 3664'. Retrieva	ve pertinent dates, including estimated date is for all markers and zones pertinent to this ts in tubing, ran in hole with tub ble bridge plug set @ 3800'.	Completion or Recompletion Report and Log form.) of starting any proposed work. If well is work.)*
5-29-97: Move in reverse to 3032' SI. 5-30-97: Circulate down 6-2-97: Ran in hole with t 6-3-97: Ran 2 3/8" tubing hereby certify that the foregoing is trice Signed.	e unit, stuck pump, found bad join to 3796', circulate clean. tubing to 37I5'. SI. bottom of SN @ 3664'. Retrieva	ve pertinent dates, including estimated date is for all markers and zones pertinent to this ts in tubing, ran in hole with tub ble bridge plug set @ 3800'.	Completion or Recompletion Report and Log form.) of starting any proposed work. If well is work.)* ing C C C C C C C C C C C C C
5-29-97: Move in reverse to 3032' SI. 5-30-97: Circulate down to 6-2-97: Ran in hole with to 6-3-97: Ran 2 3/8" tubing	e unit, stuck pump, found bad join to 3796', circulate clean. tubing to 3715'. SI. bottom of SN @ 3664'. Retrieva	ve pertinent dates, including estimated date is for all markers and zones pertinent to this ts in tubing, ran in hole with tub ble bridge plug set @ 3800'.	Completion or Recompletion Report and Log form.) of starting any proposed work. If well is work.)* ing C C C C C C C C C C C C C C C C C C
5-29-97: Move in reverse to 3032' SI. 5-30-97: Circulate down 6-2-97: Ran in hole with t 6-3-97: Ran 2 3/8" tubing hereby certify that the foregoing is trife Signed Much Much the Signed Much Much the his space for Federal or State office us	e unit, stuck pump, found bad join to 3796', circulate clean. tubing to 37I5'. SI. bottom of SN @ 3664'. Retrieva	ve pertinent dates, including estimated date is for all markers and zones pertinent to this ts in tubing, ran in hole with tub ble bridge plug set @ 3800'.	Completion or Recompletion Report and Log form.) of starting any proposed work. If well is work.)* ing C C C C C C C C C C C C C C C C C C
5-29-97: Move in reverse to 3032' SI. 5-30-97: Circulate down to 6-2-97: Ran in hole with to 6-3-97: Ran 2 3/8" tubing hereby certify that the foregoing is trife Signed With With the foregoing is trife signed Wi	and correct and correct Trite Trite	ve pertinent dates, including estimated date is for all markers and zones pertinent to this ts in tubing, ran in hole with tub ble bridge plug set @ 3800'.	Completion or Recompletion Report and Log form.) of starting any proposed work. If well is work.)* ing Completion of the second seco