

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
<i>B-935</i>

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <i>Humble Oil & Refg Co.</i>	8. Farm or Lease Name <i>Unit 2</i> <i>New Mexico B State</i>
3. Address of Operator <i>Box 1600 - Midland, Texas 79701</i>	9. Well No. <i>3</i>
4. Location of Well UNIT LETTER <i>J</i> <i>1980</i> FEET FROM THE <i>E</i> LINE AND <i>1980</i> FEET FROM THE <i>S</i> LINE, SECTION <i>29</i> TOWNSHIP <i>21-S</i> RANGE <i>36-E</i> NMPM.	10. Field and Pool, or Wildcat <i>Eumant Oil</i>
15. Elevation (Show whether DF, RT, GR, etc.) <i>3631 DF</i>	12. County <i>Lea</i>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input checked="" type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Permission is requested to plug and abandon well as follows:

1. Set cmt plug from 3700-3880' PBD w/ 50 sax cmt.
2. Set cmt plug from 50' to surface w/ 10 sax cmt.
3. Install dry hole marker and clean location.
4. Mud laden fluid between plugs.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <i>[Signature]</i>	TITLE <i>Unit Head</i>	DATE <i>1/17/70</i>
APPROVED BY <i>[Signature]</i>	TITLE <i>SUPERVISOR DISTRICT 9</i>	DATE <i>JAN 22 1970</i>
CONDITIONS OF APPROVAL, IF ANY:		