Form 9-381 a (Feb. 1951)	Loson and start	Budget Bureau No. 42-R358.4. Form Approved.	
	DEPARTMENT OF THE INTERIOR	Lease No. LC 032099 b Lease Unit	
x	GEOLOGICAL SURVEY		

SUNDRY NOTICES AND REPORTS ON WELLS

Vell No. SE/4 (4	SW/4 Sec. and Sec. 1	iec. 31	660 ft. from 21-S (Twp.)	n {S S 36- B (Range)	1980 _{t. from}	$ \begin{bmatrix} \mathbf{E}^{\mathbf{F}} \\ \mathbf{W} \end{bmatrix} $ line of sec.	
Vell No.	2 SW/4 1	is located .	660 ft. fron 21-S	$n_{} \begin{cases} \mathbf{N} \\ \mathbf{S} \end{cases}$ line and .	1980 _{t. from}		
	2	is located .	660 ft. fron				
ar (3 (4 4).)							, 17
(INDICATE ABOVE BY CHECK MARK		K NATURE OF REPORT, NOTICE, OR OTHER DATA)			, 19_ 6		
				DECKEY & FUN R/A Log			X.
NOTICE OF INTENTION TO CHANGE PLANS NOTICE OF INTENTION TO TEST WATER SHUT-OFF NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL NOTICE OF INTENTION TO SHOOT OR ACIDIZE NOTICE OF INTENTION TO PULL OR ALTER CASING							
			SUBSEQUENT REPORT OF ALTERING CASING				
						1	
				I SUBSEQUENT S	FRONT OF CUCOTING		1

The elevation of the derrick floor above sea level is _____ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Recovered 5-1/2' corroded and plugged 2" tbg in two pieces. Washed over 2" tbg to top of packer hanger at 3559. Ran socket which parted while jarring on packer hanger, leaving 18" of 4-11/16" OD socket on top of packer hanger. Top of 2" tbg at 3440'. Failed to recover packer. Workover unsuccessful. Workover started 1-27-61, completed 1-31-61. Well TSD.

	that this plan of work must receive approval in writing Continental 011 Company	*		rations may be commenced.
Company		, 		
Address	Box 68			
	Runice, New Mexico	Bv		
USGS-4 NMOCC-2 WAM File Pan Am-Hbs-3 Atl-Resy-2			District	Superintendent
	louston, Midland-1 each			

GPO 914974