

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1900, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-04865 ✓
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B1481
7. Lease Name or Unit Agreement Name	
State D	
8. Well No.	3
9. Pool name or Wildcat	Eumont Yates 7 Rvrs On gas
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	
3615'	

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER
2. Name of Operator	OXY USA Inc.
3. Address of Operator	P.O. Box 50250 Midland, TX. 79710

4. Well Location	Unit Letter A : 660 Feet From The North Line and 660 Feet From The East Line
Section 32	Township 21S Range 36E NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	
3615'	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	
OTHER: Add add'l perfs <input checked="" type="checkbox"/>	
SUBSEQUENT REPORT OF:	
REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD - 3900' PBTD - 3765' Perfs - 3243'-3610'

(See other side)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David Stewart TITLE Prod. Acct. DATE 1/28/93  
TYPE OR PRINT NAME David Stewart TELEPHONE NO. 9156855717

(This space for State Use) ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE FEB 01 1993

CONDITIONS OF APPROVAL, IF ANY:

**WORKOVER PROCEDURES  
STATE D #3**

- 1) MIRU rig. Kill well w/2% KCl water mixed w/0.4% SSO-21 (Halliburton) to control clay swelling. ND tree and NU BOP's.
- 2) POOH and LD 2-3/8" tubing. Note condition of tubing and notify Midland if new tubing will be required.
- 3) PU 6-1/4" bit and 7" csg scraper and TIH on 2-7/8" work string. TIH and wash to PBTD @ 3765'. CHC. POOH and LD bit and scraper.
- 4) RU WL. NU 3000# lubricator. Run 2000', or minimum, GR/Neutron log from PBTD. POOH and LD logging tools. PU 4" csg gun and perforate the following intervals (2 spf): 3382-87', 3506-14', 3519-23', 3528-30', 3551-60', 3674-90', 3710-20', 3724-42'. These intervals are estimated and may change depending on how the GR/Neutron looks. A geologist should be on location to pick perfs. POOH and RD WL.
  - a) Maximum anticipated BHP pressure is 1000 psi. Fluid level should not be below  $\pm 1200'$  prior to perforating.
- 5) PU 7" PPI pkr and TIH. Set pkr below perfs at  $\pm 3750'$ . Test pkr to 1500 psi. Drop RFC valve and function test. Break down perfs w/25 gals per foot of 7.5% NEFE acid mixed w/surfactant. Use a total of 5000 gals of acid. RD service company. POOH and LD PPI pkr.
- 6) RIH w/production tbg. Set EOT at  $\pm 3150'$  (100' above top perfs). ND BOP's and NU tree. RU swab and swab back load. Put well on test. Report rates and pressure until stabilized.
  - a) Run a WL re-entry guide on end of tubing.

RECEIVED

FEB 01 1993

COPIES