Submit 3 Copies to Appropriate

## Er

Form C-103 Revisied 1-1-89

District Office

**OIL CONSERVATION DIVISION** 

		State	of Nev	v Mexico	
nergy,	Minerals	and i	Vatural	Resource	s Department

P.O. Box 2088	
DISTRICT 1 Santa Fe, New Mexico 87504-2088	
P.O. Box 1980, Hobbs, NM 88240	
DISTRICT II	API NO. (assigned by OCD on New Wells)
P.O. Drawer Dd, Artesia, NM 88210	30-025-04890
DISTRICT III 1000 Rio Brezoe Rd., Aztec, Nm 87410	5. Indicate Type of Lease STATE X FEE
1	
	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	N/A
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lesse Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"	ARNOTT RAMSAY (NCT-D)
(FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well:	
OIL GAS WELL X OTHER	
2. Name of Operator	8. Well No.
CHEVRON U.S.A. INC.	9
3. Address of Operator	9. Pool name or Wildcat
P.O. BOX 1150 MIDLAND, TX 79702 ATTN: WENDI KINGSTON	EUNICE SOUTH
4. Well Location Unit Letter L : 1980 Feet From The SOUTH Line and	660 Feet From The WEST Line
	36E NMPM LEA county
10. Elevation(Show whether DF, RKB, RT, GR, etc.)	
3549' GL	
11 Check Appropriate Box to Indecate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REF	,
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTER CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS.	PLUG AND ABAN.
PULL OR ALTER CASING CASING TEST AND CMT JOB	
PULL OR ALTER CASING OTHER: CASING TEST AND CMT JOB OTHER: RECOMP IN YATES	
PULL OR ALTER CASING CASING TEST AND CMT JOB	
PULL OR ALTER CASING OTHER: CASING TEST AND CMT JOB RECOMP IN YATES  12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including esticated date of starting any proposed work) SEE RULE 1103.	/SR/QN X
CASING TEST AND CMT JOB OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including esticated date of starting any proposed work) SEE RULE 1103.  WORK STARTED 10/04/94. MIRU PU, ND WH, NU BOP. SET CIBP @3730'.	/SR/QN X
OTHER:  CASING TEST AND CMT JOB OTHER:  CASING TEST AND CMT JOB OTHER:  RECOMP IN YATES  12. Describe Proposed or Completed Operational Clearly state all pertinent details, and give pertinent dates, including esticated date of starting any proposed work) SEE RULE 1103.  WORK STARTED 10/04/94. MIRU PU, ND WH, NU BOP. SET CIBP @3730'. 3245'-3645', CAP CIBP W/20' CMT. ACDZ PERFS W/150 GALS HCL. FRACE	PERF F/
CASING TEST AND CMT JOB OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including esticated date of starting any proposed work) SEE RULE 1103.  WORK STARTED 10/04/94. MIRU PU, ND WH, NU BOP. SET CIBP @3730'. 3245'-3645', CAP CIBP W/20' CMT. ACDZ PERFS W/150 GALS HCL. FRAC W/678 BBLS 45# LINEAR GEL & 199,500 LBS 12/20 BRADY SD. FLUSH. FL	PERF F/
OTHER:  CASING TEST AND CMT JOB OTHER:  CASING TEST AND CMT JOB OTHER:  RECOMP IN YATES  12. Describe Proposed or Completed Operational Clearly state all pertinent details, and give pertinent dates, including esticated date of starting any proposed work) SEE RULE 1103.  WORK STARTED 10/04/94. MIRU PU, ND WH, NU BOP. SET CIBP @3730'. 3245'-3645', CAP CIBP W/20' CMT. ACDZ PERFS W/150 GALS HCL. FRACE	PERF F/
CASING TEST AND CMT JOB OTHER:  12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including esticated date of starting any proposed work) SEE RULE 1103.  WORK STARTED 10/04/94. MIRU PU, ND WH, NU BOP. SET CIBP @3730'. 3245'-3645', CAP CIBP W/20' CMT. ACDZ PERFS W/150 GALS HCL. FRACE W/678 BBLS 45# LINEAR GEL & 199,500 LBS 12/20 BRADY SD. FLUSH. FL SWAB. CLEAN OUT F/3640'-3677'. SWAB. ND BOP, NU WH. TURN WELL OVER TO PRODUCTION 10/12/94.	PERF F/ PERFS OW BACK.
CASING TEST AND CMT JOB OTHER:  12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including esticated date of starting any proposed work) SEE RULE 1103.  WORK STARTED 10/04/94. MIRU PU, ND WH, NU BOP. SET CIBP @3730'. 3245'-3645', CAP CIBP W/20' CMT. ACDZ PERFS W/150 GALS HCL. FRACE W/678 BBLS 45# LINEAR GEL & 199,500 LBS 12/20 BRADY SD. FLUSH. FL SWAB. CLEAN OUT F/3640'-3677'. SWAB. ND BOP, NU WH. TURN WELL OVER TO PRODUCTION 10/12/94.	PERF F/ PERFS OW BACK.
CASING TEST AND CMT JOB OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including esticated date of starting any proposed work) SEE RULE 1103.  WORK STARTED 10/04/94. MIRU PU, ND WH, NU BOP. SET CIBP @3730'. 3245'-3645', CAP CIBP W/20' CMT. ACDZ PERFS W/150 GALS HCL. FRACE W/678 BBLS 45# LINEAR GEL & 199,500 LBS 12/20 BRADY SD. FLUSH. FL SWAB. CLEAN OUT F/3640'-3677'. SWAB. ND BOP, NU WH.	PERF F/ PERFS OW BACK.
CASING TEST AND CMT JOB OTHER:  12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including esticated date of starting any proposed work) SEE RULE 1103.  WORK STARTED 10/04/94. MIRU PU, ND WH, NU BOP. SET CIBP @3730'. 3245'-3645', CAP CIBP W/20' CMT. ACDZ PERFS W/150 GALS HCL. FRACE W/678 BBLS 45# LINEAR GEL & 199,500 LBS 12/20 BRADY SD. FLUSH. FL SWAB. CLEAN OUT F/3640'-3677'. SWAB. ND BOP, NU WH. TURN WELL OVER TO PRODUCTION 10/12/94.	PERF F/ PERFS OW BACK.
CASING TEST AND CMT JOB OTHER:  12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including esticated date of starting any proposed work) SEE RULE 1103.  WORK STARTED 10/04/94. MIRU PU, ND WH, NU BOP. SET CIBP @3730'. 3245'-3645', CAP CIBP W/20' CMT. ACDZ PERFS W/150 GALS HCL. FRACE W/678 BBLS 45# LINEAR GEL & 199,500 LBS 12/20 BRADY SD. FLUSH. FL SWAB. CLEAN OUT F/3640'-3677'. SWAB. ND BOP, NU WH. TURN WELL OVER TO PRODUCTION 10/12/94.	PERF F/ PERFS OW BACK.
CASING TEST AND CMT JOB OTHER:  12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including esticated date of starting any proposed work) SEE RULE 1103.  WORK STARTED 10/04/94. MIRU PU, ND WH, NU BOP. SET CIBP @3730'. 3245'-3645', CAP CIBP W/20' CMT. ACDZ PERFS W/150 GALS HCL. FRACE W/678 BBLS 45# LINEAR GEL & 199,500 LBS 12/20 BRADY SD. FLUSH. FL SWAB. CLEAN OUT F/3640'-3677'. SWAB. ND BOP, NU WH. TURN WELL OVER TO PRODUCTION 10/12/94.	PERF F/ PERFS OW BACK.
CASING TEST AND CMT JOB OTHER:  12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including esticated date of starting any proposed work) SEE RULE 1103.  WORK STARTED 10/04/94. MIRU PU, ND WH, NU BOP. SET CIBP @3730'. 3245'-3645', CAP CIBP W/20' CMT. ACDZ PERFS W/150 GALS HCL. FRACE W/678 BBLS 45# LINEAR GEL & 199,500 LBS 12/20 BRADY SD. FLUSH. FL SWAB. CLEAN OUT F/3640'-3677'. SWAB. ND BOP, NU WH. TURN WELL OVER TO PRODUCTION 10/12/94.	PERF F/ PERFS OW BACK.
CASING TEST AND CMT JOB OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent detas, including esticated date of starting any proposed work) SEE RULE 1103.  WORK STARTED 10/04/94. MIRU PU, ND WH, NU BOP. SET CIBP @3730'. 3245'-3645', CAP CIBP W/20' CMT. ACDZ PERFS W/150 GALS HCL. FRAC W/678 BBLS 45# LINEAR GEL & 199,500 LBS 12/20 BRADY SD. FLUSH. FL SWAB. CLEAN OUT F/3640'-3677'. SWAB. ND BOP, NU WH. TURN WELL OVER TO PRODUCTION 10/12/94.	PERF F/ PERFS OW BACK.
CASING TEST AND CMT JOB OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including esticated date of starting any proposed work) SEE RULE 1103.  WORK STARTED 10/04/94. MIRU PU, ND WH, NU BOP. SET CIBP @3730'. 3245'-3645', CAP CIBP W/20' CMT. ACDZ PERFS W/150 GALS HCL. FRAC W/678 BBLS 45# LINEAR GEL & 199,500 LBS 12/20 BRADY SD. FLUSH. FL SWAB. CLEAN OUT F/3640'-3677'. SWAB. ND BOP, NU WH. TURN WELL OVER TO PRODUCTION 10/12/94.	PERF F/ PERFS OW BACK.
CASING TEST AND CMT JOB OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent detas, including esticated date of starting any proposed work) SEE RULE 1103.  WORK STARTED 10/04/94. MIRU PU, ND WH, NU BOP. SET CIBP @3730'. 3245'-3645', CAP CIBP W/20' CMT. ACDZ PERFS W/150 GALS HCL. FRAC W/678 BBLS 45# LINEAR GEL & 199,500 LBS 12/20 BRADY SD. FLUSH. FL SWAB. CLEAN OUT F/3640'-3677'. SWAB. ND BOP, NU WH. TURN WELL OVER TO PRODUCTION 10/12/94.	PERF F/ PERFS OW BACK.
CASING TEST AND CMT JOB OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including esticated date of starting any proposed work) SEE RULE 1103.  WORK STARTED 10/04/94. MIRU PU, ND WH, NU BOP. SET CIBP @3730'. 3245'-3645', CAP CIBP W/20' CMT. ACDZ PERFS W/150 GALS HCL. FRAC W/678 BBLS 45# LINEAR GEL & 199,500 LBS 12/20 BRADY SD. FLUSH. FL SWAB. CLEAN OUT F/3640'-3677'. SWAB. ND BOP, NU WH. TURN WELL OVER TO PRODUCTION 10/12/94.	PERF F/ PERFS OW BACK.
CASING TEST AND CMT JOB OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including esticated date of starting any proposed work) SEE RULE 1103.  WORK STARTED 10/04/94. MIRU PU, ND WH, NU BOP. SET CIBP @3730'. 3245'-3645', CAP CIBP W/20' CMT. ACDZ PERFS W/150 GALS HCL. FRAC W/678 BBLS 45# LINEAR GEL & 199,500 LBS 12/20 BRADY SD. FLUSH. FL SWAB. CLEAN OUT F/3640'-3677'. SWAB. ND BOP, NU WH. TURN WELL OVER TO PRODUCTION 10/12/94.  I hereby certify that be instructed by the second starting and baller. SIGNITURE  WENDI KINGSTON  TYPE OR PRINT MAME  WENDI KINGSTON	PERF F/ PERFS OW BACK.  DATE: 11/2/94
CASING TEST AND CMT JOB OTHER: RECOMP IN YATES  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent details, including esticated data of starting any proposed work) SEE RULE 1103.  WORK STARTED 10/04/94. MIRU PU, ND WH, NU BOP. SET CIBP @3730'. 3245'-3645', CAP CIBP W/20' CMT. ACDZ PERFS W/150 GALS HCL. FRACE W/678 BBLS 45 # LINEAR GEL & 199,500 LBS 12/20 BRADY SD. FLUSH. FL SWAB. CLEAN OUT F/3640'-3677'. SWAB. ND BOP, NU WH.  TURN WELL OVER TO PRODUCTION 10/12/94.  I hereby certify that the left introduce about the base confidence to the base of the starting and ballet.  TITLE TECH. ASSISTANT  TYPE OR PRINT MARKE  WENDI KINGSTON	/SR/QN   X   PERF F/ PERFS OW BACK.  DATE: 11/2/94  TELEPHONE NO. (915)687-7826
CASING TEST AND CMT JOB OTHER:  12. Describe Proposed or Completed Operations (Clearly state all partinent details, and give pertinent dates, including esticated date of starting any proposed work) SEE RULE 1103.  WORK STARTED 10/04/94. MIRU PU, ND WH, NU BOP. SET CIBP @3730'. 3245'-3645', CAP CIBP W/20' CMT. ACDZ PERFS W/150 GALS HCL. FRAC W/678 BBLS 45# LINEAR GEL & 199,500 LBS 12/20 BRADY SD. FLUSH. FL SWAB. CLEAN OUT F/3640'-3677'. SWAB. ND BOP, NU WH. TURN WELL OVER TO PRODUCTION 10/12/94.  I hereby certify that the information about the transfer of the starting and ballet.  TITLE TECH. ASSISTANT  TYPE OR PRINT MAME  WENDI KINGSTON	PERF F/ PERFS OW BACK.  DATE: 11/2/94

1.1

24 5 2 ... in 1/2) do