Submit 3 Copies to Appropriate

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revisied 1-1-89

District Office

P.O. Box 2088

-		m	~~	
	IST	R	Li	•

P.O. Box 1980, Hobbe, NM 88240

DISTRICT II

P.O. Drawer Dd, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, Nm 87410

riioi B	At Intitionals and Maraiar Mesonices Debartment
OIL	CONSERVATION DIVISION

Santa Fe, New Mexico 87504-2088 API NO. (assigned by OCD on New Wells) 30-025-04937 5. Indicate Type of Lease STATE FEE

6. State Oil & Gas Lease No. N/A SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG B 7. Lesse Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" HARRY LEONARD (NCT-C) (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: OIL GAS X WELL WELL OTHER 2. Name of Operator 8. Well No. CHEVRON U.S.A. INC. 10 3. Address of Operator 9. Pool name or Wildcat P.O. BOX 1150 MIDLAND, TX 79702 ATTN: P.R. MATTHEWS BLINEBRY 4. Well Location Unit Letter 760 Feet From Th SOUTH 2080 Feet From The WEST 36 Section 218 36E Township Range NMPM LEA County 10. Elevation(Show whether DF, RKB, RT, GR, etc.) 3514 GE 11 Check Appropriate Box to Indecate Nature of Notice, Report, or Other Data

			· post, or other sale			
NOTICE OF	FINTENTION TO:		SUBSEQUE	NT REPORT OF	€:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	X	REMEDIAL WORK		ALTER CASING	
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRILLING OPNS.		PLUG AND ABAN.	•
PULL OR ALTER CASING		_	CASING TEST AND CMT JOB	П		
OTHER:			OTHER:			

12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including esticated date of starting any proposed work) SEE RULE 1103.

## IT IS PROPOSED TO:

SPOT 35' CMT ON TOP OF CICR AT 5480'. SPOT 240' CMT. AT 5287-5047'(GLORIETA) SHOOT HOLES AT 3956', SET CICR AT 3300' PUMP 350 SX. CMT INTO CICR AND 35' CMT ON TOP. PLUG WILL COVER QUEEN AND GRAYBURG.

SPOT 200' AT 2820-2580, PLUG WILL COVER YATES AND 7-RIVERS.

SHOOT HOLES AT 1300', SET CICR AT 1050' AND SQZ WITH 150 SX LEAVE 35' CMT ON TOP.

PLUG WILL COVER RUSTLER AND TOP OF SALT.

SHOOT HOLES AT 370' AND PUMP 240SXS CMT INTO HOLES FILLING 5.5" CSG TO TOP. CUT OFF WELLHEAD AND INSTALL P & A MARKER.

CHANGE STATUS TO P & A.

auto a luggeaco per la companya de l Companya de la companya de la compa
STANT DATE: 5/7/92
TELEPHONE NO (915)687-7812
MAY 11'92