

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-06362
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Chevron USA, Inc.		6. State Oil & Gas Lease No.
3. Address of Operator 15 Smith Rd. Midland, Tx 79705		7. Lease Name or Unit Agreement Name: Harry Leonard NCT-F
4. Well Location Unit Letter <u>O</u> : <u>660</u> feet from the <u>south</u> line and <u>1980</u> feet from the <u>east</u> line Section <u>2</u> Township <u>21-S</u> Range <u>37-E</u> NMPM County <u>Lea</u>		8. Well No. 2
10. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. Pool name or Wildcat Brunson Ellenburger

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐


SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Set 7" CIBP @ 7700 spot 30sx plug 7700-7600(Brunson) Tag @ 7537
2. Displace hole w/MLF, 9.5# Brine w/25# Gel P/BBL.
3. Spot 40sx plug fr/6400-6200(Drinkard)
4. Spot 40sx plug fr/3800-3600(Queen)
5. Perf 4 holes @ 3075 sqz w/110sx fr/3025-2700(9 5/8 shoe, B-salt) Tag @ 2667
6. Perf 4 holes @ 1400 sqz w/80sx fr/1400-1000(B-salt) Tag @ 1015
7. Perf 4 holes @ 310 circ cmt fr/310 to surf w/160sx (13 3/8 shoe) Tag @ surf
8. Install dry hole marker 10-23-02

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jimmy Bagley TITLE MANAGER/SUNSET DATE 10/23/02

Type or print name Jimmy BAGLEY Telephone No. 915 5208756
(This space for State use)

APPROVED BY Harry W. Wink TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER **FEB 1 0 2003**

Conditions of approval, Harry W. Wink
OC FIELD REPRESENTATIVE II/STAFF MANAGER

GW