Office

State of New Mexico Energy, Minerals and Natural Resouces

DISTRICT I	23.			FORM C-103
1625 N. French Dr., Hobbs, NM	38240		Re	evised March 25, 1999
DISTRICT II	OIL CONSERVATION	NDIVISION	WELL API NO.	,
811 South First, Artesia, NM 882	1000 5 1 5 7		30-025-06360	
			5. Indicate Type of Lease	
DISTRICT III Santa Fe, NM 87505		1303	STATE	FEE
1000 Rio Brazos Rd., Aztec, NM	6/410		6. State Oil & Gas Lease No.	
DISTRICT IV	P. Micago		o. State Off & Gas Lease No.	
1220 South St. Francis Dr., Santa				
1	UNDRY NOTICES AND REPORTS ON WEI			
	RM FOR PROPOSALS TO DRILL OR TO DEEPEN OR		7. Lease Name or Unit Agreement Nam	16
DIFFERENT RESERVO	IR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		* * * * * * *
PROPOSALS.)			Northeast Dr	inkard Unit
Type of Well.		T ! !	}	
OIL WEL	L GAS WELL OTHER	Injection		
Name of Operator			8. Well No.	
Apache Corporation			123	
3. Address of Operator			9. Pool name or Wildcat	
2000 Post Oak Blvd	, Ste. 100, Houston, Texas 77056-4400	WFX-774	Eunice N., Blinebry-Tul	bb-Drinkard
4. Well Location	, Div. Avai Mountain and a second			
Unit Letter	H: 2217 Feet From The North	Line and 989	Feet From The East	Line
Section	2 Township 21S Range 3	7E NMPN	1 Lea County	
Section	2 10 Kauge 5 10. Elevation (Show whether DF, RKB,		1 Lea county	
	3509' GR	,,		
		to Indicate Nature of Natio	on Penart or Other Data	
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data				
NOI	TICE OF INTENTION TO:	I SUB	SEQUENT REPORT OF:	
Dowform Domodia	Work Plug and Abandon	Remedial Work	Па	Itering Casing
Perform Remedia	Work Flug and Abandon		^	itering casing
☐ Temporarily Abandon ☐ Change Plans ☐ Commence Drilling Operations ☐ Plug and Abandonment				
_		☐ Casina Task and	d Camant Jah	
Pull or Alter Casir	ig	Casing Test and	1 Cement Job	
П онь-		✓ Other	Convert to Injection	
Other			Convert to injection	
or recompletion. 11/30/2001 12/3/2001 12/4/2001 3/13/2002 3/14/2002	Test anchors. Move in and rig up. Attempt to Hot water casing w/ 50 bbls - still unable to use Run in hole w/ overshot, latch onto fish @ 38 Pull out of hole w/ remaining production equival Rig down and wait on 4" injection packer & 2 Run in hole w/ 2-3/8" & 2-1/16" polylined tule Displace backside w/ packer fluid and pressure.	nseat pump. Back off 75' and pull out of hol pment. Run in hole w 2-1/16" tubing. ping & 4" packer, set p re test casing to 500# f	rods @ 3875'. Nipple up e w/ remaining rods. // 4" casing scraper. packer @ 5801'.	
3/19/2002 4/11/2002	Hook well up to injection system and put on it. Pressure test casing and chart - OK. (See atta			Same of a training
I hereby certify that the inform	ation above is true and complete to the best of my knowledge and belief.			
10	hold du borrel	TITLE Sr Engin	eering Technician	DATE 4/29/2002
SIGNATURE	services every	_ TITLE Sr. Engin	coming recimician 1	
TYPE OR PRINT NAME	Debra J. Anderson		TELEPHONE	NO. 713-296-6338
(This space for State Use)				
,			DATE	MAY 1 3 2002
APPROVED BY	ORIGINAL SICH	ED BY	DAIE	T O TANK
CONDITIONS OF APPROVA		SENTATIVE II/STAFF	MANAGER	