

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-7

5a. Indicate Type of Lease	
State ☐	Fee ☒
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name NORTHEAST DRINKARD UNIT
2. Name of Operator SHELL WESTERN E&P INC.	8. Farm or Lease Name NORTHEAST DRINKARD UNIT
3. Address of Operator P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)	9. Well No. 211
4. Location of Well UNIT LETTER <u>I</u> , <u>4620</u> FEET FROM THE <u>SOUTH</u> LINE AND <u>660</u> FEET FROM THE <u>EAST</u> LINE, SECTION <u>3</u> TOWNSHIP <u>21S</u> RANGE <u>37E</u> N.M.P.M.	10. Field and Pool or Widened NORTH EUNICE BLINEBRY- TUBB-DRINKARD OIL & GAS
15. Elevation (Show whether DF, RT, GR, etc.) 3491' DF	12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐
PULL OR ALTER CASING ☐	OTHER ☒ SQZ TUBB, OPEN BLINEBRY, ACDZ BLINEBRY & DRINKARD

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐	ALTERING CASING ☐
COMMENCE DRILLING OPERATIONS ☐	PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

1. POH w/prod equip.
2. Set RBP @ 6550' & cap w/sd.
3. Set pkr @ 6100'. Sqz Tubb perfs 6147' - 6436' w/150 sx Cls "C" cmt + .3% Halad-9 followed by 50 sx Cls "C" cmt + 2% CaCl₂. WOC 24 hrs.
4. POH w/pkr. DO to sd. Pres tst sqz to 500#.
5. Perf Blinebry 5885' - 6119' (1 JSPF).
6. Acdz Drinkard OH 6665' - 6740' w/3360 gals 15% HCl + 750# rock salt.
7. Set RBP @ 6635'.
8. Acdz Drinkard perfs 6574' - 6624' w/840 gals 15% HCl + 250# rock salt. Rel RBP.
9. Acdz Blinebry perfs 5885' - 6119' w/2940 gals 15% HCl + 750# rock salt using RBP & pkr.
10. POH w/RBP & pkr.
11. Install prod equip & return well to prod.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE 1-21-88
ORIGINAL SIGNED BY JERRY SEXTON
APPROVED BY DISTRICT I SUPERVISOR TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: _____