	UNITED STATES MENT OF THE INTERIOR OF LAND MANAGEMENT	FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993
		5. Lease Designation and Serial No. NM-2512
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoin Use "APPLICATION FOR PERMIT—" for such proposals		6. If Indian, Allottee or Tribe Name
	BMIT IN TRIPLICATE	7. If Unit or CA, Agreement Designation
I. Type of Well Oil Gas Well Well Other		8. Well Name and No.
2. Name of Operator	······································	Hawk B-1 No. 2
CONDCO INC.		9. API Well No. 30-025-06438
10 Desta Drive W, Midland, TX 79705 (915) 686-5583 4 Location of Well (Footage, Sec., T., R., M., or Survey Description)		10. Field and Pool, or Exploratory Area
Location of Well (Footage, Sec., T., R., M., or Su	irvey Description)	Blienbry & Drinkard 11. County or Parish, State
1980' FSL & 1980' FEL 9-2	215-37E Unit g	Lea, NM
2. CHECK APPROPRIATE E	BOX(s) TO INDICATE NATURE OF NOTICE, REPO	RT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent	Abandonment	Change of Plans
Subsequent Report	Recompletion Plugging Back	New Construction
		Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	La Other <u>ACIdize</u>	Dispose Water (Note: Report results of multiple completion on Wa
3. Describe Proposed or Completed Operations (Clearly	in the section of the	Completion or Recompletion Report and Log form
-	e vertical depths for all markers and zones pertinent to this work.)*	
8-2-90 MIRU. POOH w/tbg 30 bbls acid. 600# block.	we werke depths for all markers and zones pertinent to this work.)* . Kill well. Set pkr @ 5741'. Pump 30 30 bbls acid w/34 bbls flush (9# brine). w/pump & rods. Load & test 500#. Produc	bbls acid, 600# block, Rel pkr. POOH w/pkr.
8-2-90 MIRU. POOH w/tbg 30 bbls acid. 600# block.	me vertical depths for all markers and zones pertiment to this work.)* . Kill well. Set pkr @ 5741'. Pump 30 30 bbls acid w/34 bbls flush (9# brine).	bbls acid, 600# block, Rel pkr. POOH w/pkr. ing.
8-2-90 MIRU. POOH w/tbg 30 bbls acid. 600# block.	me vertical depths for all markers and zones pertiment to this work.)* . Kill well. Set pkr @ 5741'. Pump 30 30 bbls acid w/34 bbls flush (9# brine).	bbls acid, 600# block, Rel pkr. POOH w/pkr. ing.
8-2-90 MIRU. POOH w/tbg 30 bbls acid. 600# block.	me vertical depths for all markers and zones pertiment to this work.)* . Kill well. Set pkr @ 5741'. Pump 30 30 bbls acid w/34 bbls flush (9# brine).	bbls acid, 600# block, Rel pkr. POOH w/pkr. ing.
8-2-90 MIRU. POOH w/tbg 30 bbls acid. 600# block.	me vertical depths for all markers and zones pertiment to this work.)* . Kill well. Set pkr @ 5741'. Pump 30 30 bbls acid w/34 bbls flush (9# brine).	bbls acid, 600# block, Rel pkr. POOH w/pkr. ing.
8-2-90 MIRU. POOH w/tbg 30 bbls acid. 600# block.	me vertical depths for all markers and zones pertiment to this work.)* . Kill well. Set pkr @ 5741'. Pump 30 30 bbls acid w/34 bbls flush (9# brine).	bbls acid, 600# block, Rel pkr. POOH w/pkr. ing. RECEIVE
8-2-90 MIRU. POOH w/tbg 30 bbls acid. 600# block.	e vertical depths for all markers and zones pertinent to this work.)* . Kill well. Set pkr @ 5741'. Pump 30 30 bbls acid w/34 bbls flush (9# brine). w/pump & rods. Load & test 500#. Produc	bbls acid, 600# block, Rel pkr. POOH w/pkr. ing.
8-2-90 MIRU. POOH w/tbg 30 bbls acid. 600# block.	e vertical depths for all markers and zones pertinent to this work.)* . Kill well. Set pkr @ 5741'. Pump 30 30 bbls acid w/34 bbls flush (9# brine). w/pump & rods. Load & test 500#. Produc	bbls acid, 600# block, Rel pkr. POOH w/pkr. ing. AREA BECEIVE
8-2-90 MIRU. POOH w/tbg 30 bbls acid. 600# block.	e vertical depths for all markers and zones pertinent to this work.)* . Kill well. Set pkr @ 5741'. Pump 30 30 bbls acid w/34 bbls flush (9# brine). w/pump & rods. Load & test 500#. Produc	bbls acid, 600# block, Rel pkr. POOH w/pkr. ing.
8-2-90 MIRU. POOH w/tbg 30 bbls acid, 600# block, GIH w/MA, SN, & tbg. GIH RLM (6) File NMFU (3) 1 hereby certify that the foregoing is true and correct Signed	e vertical depths for all markers and zones pertinent to this work.)* . Kill well. Set pkr @ 5741'. Pump 30 30 bbls acid w/34 bbls flush (9# brine). w/pump & rods. Load & test 500#. Produc	bbls acid, 600# block, Rel pkr. POOH w/pkr. ing. AREA 001 15 RECEIVED
8-2-90 MIRU. POOH w/tbg 30 bbls acid, 600# block, GIH w/MA, SN, & tbg. GIH BLM (6) File NMFU (3) 1 hereby certify that the foregoing is true and correc Signed Or Control (This space for Federal or State office use)	Accords Accord	bbls acid, 600# block, Rel pkr. POOH w/pkr. ing. ARAM OCT 15 RECEIVED
8-2-90 MIRU. POOH w/tbg 30 bbls acid, 600# block, GIH w/MA, SN, & tbg. GIH RLM (6) File NMFU (3) 1 hereby certify that the foregoing is true and correct Signed	e vertical depths for all markers and zones pertinent to this work.)* . Kill well. Set pkr @ 5741'. Pump 30 30 bbls acid w/34 bbls flush (9# brine). w/pump & rods. Load & test 500#. Produc	bbls acid, 600# block, Rel pkr. POOH w/pkr. ing.
8-2-90 MIRU. POOH w/tbg 30 bbls acid, 600# block, GIH w/MA, SN, & tbg. GIH BLM (6) File NMFU (3) 1 hereby certify that the foregoing is true and correc Signed	Accords Accord	bbls acid, 600# block, Rel pkr. POOH w/pkr. ing.
8-2-90 MIRU. POOH w/tbg 30 bbls acid, 600# block, GIH w/MA, SN, & tbg. GIH BLM (6) File NMFU (3) 1 hereby certify that the foregoing is true and correct Signed	e vertical depths for all markers and zones pertinent to this work.)* . Kill well. Set pkr @ 5741'. Pump 30 30 bbls acid w/34 bbls flush (9# brine). w/pump & rods. Load & test 500#. Product w/pump & rods. Load & test 500#. Product	bbls acid, 600# block, Rel pkr. POOH w/pkr. ing. Date 10-08-1990 Date

-

