

NEW MEXICO OIL CONSERVATION COMMISSION
SANTA FE, NEW MEXICO

MISCELLANEOUS NOTICES

SUBMIT THIS NOTICE IN TRIPPLICATE TO THE DISTRICT OFFICE, OIL CONSERVATION COMMISSION, BEFORE THE WORK SPECIFIED IS TO BEGIN. A COPY WILL BE RETURNED TO THE SENDER ON WHICH WILL BE GIVEN THE APPROVAL, WITH ANY MODIFICATIONS CONSIDERED ADVISABLE, OR THE REJECTION BY THE COMMISSION OR AGENT, OF THE PLAN SUBMITTED. THE PLAN AS APPROVED SHOULD BE FOLLOWED, AND WORK SHOULD NOT BEGIN UNTIL APPROVAL IS OBTAINED. SEE ADDITIONAL INSTRUCTIONS IN THE RULES AND REGULATIONS OF THE COMMISSION.

INDICATE NATURE OF NOTICE BY CHECKING BELOW

NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO TEMPORARILY ABANDON WELL		NOTICE OF INTENTION TO DRILL DEEPER	
NOTICE OF INTENTION TO PLUG WELL		NOTICE OF INTENTION TO PLUG BACK	X	NOTICE OF INTENTION TO SET LINER	
NOTICE OF INTENTION TO SQUEEZE		NOTICE OF INTENTION TO ACIDIZE		NOTICE OF INTENTION TO SHOOT (CHRO)	
NOTICE OF INTENTION TO GUN PERFORATE		NOTICE OF INTENTION (OTHER) Dual Complete	X	NOTICE OF INTENTION (OTHER)	

OIL CONSERVATION COMMISSION
SANTA FE, NEW MEXICO

Hobbs, New Mexico

November 3, 1958

(PLACE)

(DATE)

GENTLEMEN:

FOLLOWING IS A NOTICE OF INTENTION TO DO CERTAIN WORK AS DESCRIBED BELOW AT THE

Humble Oil & Refining Company, N. M. State V WELL NO. 11 IN S
(COMPANY OR OPERATOR)
NE 1/4 SW 1/4 OF SEC. 19 T. 21-S. R. 37-E, NMPM, Hare POOL
(40-ACRE SUBDIVISION)
Lea COUNTY

FULL DETAILS OF PROPOSED PLAN OF WORK
(FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS)

It is proposed to abandon the Hare Field completion in State V-11 and recomplete as a dual Bluebry and Tubb field gas well as follows:

1. Squeeze off Hare zone perforations from 7620 to 7752 below Baker packer at 7600 feet.
2. Pressure test casing with 2000 psi for 30 minutes.
3. Perforate Tubb from 6708 to 6813, 6140 to 6150, 6194 to 622, 6232 to 6248 and 6262 to 6290 feet.
4. Set Baker Model D packer at 60.0 feet.
5. Perforate Bluebry from 5594 to 5599, 5613 to 5632, 5645 to 5660, 5656 to 5665, 5669 to 5673, 5674 to 5684, 5712 to 5722 and 5737 to 5753 feet.
6. Go in with 2-inch tubing with seating nipple for blanking plug placed to be below packer and circulating sleeve (closed position) placed to be above packer.
7. Swab down Tubb zone. Acidize as required.
8. Set blanking plug and open circulating sleeve.
9. Swab down Bluebry zone. Acidize as required.
10. Close circulation sleeve and remove blanking plug.
11. Place both zones on production and conduct packer leakage test.

APPROVED _____ 19_____
EXCEPT AS FOLLOWS:

Humble Oil & Refining Company
COMPANY OR OPERATOR
BY R. R. ALWORTH

POSITION Agent
SEND COMMUNICATIONS REGARDING WELL TO

APPROVED _____
OIL CONSERVATION COMMISSION

NAME Humble Oil & Refining Company
ADDRESS Box 2347, Hobbs, New Mexico
DEH/mcb