MOLK OF COPIES RECEIVED						
	1	NEW MEXICO OI	L CONSERVAT	ION CC SSION		FORM C-110
É		SAN	TA FE, NEW M	IEXICO		(Rev. 7-60)
G.5.					ATION	
	CERTIFI	CATE OF CO	MPLIANCE	ANDAUTHURLZ	NULA.	
GAS	1 Τ	O TRANSPOI	RT OIL AND	AND AUTHORIZ	2. 	
RATION OFFICE						
	FILE THE C	DRIGINAL AND 4	COPIES WITH TH	HE AMAROPRIATE OF	FILLE DY	
mpany or Operator Shell 01.	l Company			Lease State (Sec.2	2)	Well No. 16
nit Letter Section	Township 21	Range	37	County Les		
K 2	<u></u>		21	Kind of Lease (State, F	'ed,Fee)	
Terry-Blineb If well produces oil or con		Unit Letter	Section	Township	Rang	ge
give location of tan		Ţ	2	21. ddress to which approved of	conv of this t	37
athorized transporter of oil 🛖 or	condensate		Address (give a	taress to which approved t		
Shell Pipe Line Corp	•		Bex	1598 Hobbs, N	w Mexic	0
	ls Gas A	ctually Connec				
uthorized transporter of casing head	gas 😰] or dry gas	Date Con- nected	Address (give a	ddress to which approved a	copy of this j	form is to be sent)
Skelly Oil Company		1-18-64	Box 11	35 Eunice, N	ew Mexic	•
gas is not being sold, give reasons	and also explain it	s present disposition	<u> </u>			
New Well .	REAS	50N(S) FOR FILIN	Change in Own	nership	🗆	
Change in ' Oil		 one) y Gas	Change in Own Other (<i>explain</i> Recomp Le	nership		Blinebry
Change in ' Oil	Transporter (check o	 one) y Gas	Change in Own Other (<i>explain</i> Recomp Le	nership below) ted from Hare to		Blinebry
Change in ' Oil	Transporter (check o	 one) y Gas	Change in Own Other (<i>explain</i> Recomp Le	nership below) ted from Hare to		Bline bry
Change in ' Oil Casing	Transporter (check o	 one) y Gas	Change in Own Other (<i>explain</i> Recomp Le	nership below) ted from Hare to		Blinebry
Change in ' Oil Casing	Transporter (check o	 one) y Gas	Change in Own Other (<i>explain</i> Recomp Le	nership below) ted from Hare to		Blinebry
Change in ' Oil Casing	Transporter (check o	 one) y Gas	Change in Own Other (<i>explain</i> Recomp Le	nership below) ted from Hare to		Blinebry
Change in ' Oil Casing	Transporter (check o	 one) y Gas	Change in Own Other (<i>explain</i> Recomp Le	nership below) ted from Hare to		Blinebry
Change in ' Oil Casing	Transporter (check o	 one) y Gas	Change in Own Other (<i>explain</i> Recomp Le	nership below) ted from Hare to		Blinebry
Change in Oil Casing emarks	Transporter (check o	one) y Gas	Change in Ow Other (explain Recomp le January	nership below) ted from Hare t 18, 1964.	o Terry-	
Change in Oil Casing .emark s	Transporter (check o	one) y Gas	Change in Ow Other (explain Recomp le January	nership below) ted from Hare t 18, 1964.	o Terry-	
Change in Oil Casing Temarks	Transporter (check o Dr head gas . Co	one) y Gas ondensate ondensate	Change in Ow Other (explain Recomp le January	nership below) ted from Hare t 18, 1964.	o Terry-	
Change in Oil Casing Remarks The undersigned certifies that th Execut	Transporter (check o	one) y Gas ondensate ondensate alations of the Oil day of Ja	Change in Own Other (explain Recomp le January Conservation Con MATY By	mership below) ted from Hare to 18, 1964. mmission have been con , 19 64.	• Terry-	
Change in Oil Casing Remarks The undersigned certifies that th Execut OIL CONSERV	Transporter (check o Dr head gas . Co ne Rules and Regu ed this the 20 1	one) y Gas ondensate ondensate alations of the Oil day of Ja	Change in Own Other (explain Recomp le January Conservation Con Mary By S. B.	nership below) ted from Hare to 18, 1964. mmission have been con , 19 64.	• Terry-	
Change in Oil Casing Remarks The undersigned certifies that th Execut	Transporter (check o Dr head gas . Co ne Rules and Regu ed this the 20 1	one) y Gas ondensate ondensate alations of the Oil day of Ja	Change in Own Other (explain Recomp le January Conservation Con By By S. B. Title Divis	mership below) ted from Hare to 18, 1964. mmission have been con , 19 64.	• Terry-	
Change in Oil Casing Remarks The undersigned certifies that th Execut OIL CONSERV	Transporter (check o Dr head gas . Co ne Rules and Regu ed this the 20 1	one) y Gas ondensate ondensate alations of the Oil day of Ja	Change in Own Other (explain Recomple January Conservation Con By By By S. B. Title Divist Company	nership below) ted from Hare to 18, 1964. mmission have been con , 1964. Deal	• Terry-	
Change in Oil Casing Remarks The undersigned certifies that th Execut OIL CONSERV	Transporter (check o Dr head gas . Co ne Rules and Regu ed this the 20 1	one) y Gas ondensate ondensate alations of the Oil day of Ja	Change in Own Other (explain Recomple January Conservation Con By By S. B. Title Divisi Company Shell	nership below) fted from Hare to 18, 1964. mmission have been con , 1964. Deal Lon Production S Oil Company	• Terry-	
Change in Oil Casing Remarks The undersigned certifies that th Execut OIL CONSERV Approved by Finte	Transporter (check o Dr head gas . Co ne Rules and Regu ed this the 20 1	one) y Gas ondensate ondensate alations of the Oil day of Ja	Change in Own Other (explain Recomple January Conservation Con By By By S. B. Title Divist Company	nership below) fted from Hare to 18, 1964. mmission have been con , 1964. Deal Lon Production S Oil Company	• Terry-	

	SRECEIVED										
a second and the second se	STRIBUTION	 									
FILE			<u> </u>	NEW MEX	100 0		NSER	VATION 0	COMMISSIO)3
U.S.G.S. LAND OFFICE) pro en	·		NELL'S	(Rev 3-55)	
TRANSPORTER	OIL GAS									-	
PRORATION OFFI	ся		(Subn	nit to appro	priate L	Distric	Office	as per din	ALE SIGN AUGO	110064	
Name of Compa	•	011 C	ompany			Addres	-	1858	Roswell.	, New Maxico	
Lease				Well No.	Unit	Letter	Section	Township	•	Range	
A	State			16	1	<u> </u>	2		. 9	37-5	
Date Work Peri	· · · ·	F	Pool Terry.	bry				County	Lea		
		· ·	and the second	S A REPOR	T OF: (Cbeck					
Beginning	g Drilling Op	erations	<u> </u>	asing Test a	and Cem	ent Job		Cther (E	Explain): Terr	·y-	
Plugging			R	emedial Worl	k	Reco			ire to Blin		
	int of work d	one, natu	ire and quantity	of materials	s used,					• • • • • • • • • • • • • • • • • • •	
15% 5. Trea each 6. Pull 7. Ran 8. Trea Mark 9. Pull 10. Ran Witnessed by	BDA with ted with stage. ed tubing Baker FRI ted with II Adom ed 3" tui 186 joint	Fe ad 1300 g and BC on 20,00 ite/ga bing. ts (57	ditive. R gallons 15 packer. 3" X-line 0 gallons llon.	Aised tu S BDA in frac tub lease or ME. Srd.	bing (13 - dng a ude s	to 57 100 ni se ontai	41'. gallor t pack ning J	n stages (er @ 572 L# 20-40	using ball	otted 200 gallon 1 sealers betwee /gallon and 1/20	A
¥.	D. Moor			Position	n		ng, hi	Company	_	ended 4 ¹ sub bel (ever)	
				Pro	d. Po	rezen		Company Shell	011 Comp	(ever)	
D F Elev.			FILL IN BE	ELOW FOR	d. Po	DIAL W	ORK R	Company Shell	011 Comp	(ever)	
		TD	FILL IN BE	ELOW FOR	REMEI	DIAL W	ORK R	Company Shell	Oil Comp	(ever)	
		T D		ELOW FOR	REMEI	DIAL W	ORK R	Company Shell E PORTS Of Producing	O11 Comp NLY 3 Interval	(over)	
Tubing Diame	ter	T D	FILL IN BE	ELOW FOR	REMEI	DIAL W	ORK R	Company Shell E PORTS Of Producing	O11 Comp NLY 3 Interval	(over)	
	<u></u>	T D		ELOW FOR	REMEI	DIAL W	ORK R	Company Shell E PORTS Of Producing	O11 Comp NLY 3 Interval	(over)	
Tubing Diame	erval(s)	T D		ELOW FOR	REMEI	Oil Stri	ORK R	Company Shell EPORTS Of Producing eter	O11 Comp NLY 3 Interval	(over)	
Tubing Diamet	erval(s)	T D		Pro ELOW FOR ORI PBT	REMEI	PERENE DIAL W WELL I Oil Stri	ORK R DATA ng Diamo	Company Shell EPORTS Of Producing eter	O11 Comp NLY 3 Interval	(over)	
Tubing Diamet	erval(s)	T D		ELOW FOR ORI PBT RESU	REMEI	Produci F WORI	ng Diamo	Company Shell EPORTS Of Producing eter	O11 Comp NLY 3 Interval	(ever)	
Tubing Diamet Perforated Inte Open Hole Inte	erval(s) erval Date o	T D	Tubing Depth Oil Producti	ELOW FOR ORI PBT RESU	REMEI GINAL TD	Produci F WORI	ng Diamo	Company Shell E PORTS Of Producing eter ation(s) Production	OIL Compo NLY GINTERVAL OIL Strin	(ever)	.
Tubing Diamer Perforated Into Open Hole Into Test Before	erval(s) erval Date o	T D	Tubing Depth Oil Producti	ELOW FOR ORI PBT RESU	REMEI GINAL TD	Produci F WORI	ng Diamo	Company Shell E PORTS Of Producing eter ation(s) Production	OIL Compo NLY GINTERVAL OIL Strin	(ever)	
Tubing Diamet Perforated Into Open Hole Into Test Before Workover After	erval(s) erval Date o Test	T D	Tubing Depth Oil Producti	RESU on Gas	REMEI GINAL TD	Produci F WORI	ORK R DATA ng Diamo ing Form KOVER Water I H	Company Shell E PORTS 0 Producing eter ation(s) Production B P D	OIL Compo NLY GINTERVAL OIL String GOR Cubic feet/	(ever)	e¥.
Tubing Diamet Perforated Into Open Hole Into Test Before Workover After	erval(s) erval Date o Test	T D	Tubing Depth Oil Producti BPD	RESU on Gas	REMEI GINAL TD LTS OF Produc	Produci F WORI	ATA ng Diame ing Form KOVER Water I I eby certi e best of	Company Shell E PORTS Of Producing eter ation(s) Production B P D ify that the in f my knowled	OIL Compo NLY GINERVAL OIL String OIL String GOR Cubic feet/ Information give Ige. Origin	(over)	e¥.
Tubing Diamer Perforated Into Open Hole Into Test Before Workover After Workover	erval(s) erval Date o Test	T D	Tubing Depth Oil Producti BPD	RESU on Gas	REMEI GINAL GINAL TD LTS OF Produc MC F P I	Produci F WORI tion I here to the	ATA ng Diamo ing Form KOVER Water I H eby certi e best of R.	Company Shell E PORTS OF Producing eter ation(s) Production B P D fy that the in f my knowled A. Lewell	OIL Compo NLY GINTERVAL OIL Strin GOR Cubic feet/ Cubic feet/ Information give ge. Origin B. A.	(ever)	e¥.
Tubing Diamen Perforated Into Open Hole Into Test Before Workover After Workover	erval(s) erval Date o Test	T D	Tubing Depth Oil Producti BPD	Pro ELOW FOR OR PBT PBT Con Gas	REMEI GINAL TD LTS OF Produc	Produci Oil Stri Produci F WORI tion D	ATA ng Diamo ing Form KOVER Water I H eby certi e best of R. ion Din any	Company Shell E PORTS OF Producing eter ation(s) Production B P D fy that the in f my knowled A. Lewell	Oil Compo NLY GINERVAL Oil Strin GOR Cubic feet/ Cubic feet/ Information give Ige. Origin -B. A. sploit atio	(over)	e¥ tial

4

ŧ١

E . ę

choke. FTP 105 pai. CP packer. Gravity 41.40 API.

12. Recovered load. "Π

packer; top 40 Joints (1500') tubing internally plastic coated.

NUMBER OF COPIES RECEIV DISTRIBUTIO SANTA FF FILE U.E.G.S. LAND OFFICE TRANSPORTER OFL OPERATION OFFICE OPERATOR		EW MEXI WELL LOCATI SEE INSTRUCTIONS		EAGE DED		PLATO. C. C.	C-128 5/1/57
			SECTION A				
Operator Shel	1 011 Company	1 7	Lease	ate (Sec.2)		Well No. 16	
Unit Letter K	Section 2	Township 21	Range 31	County	Lea	1	
Actual Footage Lo 3546	ocation of Well: feet from the	north line and	1700	t i tai a sha			
Ground Level Elev			Pool	feet from the		line Dedicated Acreage:	
34921	Bl	linebry	Terry-	Blinebry		40	Acres
2. If the answer t wise? YES	NO I	"no," have the interests If answer is "yes," Type "no," list all the owners	of Consolidation and their respective			zation agreement or	other-
		SECTION B			י ך	CERTIFICATION	
					in SECTION plete to the belief. Name R. A. Position Dist. Company Shell (ertify that the inform N A above is true an e best of my knowled Original Sign H. A. LOW Lewery Exploitation H Oil Company N 2 1 1964	nd com- dge and ned By ERY
	00'				shown on the plotted from surveys made supervision and correct and belief. Date Survey	yed Professional Engine d Surveyor	B was al y is true nowledge

INSTRUCTIONS FOR COMPLETION OF FORM C-128

- 1. Operator shall furnish and certify to the information called for in Section A.
- 2. Operator shall outline the dedicated acreage for *both* oil and gas wells on the plat in Section B.
- 3. A registered professional engineer or land surveyor registered in the State of New Mexico or approved by the Commission shall show on the plat the location of the well and certify this information in the space provided.
- 4. All distances shown on the plat must be from the outer boundaries of the Section.

.

5. If additional space is needed for listing owners and their respective interests as required in question 3 of Section A, please use space below.

DI	TRIBUTION	
SANTA FE		1
FILE		1
U.S.G.S.		
LAND OFFICE		
	OIL	
TRANSPORTER	GAS	
PROBATION OFFIC	:E	
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

1.

· · · ż

MISCELLANEOUS NOTICES



strict Office, Oil Conservation Commission, before the work specified is to begin. A copy will be

Shell Oil Company

Box 1858

Roswell, New Mexico

Name.....

Address...

returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

 Pull tubing and packer. Set CIBP at 6550' and cap with Perforate with one 3/8" jet sho 5813', 5852', 5863', 5866', 58' 5928'. Run tubing and packer and acidy stages. Pull tubing and packer. Run 3" XL tubing and packer and oil plus 1#/gallon sand plus 1, Pull 3" XL tubing and packer at 8. Run tubing and place on products 	CK INTENTION	Notice of Intention to Set Liner Notice of Intention to Shoot (Nitro)	
NOTICE OF INTENTION TO ACIDIZE NOTICE OF INTENTION NOTICE OF (OTHER) OIL CONSERVATION COMMISSION SANTA FE, NEW MEXICO Gentlemen: Following is a Notice of Intention to do certain work Shell Oil Company State (40-acre Subdivision) Lea Company or Operator) NE NE 1/4 of Sec. (40-acre Subdivision) Lea County. RECOMPLETE FROM HARE TO BLINEBRY FULL DETAIL (FOLLOW INSTRUCT) Pull tubing and packer. Set CIBP at 6550' and cap with 3. Perforate with one 3/8" jet shot 5813', 5852', 5863', 5856', 587 5928'. 4. Run tubing and packer and acidi stages. 5. Pull tubing and packer and acidi stages. 6. Run 3" XL tubing and packer and acidi plus 1#/gallon sand plus 1, 7. Pull 3" XL tubing and packer and 8. Run tubing and place on products			
ALL INDEXTY (OTHER) IL CONSERVATION COMMISSION SANTA FE, NEW MEXICO Gentlemen: Following is a Notice of Intention to do certain work Shell Oil Company State (Company or Operator) NE 1/4 SW (40-acre Subdivision) Lea County. RECOMPLETE FROM HARE TO BLINEBRY FULL DETAIL (FOLLOW INSTRUCT) 1. Pull tubing and packer. 2. Set CIBP at 6550' and cap with 3. Perforate with one 3/8" jet shot 5813', 5852', 5863', 5866', 58' 5928'. 4. Bun tubing and packer and acidy stages. 5. Pull tubing and packer and acidy stages. 5. Pull tubing and packer and acidy stages. 5. Pull tubing and packer and 6. Run 3" XL tubing and packer and 7. Pull 3" XL tubing and packer and 8. Run tubing and place on product	Intention		
SANTA FE, NEW MEXICO Gentlemen: Following is a Notice of Intention to do certain work Shell Oil Company State (Company or Operator) NE // SW // of Sec. 2 , T. 21 (10-acre Bubdivision) Lea County. RECOMPLETE FROM HARE TO BLINEBRY FULL DETAIL (FOLLOW INSTRUCT) Pull tubing and packer. Set CIBP at 6550' and cap with Perforate with one 3/8" jet sho 5813', 5852', 5863', 5866', 58' 5928'. 4. Run tubing and packer and acidi stages. 5. Pull tubing and packer. 6. Run 3" IL tubing and packer and oil plus 1#/gallon sand plus 1, 7. Pull 3" XL tubing and packer at 8. Run tubing and place on products		Notice of Intention (Other)	
Following is a Notice of Intention to do certain work Shell Oil Company State (Company or Operator) NE <u>/4</u> SW /4 of Sec. 2 2] (40-acres Bubdivision) Lea County. RECOMPLETE FROM HARE TO BLINEBRY FULL DETAIL (FOLLOW INSTRUCT) 1. Pull tubing and packer. 2. Set CIBP at 6550' and cap with 3. Perforate with one 3/8" jet sho 5813', 5852', 5863', 5866', 58' 5928'. 4. Run tubing and packer and acidy stages. 5. Pull tubing and packer. 6. Run 3" XL tubing and packer and oil plus 1#/gallon sand plus 1, 7. Pull 3" XL tubing and packer and 8. Run tubing and place on products	Roswell, New Mex (Place)	ico January 3, 1964 (Date)	<u>k</u>
Shell Oil Company State colspany colspany <t< td=""><td>as described below at the.</td><td></td><td></td></t<>	as described below at the.		
NE <u>14</u> SW <u>14</u> of Sec. <u>2</u> , T. <u>21</u> (40-acre Bubdivision) Lea <u>County.</u> <u>RECOMPLETE FROM HARE TO BLINEBRY</u> FULL DETAIL (FOLLOW INSTRUCT 1. Pull tubing and packer. 2. Set CIBP at 6550' and cap with 3. Perforate with one 3/8" jet sho 5813', 5852', 5863', 5866', 58' 5928'. 4. Run tubing and packer and acidy stages. 5. Pull tubing and packer. 6. Run 3" XL tubing and packer and oil plus 1#/gallon sand plus 1, 7. Pull 3" XL tubing and packer and 8. Run tubing and place on products		• /	17
Lea	.S B 37 E	MPM. Hare	(Unit) Pool
 RECOMPLETE FROM HARE TO BLINEBRY FULL DETAIL (FOLLOW INSTRUCT) Pull tubing and packer. Set CIBP at 6550' and cap with Perforate with one 3/8" jet sho 5813', 5852', 5863', 5866', 58' 5928'. Run tubing and packer and acidi stages. Pull tubing and packer. Run 3" XL tubing and packer and oil plus 1#/gallon sand plus 1, 7. Pull 3" XL tubing and packer at 8. Run tubing and place on products 	,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,,	· · · · ·	
7. Pull 3" XL tubing and packer at 8. Run tubing and place on product	t at 5786', 5791' 72', 5874', 5881', 20 with 1500 gal i set @ 5750'. Fr	, 5799', 5801', 5804', , 5882', 5901', 5912', lons 15% BDA using 2 Ru racture treat with 20,0	CN balls betwee
A 1	id sheek for sand	fill.	
Approved.		Company or Original S	igned By
Except as follows:	19 She		
Approved	19 She. By R. J	A. Lowery B. A. LO.	WERY