
Form 9-331 a (Feb. 1951)



(SUBMIT IN TRIPLICATE)

Land Office	Las	Cruce	В
Lease No	LC (031741	Ъ
Unit	nmpi	U	

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

	F INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF	F INTENTION TO CHANGE I	1	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.
	F INTENTION TO TEST WAT		SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF	F INTENTION TO RE-DRILL	OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
	F INTENTION TO SHOOT OF	ľ	SUBSEQUENT REPORT OF ABANDONMENT
	F INTENTION TO PULL OR A F INTENTION TO ABANDON		SUPPLEMENTARY WELL HISTORY
	(indica	TE ABOVE BY CHECK MARK N	NATURE OF REPORT, NOTICE, OR OTHER DATA)
Hawk	B-3		April 17
_			line and 1980 ft. from $\begin{bmatrix} E \end{bmatrix}$ line of sec.
	Sec. 3 Sec. and Sec. No.)	21 S 37 (Twp.) (F	E NMPM
OLLA	Blinebry	Lee	Range) (Meridian)
	(Field)		Subdivision) (State or Territory)
	mided 4-8-57.	Ran 10 3/4	casing set at 268t with 250 an
Spe		Plus dos 1 0	-57. Casing test before drilli
Spo ent c	ILTULIALEIL.	LTAK GOMM P-A	(T)/* OGBINE CESC DEINTE CT1111
g 100	0#-1000#. F	ormation test	after drilling plug: broke from
Spo ent o g 100	ILTULIALEIL.	ormation test	after drilling plug: broke fr
Spo ent o g 100 # to	00#-1000#. F 200#.	ormation test	after drilling plug: broke fr
Spo ent o g 100 # to	00#-1000#. F 200#.	ormation test	after drilling plug: broke fr
Spuent of 100 Ran	200#. F 200#. 75 joints 7	5/8" casing	set at 3119 with 1150 sacks, to
Spuent of 100 Rancement ore d	200#. F 200#. 75 joints 7	5/8" casing	after drilling plug: broke fr
Spuent of 100 Rancement	17-011ated. 00#-1000#. F 200#. 1 75 joints 7 1 1350'. Pl 1 111ling plug	5/8" casing	set at 3119 with 1150 sacks, to
Spuent of 100 Ran	17-011ated. 00#-1000#. F 200#. 1 75 joints 7 1 1350'. Pl 1 111ling plug	5/8" casing	set at 3119 with 1150 sacks, to
Spure of to Ran cemen ore d	75 joints 7 t 1350'. Plants 1 t 1350'. Plants 1 t 1000#.	5/8" casing ug down 4-14-1200#.	set at 3119° with 1150 sacks, to 57. Fifteen minute casing test Formation test after drilling
Ran Ran Cemen ore d	75 joints 7 it 1350'. Plailing plug	5/8" casing ug down 4-14-1200#.	set at 3119 with 1150 sacks, to
Ran Ran Cemen ore d	75 joints 7 t 1350'. Plants 1 t 1350'. Plants 1 t 1000#.	5/8" casing ug down 4-14-1200#.	set at 3119° with 1150 sacks, to 57. Fifteen minute casing test Formation test after drilling
Rancement of attended	175 joints 7 175 joints 7 175 joints 7 18 1350'. Pl 18 111ing plug 1000#. Continental Box 68	5/8" casing ug down 4-14-1200#.	set at 3119° with 1150 sacks, to 57. Fifteen minute casing test Formation test after drilling
Rancement of attended	175 joints 7 175 joints 7 175 joints 7 18 1350'. Pl 18 111ing plug 1000#. Continental Box 68	5/8" casing ug down 4-14-1200#	set at 3119 with 1150 sacks, to 57. Fifteen minute casing test Formation test after drilling iting by the Geological Survey before operations may be commenced.
Spuent of 100 Rancemen de at	75 joints 7 it 1350'. Plarilling plug 1000#. Continental	5/8" casing ug down 4-14-1200#	set at 3119° with 1150 sacks, to 57. Fifteen minute casing test Formation test after drilling