Submit 3 Copies to Approriate		<i>c</i> ·	
Office	District State of New M Energy, Minerals and Na		
DISTRICT I	Energy, winter as and ina	atural Resouces	
1625 N. French Dr., Hobbs, N	IM 88240		FORM C-1 Revised March 25, 19
DISTRICT II	OIL CONSERVATIO	N DIVISION	WELL API NO.
811 South First, Artesia, NM			
DISTRICT III	Santa Fe, NM		30-025-06519 5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, N		07505	STATE FEE
DISTRICT IV			6. State Oil & Gas Lease No.
1220 South St. Francis Dr., Sa	nta Fe, NM 87505		
	SUNDRY NOTICES AND REPORTS ON WE		
(DO NOT USE THIS :	FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OF	R PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERV	OIR. USE "APPLICATION FOR PERMIT" (FORM C-10	1) FOR SUCH	
PROPOSALS.)			Northeast Drinkard Unit
Type of Well:		Injection	
Name of Operator			8. Well No.
Apache Corporation	<u>on</u>		207
2000 Post Oak Bly	<u>zd., Ste₄ 100, Houston, Texas 77056-4400</u>	WFX-774	9. Pool name or Wildcat Eunice N., Blinebry-Tubb-Drinkard
Well Location Unit Letter	N / 4: 2970 Feet From The South	Line and 2308	TTT /
Section		37E NM	
	10. Elevation (Show whether DF, RKB,		Country
	3458' GR Check Appropriate Pol	v to Indicate Nature - CN-	tice, Report, or Other Data
NC	DTICE OF INTENTION TO:		BSEQUENT REPORT OF:
Perform Remed	ial Work 🛛 Plug and Abandon	Remedial Wo	
Temporarily Aba	-	Commence D	rilling Operations I Plug and Abandonment
Pull or Alter Cas	sing	Casing Test a	nd Coment Joh
Other			
Other 2. Describe propose	ed or completed operations (Clearly state all pertinen	Other	Convert to Injection
2. Describe propose	ed or completed operations. (Clearly state all pertinen roposed work). SEE RULE 1103. For Multiple Com Test anchors. Move in and rig up. Pull out of	Other tt details, and give perti pletions: Attach wellbo	Convert to Injection nent dates, including estimated date ore diagram of proposed completion
2. Describe propose of starting any pr or recompletion.	Test anchors. Move in and rig up. Pull out of	Other t details, and give perti pletions: Attach wellbo f hole w/ production	Convert to Injection nent dates, including estimated date ore diagram of proposed completion equipment. Nipple up BOP.
 Describe propose of starting any pr or recompletion. 2/27/2002 2/28/2002 	Test anchors. Move in and rig up. Pull out of Run in hole w/ 5-1/2" casing scraper to 6851'.	Other t details, and give pertipletions: Attach wellbo f hole w/ production Circulate hole clean	Convert to Injection nent dates, including estimated date ore diagram of proposed completion equipment. Nipple up BOP.
 Describe propose of starting any pr or recompletion. 2/27/2002 	Test anchors. Move in and rig up. Pull out of	Other tt details, and give perti- pletions: Attach wellbo f hole w/ production Circulate hole clean ker, set packer @ 561	Convert to Injection nent dates, including estimated date ore diagram of proposed completion equipment. Nipple up BOP.
 Describe propose of starting any pr or recompletion. 2/27/2002 2/28/2002 	Test anchors. Move in and rig up. Pull out of Run in hole w/ 5-1/2" casing scraper to 6851'. Run in hole w/ 2-3/8" polylined tubing & pack	Other t details, and give pertipletions: Attach wellbo f hole w/ production Circulate hole clean ker, set packer @ 561 K.	Convert to Injection nent dates, including estimated date ore diagram of proposed completion equipment. Nipple up BOP.
 Describe propose of starting any pr or recompletion. 2/27/2002 2/28/2002 3/4/2002 	Test anchors. Move in and rig up. Pull out of Run in hole w/ 5-1/2" casing scraper to 6851'. Run in hole w/ 2-3/8" polylined tubing & pack pressure test casing to 500# for 30 minutes - C	Other tt details, and give perti- pletions: Attach wellbo f hole w/ production Circulate hole clean ker, set packer @ 561 OK. njection.	Convert to Injection nent dates, including estimated date ore diagram of proposed completion equipment. Nipple up BOP.
 Describe propose of starting any pr or recompletion. 2/27/2002 2/28/2002 3/4/2002 3/13/2002 	Test anchors. Move in and rig up. Pull out of Run in hole w/ 5-1/2" casing scraper to 6851'. Run in hole w/ 2-3/8" polylined tubing & pack pressure test casing to 500# for 30 minutes - C Hook well up to injection system and put on in	Other tt details, and give perti- pletions: Attach wellbo f hole w/ production Circulate hole clean ker, set packer @ 561 OK. njection.	Convert to Injection nent dates, including estimated date ore diagram of proposed completion equipment. Nipple up BOP.
 Describe propose of starting any pr or recompletion. 2/27/2002 2/28/2002 3/4/2002 3/13/2002 	Test anchors. Move in and rig up. Pull out of Run in hole w/ 5-1/2" casing scraper to 6851'. Run in hole w/ 2-3/8" polylined tubing & pack pressure test casing to 500# for 30 minutes - C Hook well up to injection system and put on in	Other tt details, and give perti- pletions: Attach wellbo f hole w/ production Circulate hole clean ker, set packer @ 561 OK. njection.	Convert to Injection nent dates, including estimated date ore diagram of proposed completion equipment. Nipple up BOP.
 Describe propose of starting any pr or recompletion. 2/27/2002 2/28/2002 3/4/2002 3/13/2002 	Test anchors. Move in and rig up. Pull out of Run in hole w/ 5-1/2" casing scraper to 6851'. Run in hole w/ 2-3/8" polylined tubing & pack pressure test casing to 500# for 30 minutes - C Hook well up to injection system and put on in	Other tt details, and give perti- pletions: Attach wellbo f hole w/ production Circulate hole clean ker, set packer @ 561 OK. njection.	Convert to Injection nent dates, including estimated date ore diagram of proposed completion equipment. Nipple up BOP.
 Describe propose of starting any pr or recompletion. 2/27/2002 2/28/2002 3/4/2002 3/13/2002 	Test anchors. Move in and rig up. Pull out of Run in hole w/ 5-1/2" casing scraper to 6851'. Run in hole w/ 2-3/8" polylined tubing & pack pressure test casing to 500# for 30 minutes - C Hook well up to injection system and put on in	Other tt details, and give perti- pletions: Attach wellbo f hole w/ production Circulate hole clean ker, set packer @ 561 OK. njection.	Convert to Injection nent dates, including estimated date ore diagram of proposed completion equipment. Nipple up BOP.
 Describe propose of starting any pr or recompletion. 2/27/2002 2/28/2002 3/4/2002 3/13/2002 	Test anchors. Move in and rig up. Pull out of Run in hole w/ 5-1/2" casing scraper to 6851'. Run in hole w/ 2-3/8" polylined tubing & pack pressure test casing to 500# for 30 minutes - C Hook well up to injection system and put on in	Other tt details, and give perti- pletions: Attach wellbo f hole w/ production Circulate hole clean ker, set packer @ 561 OK. njection.	Convert to Injection nent dates, including estimated date ore diagram of proposed completion equipment. Nipple up BOP. 6'. Displace backside w/ packer fluid and
 Describe propose of starting any pr or recompletion. 2/27/2002 2/28/2002 3/4/2002 3/13/2002 4/11/2002 	Test anchors. Move in and rig up. Pull out of Run in hole w/ 5-1/2" casing scraper to 6851'. Run in hole w/ 2-3/8" polylined tubing & pack pressure test casing to 500# for 30 minutes - C Hook well up to injection system and put on in Pressure test casing and chart - OK. (See attac	Other tt details, and give perti- pletions: Attach wellbo f hole w/ production Circulate hole clean ker, set packer @ 561 OK. njection.	Convert to Injection nent dates, including estimated date ore diagram of proposed completion equipment. Nipple up BOP.
 Describe propose of starting any pr or recompletion. 2/27/2002 2/28/2002 3/4/2002 3/13/2002 4/11/2002 	Test anchors. Move in and rig up. Pull out of Run in hole w/ 5-1/2" casing scraper to 6851'. Run in hole w/ 2-3/8" polylined tubing & pack pressure test casing to 500# for 30 minutes - C Hook well up to injection system and put on in	Other t details, and give pertipletions: Attach wellbo f hole w/ production Circulate hole clean (ker, set packer @ 561 OK. ajection. Ched chart)	Convert to Injection nent dates, including estimated date ore diagram of proposed completion equipment. Nipple up BOP. 6'. Displace backside w/ packer fluid and
 Describe propose of starting any pr or recompletion. 2/27/2002 2/28/2002 3/4/2002 3/13/2002 4/11/2002 	Test anchors. Move in and rig up. Pull out of Run in hole w/ 5-1/2" casing scraper to 6851'. Run in hole w/ 2-3/8" polylined tubing & pack pressure test casing to 500# for 30 minutes - C Hook well up to injection system and put on in Pressure test casing and chart - OK. (See attac	Other t details, and give pertipletions: Attach wellbo f hole w/ production Circulate hole clean (ker, set packer @ 561 OK. ajection. Ched chart)	Convert to Injection nent dates, including estimated date ore diagram of proposed completion equipment. Nipple up BOP. 6'. Displace backside w/ packer fluid and
 Describe propose of starting any pr or recompletion. 2/27/2002 2/28/2002 3/4/2002 3/13/2002 4/11/2002 4/11/2002 Chereby certify that the information of the second start of the second	Test anchors. Move in and rig up. Pull out of Run in hole w/ 5-1/2" casing scraper to 6851'. Run in hole w/ 2-3/8" polylined tubing & pack pressure test casing to 500# for 30 minutes - C Hook well up to injection system and put on in Pressure test casing and chart - OK. (See attac	Other t details, and give pertipletions: Attach wellbo f hole w/ production Circulate hole clean (ker, set packer @ 561 OK. ajection. Ched chart)	Convert to Injection nent dates, including estimated date one diagram of proposed completion equipment. Nipple up BOP. 6'. Displace backside w/ packer fluid and
 Describe propose of starting any pr or recompletion. 2/27/2002 2/28/2002 3/4/2002 3/13/2002 4/11/2002 	Test anchors. Move in and rig up. Pull out of Run in hole w/ 5-1/2" casing scraper to 6851'. Run in hole w/ 2-3/8" polylined tubing & pack pressure test casing to 500# for 30 minutes - C Hook well up to injection system and put on in Pressure test casing and chart - OK. (See attac	Other the details, and give pertipletions: Attach wellbor f hole w/ production of Circulate hole clean (ker, set packer @ 561) (K.) aljection. Ched chart) TITLE Sr. Engin	Convert to Injection nent dates, including estimated date ore diagram of proposed completion equipment. Nipple up BOP. 6'. Displace backside w/ packer fluid and 6'. Displace backside w/ packer fluid and data data
 Describe propose of starting any pr or recompletion. 2/27/2002 2/28/2002 3/4/2002 3/13/2002 4/11/2002 I hereby certify that the information of the print name 	Test anchors. Move in and rig up. Pull out of Run in hole w/ 5-1/2" casing scraper to 6851'. Run in hole w/ 2-3/8" polylined tubing & pack pressure test casing to 500# for 30 minutes - C Hook well up to injection system and put on in Pressure test casing and chart - OK. (See attac	Other t details, and give pertipletions: Attach wellbo f hole w/ production Circulate hole clean (ker, set packer @ 561 OK. ajection. Ched chart)	Convert to Injection nent dates, including estimated date ore diagram of proposed completion equipment. Nipple up BOP. 6'. Displace backside w/ packer fluid and 0'. Organization doology neering Technician DATE TELEPHONE NO. 713-296-6338

5

abmit to Appropriate District Office			of New Mex als and Natur		UTCAC		
et Lease-6 copies ee Lease-5 copies		E jy, wintera	als and matur	iai Kesu	uices		
ISTRICT I							Form C-
625 N French Dr., Houbs, NM 88240							Revised March 25, 1
ISTRICT II						WELL API NO.	
11 South First, Artesia, NM 88210		OIL CONSE			N	30-025-06519)
ISTRICT III		1220 South St. Francis Drive			5. Indicate Type of Lease		
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87				505			FEE
<u>DISTRICT IV</u> 220 South St. Francis Dr., Santa Fe, NM 87505						6. State Oil & Gas Lease No.	
WELL COMPLE'	TION OR 1	RECOMPLETION	NREPORT	ANDLO	G		
a. Type of Well:	11011 0101		(nun ontri			7. Lease Name or Unit Agreen	nent Name
OIL WELL GAS GAS	WELL		OTHER	Inject	ion	Northe	east Drinkard Unit
New Well Workover	Deep	en 🗌 Plug Bac	k 🗌 Diff	. Resvr.	✓ Other		
Name of Operator						8. Well No. 20	7
Apache Corporation						9. Pool name or Wildcat	11
2000 Post Oak Blvd., Ste. 100, Well Location	Houston,	Texas 77056-440	00 / 713-296-	-6000	WFX-774	Eunice N., Blinebry	y-Tubb-Drinkard
Unit Letter N :	2970	Feet From The	South	Line and	2308	Feet From The W	est Line
Section 3 To	wnship	21S	Range	37E	NMPI	A Lea County	
0. Date Spudded 11. Date T.D. Reach	hed 1	2. Date Compl. (Ready to P		13. Eleva	tions (DF& RKB, RT, G		nghead
5 Total Depth 16. Plug Back		3/13/0 17. If Multiple Compl			3458'	GR Rotary Tools	Cable Tools
	6885	Many Zones?	l. How		18. Intervals Drilled By	Rotary 1001s	
P. Producing Interval(s), of this completion - To	p, Bottom, Name					20. Was Direc	tional Survey Made
Blinebry 5819 - 5890	Tubb 6	097 - 6191	Drinkard 6	5555 - 68	313		
1. Type Electric and Other Logs Run						22. Was Well Cored	
J.						.1	
					strings set in	well)	
CASING SIZE WEIGHT I		DEPTH SET	HOLES			NTING RECORD	AMOUNT PULLED
3-3/8 36#		215	17-1/2			lated to Surface	
3-5/8 28#/3	32#	3153	1	1	1600 sx / Circ	ulated to Surface	
			1	· · · · · ·			
4	LINER REC			25.		TUBING RI	
SIZE TOP	BOTTOM	SACKS CEMENT	SCREEN		SIZE	DEPTH SET	PACKER SET
5-1/2 2648	7000	810			2-3/8		5616
6. Perforation record (interval, size,		<u> </u>	<u> </u>	27. AC	ID SHOT FRAC	TURE, CEMENT, SQUI	EFZE ETC
5. Perioration record (interval, size,	, and number)			PTH INTERVAL		ND KIND MATERIAL USED
linebry 5819 - 5890 - 123 Holes							
655 - 5790 (Abandoned)					5655 - 5790	Cement squeezed w/ 3	50 sx
ubb 6097 - 6191 (35 Holes)							31-1242
Orinkard 6555 - 6813 (338 Holes)				· <u> </u>			
				ļ			n v z digitizi) Historia (1997)
				·			E
						Hobbs	
8.		<u> </u>	PRODUC	TION		1	000
ate First Production		Production Method	(Flowing, gas lift,)		e and type pump)	Well S	tatus (Prod. or Shut-in)
0/13/02					<u>.</u>		Injecting
ate of Test Hours Tested	C		n For Period	Oil - Ebl.	Gas - MCF	Water - Bbl.	Gas - Oil Ratio
low Tubing Press. Casing Pressure	Calculated 24 Hour Rate		Gas - M	ICF	Water - Bbl.	·	Oil Gravity - API - (Corr.)
low rubing rices.		<u></u>			I		Test Witnessed By
9. Disposition of Gas (Sold, used for fuel, vented	1, etc.)						
	ц, еас.)						
9. Disposition of Gas (Sold, used for fuel, vented 0. List Attachments C-103 Sundry Notice w/ Chart		· · · · · · · · · · · · · · · · · · ·				****	
 Disposition of Gas (Sold, used for fuel, vented List Attachments 		form is true and complete to		vledge and be	lief		
 Disposition of Gas (Sold, used for fuel, vented List Attachments C-103 Sundry Notice w/ Chart 		form is true and complete to	Printed	vledge and be bra J. A		_Title _Sr. Engineerir	ng Technician Date 4/29

INSTRUCTIONS

This form is to filed with the appropriate District Office of the Division Office not later than 20 days after the completion of any newly-drilled or deepened well. It shall be accompanied by one copy of all electrical and radio-activity logs run on the well and a summary of all special tests conducted, including drill stem tests. All depths reported shall be measured depths. In the case of directionally drilled wells, true vertical depths shall also reported. For multiple completions, items 25 through 29 shall be reported for each zone. The form is to be filed in quintuplicate except on state land, where six copies are required. See Rule 1105.

INDICATE FORMATION TOPS IN CONFORMANCE WITH GEOGRAPHICAL SECTION OF STATE

		Southeastern	New	/ Mexico			Northwestern	New Mexico
T. Anhy	-		Т.	Canyon		T. Ojo Alamo		T. Penn. "B"
T. Salt			Т.	Strawn		T. Kirtland-Frui	itland	T. Penn. "C"
B. Salt			Т.	Atoka		T. Pictured Clif	fs	T. Penn. "D"
T. Yates	·····		Т.	Miss		T. Cliff House		T. Leadville
T. 7 Rivers			Т.	Devonian		T. Menefee		T. Madison
T. Queen			Т.	Silurian		T. Point Lookou	1t	T. Elbert
T. Grayburg	; 		Т.	Montoya		T. Mancos		T. McCracken
T. San Andr	res		<u>.</u> Т.	Simpson		T. Gallup		T. Ignacio Otzte
T. Glorieta		···	Τ.	МсКее		Base Greenhorn	L	T. Granite
T. Paddock			Т.	Ellenburger		T. Dakota		T
T. Blinebry			-	Gr. Wash		T. Morrison		T
T. Tubb			Т.	Delaware Sand		T. Todilto		Т
T. Drinkard			Т.	Bone Springs		T. Entrada		Т
T. Abo			Т.	Rustler		T. Wingate		Т
T. Wolfcam	р <u> </u>		Т.			T. Chinle		Т.
T. Penn			Т.			T. Permain		T.
T. Cisco (Bo	ough C)		Т.			T. Penn "A"		Т.
				OIL OR	GAS SAN	DS OR ZON	ES	
No. 1, from			to		No. 3, from			to
No. 2, from	•••••••••••••••••••••••••••••••••••••••		to		No. 4, from			to
				IMPOR	RTANT WA	ATER SAND	S	
				on to which water ros	se in hole.			
							feet	
No. 2. from				to			feet	
,	•••••		*********					******
No. 3, from	••••••			to			feet	
No. 3, from		·····					feet	
No. 3, from From	То			to			feet	
No. 3, from		Thickness in		IOLOGY RECOR	D (Attach	additional she	feet set if necessary)	
No. 3, from		Thickness in		IOLOGY RECOR	D (Attach	additional she	feet set if necessary)	
No. 3, from		Thickness in		IOLOGY RECOR	D (Attach	additional she	feet set if necessary)	
No. 3, from		Thickness in		IOLOGY RECOR	D (Attach	additional she	feet set if necessary)	
No. 3, from		Thickness in		IOLOGY RECOR	D (Attach	additional she	feet set if necessary)	
No. 3, from		Thickness in		IOLOGY RECOR	D (Attach	additional she	feet set if necessary)	
No. 3, from		Thickness in		IOLOGY RECOR	D (Attach	additional she	feet set if necessary)	
No. 3, from		Thickness in		IOLOGY RECOR	D (Attach	additional she	feet set if necessary)	
No. 3, from		Thickness in		IOLOGY RECOR	D (Attach	additional she	feet set if necessary)	
No. 3, from		Thickness in		IOLOGY RECOR	D (Attach	additional she	feet set if necessary)	
No. 3, from		Thickness in		IOLOGY RECOR	D (Attach	additional she	feet set if necessary)	
No. 3, from		Thickness in		IOLOGY RECOR	D (Attach	additional she	feet set if necessary)	
No. 3, from		Thickness in		IOLOGY RECOR	D (Attach	additional she	feet set if necessary)	
No. 3, from		Thickness in		IOLOGY RECOR	D (Attach	additional she	feet set if necessary)	
No. 3, from		Thickness in		IOLOGY RECOR	D (Attach	additional she	feet set if necessary)	
No. 3, from		Thickness in		IOLOGY RECOR	D (Attach	additional she	feet set if necessary)	
No. 3, from		Thickness in		IOLOGY RECOR	D (Attach	additional she	feet set if necessary)	
No. 3, from		Thickness in		IOLOGY RECOR	D (Attach	additional she	feet set if necessary)	

а.

