

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

310 Old Santa Fe Trail, Room 206
Santa Fe, New Mexico 87503

WELL API NO.	30-025-06521
5. Indicate Type of Lease	FED <input type="checkbox"/> STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101 FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other Water Injector	7. Lease Name or Unit Agreement Name NORTHEAST DRINKARD UNIT
2. Name of Operator SHELL WESTERN E&P INC.	8. Well No. 205W
3. Address of Operator P. O. BOX 1950, HOBBS, NM 88240 505/393-0199	9. Pool name or Wildcat N. EUNICE BLINEBRY-TUBB-DRINKARD
4. Well Location Unit Letter <u>M</u> : <u>3300</u> Feet From The <u>South</u> Line and <u>660</u> Feet From The <u>West</u> Line Section <u>3</u> Township <u>21</u> <u>SOUTH</u> Range <u>37</u> <u>EAST</u> NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT GR, etc.) 3434 [GR]	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG & ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)
SEE RULE 1103.

1. Rig up Pulling Unit. Install BOP.
2. P O H w/tbg & Inj Pkr.
3. R I H w/ 2 1/16" workstring & displace the hole w/mud (1 sx gel/4bbl 9.5# brine)
4. Spot seven 5 sx cmt plugs @6400, 6050, 5550, 3987, 2600, & 1050. Spot 10 sx cmt plug from 350' to 3'
5. Cut casing off 4' below surface and install P&A marker. Clean and level the location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE C. L. Mann TITLE PRODUCTION FOREMAN DATE 02/08/96
TYPE OR PRINT NAME C. L. MANN TELEPHONE NO. 505/393-0209

(This space for State Use)

ORIGINAL SIGNED BY

APPROVED BY GARY WINK TITLE FIELD REP DATE FEB 15 1996

CONDITIONS OF APPROVAL IF ANY:

dp

