		Form C-103
and the second s	P. O. BOX 2088	Revised 10-1-7
BANTA PE	SANTA FE, NEW MEXICO 87501	
PILE		5a. Indicate Type of Lease
U.S.O.S.	-	
LAND OFFICE	-	5. State Oil & Gas Lease No.
OPERATOR		NO
SUND	RY NOTICES AND REPORTS ON WELLS	
USE "APPLICA	ATION FOR PERMIT (FORM C-TOT) FOR BUCH PHOTOSECUL	7. Unit Agreement Name
au (V) •••		NO
weit K weit L	OTHER.	8. Form or Lease Hame
ame of Operator		EUBANKS
J. R. CONE		9. Well No.
ddress of Operator		2
P.O. BOX 10217, LU	UBBOCK, TEXAS 79408	10. Field and Pool, or Wildcat
ocation of Well		DRINKARD
L	1980 FEET FROM THE South LINE AND 660 FEET	
UNIT LETTER	01C 07E	
West	14 <u>21S</u> <u>37E</u>	
THE LINE, SEC		
TIMMIN TIM	15. Elevation (Show whether DF, RT, GR, etc.)	LEA
	3422 DF	
work) SEE RULE 1103.	PLUG AND ABANDON ARMEDIAL WORK (X CHANGE PLANS COMMENCE DRILLING OPNS. CHANGE PLANS CASING TEST AND CEMENT JOB OTHER OTHER CHANGE PLANS CASING TEST AND CEMENT JOB OTHER OTHER OTHER OTHER OTHER DIAL WORK (Clearly state all pertinent details, and give pertinent dates, inc ed from the Drinkard Oil Pool through Drinkard 622 from 5-49 to 3-64 when the zone was abandon	Perfs 6535-45 and
open hole 6567-66 was 3 BOPD, GOR (commingled down to TD and packer stablized at 6 B	7600/1. Well was then produced from Binebry a hole by order No. 5481) In July 1984 the well installed between Tubb and Drinkard perfs, whe OPD, GOR 6500/1. On August 16, 1984 under orde	nd Tubb zones was cleaned out re the Drinkard r No. DHC-473 the bry, Tubb and
open hole 6567-66 was 3 BOPD, GOR (commingled down to TD and packer stablized at 6 B	7600/1. Well was then produced from binneby a hole by order No. 5481) In July 1984 the well installed between Tubb and Drinkard perfs, whe	nd Tubb zones was cleaned out re the Drinkard r No. DHC-473 the bry, Tubb and
open hole 6567-66 was 3 BOPD, GOR (commingled down to TD and packer stablized at 6 B	7600/1. Well was then produced from Binebry a hole by order No. 5481) In July 1984 the well installed between Tubb and Drinkard perfs, whe OPD, GOR 6500/1. On August 16, 1984 under orde	nd Tubb zones was cleaned out re the Drinkard r No. DHC-473 the bry, Tubb and
open hole 6567-66 was 3 BOPD, GOR (commingled down to TD and packer stablized at 6 B	7600/1. Well was then produced from Binebry a hole by order No. 5481) In July 1984 the well installed between Tubb and Drinkard perfs, whe OPD, GOR 6500/1. On August 16, 1984 under orde	nd Tubb zones was cleaned out re the Drinkard r No. DHC-473 the bry, Tubb and
open hole 6567-66 was 3 BOPD, GOR (commingled down to TD and packer stablized at 6 B	7600/1. Well was then produced from Binebry a hole by order No. 5481) In July 1984 the well installed between Tubb and Drinkard perfs, whe OPD, GOR 6500/1. On August 16, 1984 under orde	nd Tubb zones was cleaned out re the Drinkard r No. DHC-473 the bry, Tubb and
open hole 6567-66 was 3 BOPD, GOR (commingled down to TD and packer stablized at 6 B	7600/1. Well was then produced from Binebry a hole by order No. 5481) In July 1984 the well installed between Tubb and Drinkard perfs, whe OPD, GOR 6500/1. On August 16, 1984 under orde	nd Tubb zones was cleaned out re the Drinkard r No. DHC-473 the bry, Tubb and
open hole 6567-66 was 3 BOPD, GOR 3 (commingled down to TD and packer stablized at 6 B packer was remove Drinkard total 3	7600/1. Well was then produced from Binebry a hole by order No. 5481) In July 1984 the well installed between Tubb and Drinkard perfs, whe OPD, GOR 6500/1. On August 16, 1984 under orde ed, 1000 gal Acid was spotted across each Bline 000 gal. and well was returned to production.	nd Tubb zones was cleaned out re the Drinkard r No. DHC-473 the bry, Tubb and
open hole 6567-66 was 3 BOPD, GOR 3 (commingled down to TD and packer stablized at 6 B packer was remove Drinkard total 3	7600/1. Well was then produced from Binebry a hole by order No. 5481) In July 1984 the well installed between Tubb and Drinkard perfs, whe OPD, GOR 6500/1. On August 16, 1984 under orde ed, 1000 gal Acid was spotted across each Bline 000 gal. and well was returned to production.	nd Tubb zones was cleaned out re the Drinkard r No. DHC-473 the bry, Tubb and
open hole 6567-66 was 3 BOPD, GOR 3 (commingled down to TD and packer stablized at 6 B packer was remove Drinkard total 3	7600/1. Well was then produced from Billebry a hole by order No. 5481) In July 1984 the well installed between Tubb and Drinkard perfs, whe OPD, GOR 6500/1. On August 16, 1984 under orde ed, 1000 gal Acid was spotted across each Bline 000 gal. and well was returned to production.	nd Tubb zones was cleaned out re the Drinkard r No. DHC-473 the bry, Tubb and Test to follow.
open hole 6567-66 was 3 BOPD, GOR 3 (commingled down to TD and packer stablized at 6 B packer was remove Drinkard total 3	7600/1. Well was then produced from Billebry a hole by order No. 5481) In July 1984 the well installed between Tubb and Drinkard perfs, whe OPD, GOR 6500/1. On August 16, 1984 under orde ed, 1000 gal Acid was spotted across each Bline 0000 gal. and well was returned to production.	nd Tubb zones was cleaned out re the Drinkard r No. DHC-473 the bry, Tubb and
open hole 6567-66 was 3 BOPD, GOR 3 (commingled down to TD and packer stablized at 6 B packer was remove Drinkard total 3	7600/1. Well was then produced from Billebry a hole by order No. 5481) In July 1984 the well installed between Tubb and Drinkard perfs, whe OPD, GOR 6500/1. On August 16, 1984 under orde ed, 1000 gal Acid was spotted across each Bline 000 gal. and well was returned to production.	nd Tubb zones was cleaned out re the Drinkard r No. DHC-473 the bry, Tubb and Test to follow.