Sul mit 3 Copies to Appropriate District Office

State of New Mexico Energy, rerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

WELL API NO	.		
	30-025-06587	,	
5. Indicate Ty	pe of Lease STATE X	FEE	
6. State Oil &	Gas Lease No.		

SETECT DO LAWER DD, Anteria NM 8210 Santa Fe, New Mexico 87504-2088 5. Indicate Type of Lases STATE X STATE X FEE STATE X 6. Sana Oil & Gia Lases No. SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM POR PROPOSALS TO DRILL OR TO DESPEK OR PLUG BACK TO A (DO NOT USE THIS FORM POR PROPOSALS TO DRILL OR TO DESPEK OR PERMIT (DO NOT USE THIS FORM POR PROPOSALS TO DRILL OR TO DESPEK OR PERMIT (DO NOT USE THIS FORM POR PROPOSALS) TOPE of Well: ONE.	P.O. Box 2088	30-025-06587
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS PORM FOR PROPOSALS TO BRILL ON TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: ONL:	DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 8/50	5. Indicate Type of Lease
(DO NOT USE THIS FORM FOR PROPERSURS TO DRILL OR TO DEEPEN OR PENALTY (FORM C-101) FOR SUCH PROPOSALS) Type of Well ONE Not least Drinkard Unit Northeast Drinkard Northeast Drinkard Unit Northeast Drinkard Northeast Drinkard Northeast Unit Northeast		
Neme of Operator Altura Energy LTD Address of Operator P.O. Box 4294, Houston, TX 77210-4294 **Well Lossing Dail Letter F 3375 Feet From The South Lise and 3225 Feet From The East Lise Section 15 Township 21-S Range 37-E NMFM Lea County 10. Elevation (Show whather DF, REB, RT, GR, stc.) 3775' CR Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: ERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK X ALTERING CASING ULL OR ALTER CASING CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB DITHER: OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all periment databilit, and give periment dates, including estimated data of stating ary proposed worth) SEE RULE 1103. 12/9/97 - 12/19/97: MI x RU pulling unit. RIH with workstring x bit. Drill out CIBP at 4030'. Drill out cement plug from 5501' - 5551'. Drill out CIBP at 5551'. Drill out cement plug from 6410' - 6462'. Drill out CIBP at 6462'. Clean out wellbore to 6777' x POH. RIH with 2-3/8" production tubing x rods x pump. Put well back on production. 1 brevey sortly that the information sown is true and complete to the bot of any incondedge and balled. SHORALIZE MARK Stephens THE Business Analyst (SG) PATE 1/12/98 (281) THE PROPRIATION MARK Stephens AUG 3 1 1996	(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR P DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) Type of Well:	
Address of Operation P.O. Box 4294, Houston, TX 77210-4294 Section F : 3375 Feet From The South Line and 3225 Feet From The East Lies		8. Well No.
Well Lester F : 3375 Feet From The South Line and 3225 Feet From The East Lise Section 15 Township 21-S Range 37-E NMPM Lea County 3775 CR Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMORARILY ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB OTHER: Ca	•	
Well Locause Unix Letter F : 3375 Feet From The South Line and 3225 Feet From The East Liter Section 15	•	
Unit Letter F: 3375 Foot From The South Line and 3225 Feet From The East Line Section 15 Township 21-S Range 37-E NMPM Lea County 10. Elevatica (Show whiteher DF, RKB, RT, GR, ac.) 3775 CR 1. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REPORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB THER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including automated date of starting any proposed work) SEE RULE 103. 12/9/97 - 12/19/97: MI X RU pulling unit. RIH with workstring X bit. Drill out CIBP at 4030'. Drill out cement plug from 5501' - 5551'. Drill out CIBP at 5551'. Drill out CIBP at 6462'. Clean out wellbore to 6777' X POH. RIH with 2-3/8" production tubing X rods X pump. Put well back on production. There are a substantial back on production. The proof results the information above is true and complete to the best of my inconding and ballet. The proof results the information above is true and complete to the best of my inconding and ballet. The proof results the information above is true and complete to the best of my inconding and ballet. The proof results the information above is true and complete to the best of my inconding and ballet. The proof results the information above is true and complete to the best of my inconding and ballet. The proof results the information above is true and complete to the best of my inconding and ballet. The proof results the information above is true and complete to the best of my inconding and ballet. The proof results the information above is true and complete to the best of my inconding and ballet. The proof results the information above is true and complete to the best of my inconding and ballet. The proof results the information above is true and complete to the best of my inconding and ballet. Th		Editice Billiebly-Iubb-blilikald-No.
10. Elevation (Show whether DP, RKB, RT GR, etc.) 3775' CR 1. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REFORM REMEDIAL WORK PLUG AND ABANDON GRANDON		Line and 3225 Feet From The East Line
1. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK		37-E NMPM Lea County
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: ERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: DILL OR ALTER CASING OTHER: DOTHER: DOTHER: DOTHER: DOTHER: DOTHER: DOTHER	///////	Υ/////////////////////////////////////
ERPORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT DILL OR ALTER CASING CASING TEST AND CEMENT JOB OTHER: OTHER: OT	1. Check Appropriate Box to Indicate Natu	re of Notice, Report, or Other Data
COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB CASING TEST AND CEMENT JOB CHER. OTHER:	NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF
CASING TEST AND CEMENT JOB THER: DTHER: DTHER: DT	RFORM REMEDIAL WORK PLUG AND ABANDON RE	MEDIAL WORK X ALTERING CASING
OTHER: 2. Describe Proposed or Completed Operations (Clearly state all pertunent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 12/9/97 - 12/19/97: MI x RU pulling unit. RIH with workstring x bit. Drill out CIBP at 4030'. Drill out cement plug from 5501' - 5551'. Drill out CIBP at 5551'. Drill out cement plug from 6410' - 6462'. Drill out CIBP at 6462'. Clean out wellbore to 6777' x POH. RIH with 2-3/8" production tubing x rods x pump. Put well back on production. 1 hereby ceruly that the information above is true and complete to the best of my incovinde and belief. SKINATURE MARK Stephens TITLE Business Analyst (SG) DATE 1/12/98 (281) TELEPHONE NO. 552-1158 CHIMS SPACE SCALED BY CHRIS WILLIAMS ORIGINAL SCALED BY CHRIS WILLIAMS ORIGINAL SCALED BY CHRIS WILLIAMS ORIGINAL SCALED BY CHRIS WILLIAMS	EMPORARILY ABANDON CHANGE PLANS CO	MMENCE DRILLING OPNS. PLUG AND ABANDONMENT
2. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 12/9/97 - 12/19/97: MI x RU pulling unit. RIH with workstring x bit. Drill out CIBP at 4030'. Drill out cement plug from 5501' - 5551'. Drill out CIBP at 5551'. Drill out cement plug from 6410' - 6462'. Drill out CIBP at 6462'. Clean out wellbore to 6777' x POH. RIH with 2-3/8" production tubing x rods x pump. Put well back on production. 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. SIONATURE	JLL OR ALTER CASING CA	SING TEST AND CEMENT JOB
12/9/97 - 12/19/97: MI x RU pulling unit. RIH with workstring x bit. Drill out CIBP at 4030'. Drill out cement plug from 5501' - 5551'. Drill out CIBP at 5551'. Drill out cement plug from 6410' - 6462'. Drill out CIBP at 6462'. Clean out wellbore to 6777' x POH. RIH with 2-3/8" production tubing x rods x pump. Put well back on production. 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE MARK Stephens TYPE OR FRINT NAME MARK Stephens MARK Stephens AUG 3 1 1996 ORIGINAL SIGNAL SIGNAL SHALES WILLIAMS ORIGINAL SIGNAL SHALES WILLIAMS ORIGINAL SIGNAL SHALES WILLIAMS	THER: OT	HER:
Signature Mark Stephens Title Business Analyst (SG) Date 1/12/98 (281) Telephone no. 552-1158 Original Signal Stocked Bey Christ Williams Original Stocked Bey Christ Williams Christ Stocked Bey Christ Stocked Bey Christ Williams Christ Stocked Bey Christ Stocked	work) SEE RULE 1103. 12/9/97 - 12/19/97: MI x RU pulling unit. RIH w:	ith workstring x bit. Drill out CIBP at
SKINATURE Mark Stephens TITLE Business Analyst (SG) DATE 1/12/98 (281) (281) TELEPHONE NO. 552-1158 ORIGINAL SIGNED BY CHRIS WILLIAMS ORIGINAL SIGNED BY CHRIS WILLIAMS	5551'. Drill out cement plug 6462'. Clean out wellbore to	g from 6410' - 6462'. Drill out CIBP at o 6777' x POH. RIH with 2-3/8" production
ORIGINAL SIGNED BY CHRIS WILLIAMS AUG 3 1 1990	SIGNATURE Mark Stephens TITLE	Business Analyst (SG) DATE 1/12/98
	ORIGINAL SIGNED BY CHRIS WILLIAMS	AUG 3 1 1998

