

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-06592
5. Indicate Type of Lease	STATE ☐ FEE ☒
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	
NORTHEAST DRINKARD UNIT	
8. Well No.	706
9. Pool name or Wildcat	NORTH EUNICE BLINEBRY-TUBB- DRINKARD OIL & GAS
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	
3418' GR	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☐ GAS WELL ☒ OTHER	2. Name of Operator SHELL WESTERN E&P INC.
3. Address of Operator P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)	4. Well Location Unit Letter <u>J</u> : <u>1980</u> Feet From The <u>SOUTH</u> Line and <u>1980</u> Feet From The <u>EAST</u> Line Section <u>15</u> Township <u>21S</u> Range <u>37E</u> NMPM <u>LEA</u> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3418' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: <u>OAP & Acdz</u> ☒	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Kill well w/9# brine. Rel Baker Lok-set PKR @ 6149' & scanalog Htg OOH.
2. CO to 6432' (PBTD).
3. Run GR/CCL from PBTD to 5500'.
4. Perf Tubb 6083' - 6411' (2 JSPF).
5. Acdz perfs 6083' - 6411' w/4704 gals 15% NEFE HCl + 900# rock salt + 108 ball sealers.
6. TIH w/prod equip.
7. Swab well until well kicks off. Flow to pit until cln gas is prod. Open prod line to Northern Natural Gas Co. prod line.
8. Once prod has stabilized, perform NMOCN multi-pt tst.

NOTE: We currently plan to tst the Tubb gas zn first, then when adequate data is gathered the Blinebry gas zn will be opnd and dually completed w/ the Tubb.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. H. SMITHERMAN TITLE REGULATORY SUPV. DATE 1-08-90
TYPE OR PRINT NAME J. H. SMITHERMAN (713) 870-3797 TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

JAN 16 1990