NO. OF COPIES RECEIVED		Form C-103
DISTRIBUTION	. O. C.	Supersedes Old
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
FILE		
U.S.G.S.	100 M 166	Sa. Indicate Type of Lease
LAND OFFICE	Fixed 4	State Fee X
OPERATOR		5. State Oil & Gas Lease No.
		Fee
	CHARDY MOTICES AND DEDODES OF ME	mmmmink
(DO NOT USE THIS	SUNDRY NOTICES AND REPORTS ON WELLS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.	
1.	SE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
OIL GA	AS OTHER-	7. Unit Agreement Name NONE
2. Name of Operator	· · · · · · · · · · · · · · · · · · ·	8. Form or Lease Name
	TEXACO Inc.	Mittie Weatherly
3. Address of Operator	P. O. Box 728 - Hobbs, New Mexico	9. Well No.
4. Location of Well	r. U. DOX 120 - HODDS, New Mexico	1
	7080 Nowth 7080	10. Field and Pool, or Wildcat Drinkard
UNIT LETTER	. 1980 FEET FROM THE North LINE AND 1980 FEET FROM	THE DITTING TO
West	LINE, SECTION 17 TOWNSHIP 21-S RANGE 37-E NMPM.	
	TING, DECTION TOWNSHIP RANGE NMPM.	
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
		Lea
16.	Check Appropriate Box To Indicate Nature of Notice, Report or Otl	ner Data
NOT	7100 A = 11100 - 11101 - 11101 - 11101 - 11101 - 11101 - 11101 - 11101 - 11101 - 11101 - 11101 - 11101 - 11101	REPORT OF:
_		
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	
	OTHER	
OTHER		
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed		
work) SEE RULE 103.		
We propose to do the following work on subject well:		
1. Pull tubing, and set retrievable bridge plug at 6570.		
1. Tull bubling, and set redirevable bridge prug at 05/0.		
2. Perforate 5 1/2" Casing, Drinkard pool, with two jet shots at 6440',		
6450', 6483', 6500', 6508', 6511', 6542', and 6558'. (Approximate)		
· · · · · · · · · · · · · · · · · · ·		
	Acidize perforations with 2000 gals. 15% NE acid in two	stages with
	eight ball sealers between stages.	
4.	Frac with 10,000 gals lease crude, and 10,000 pounds say	nd -
4.	11do with 10,000 gain 10abo of ada, and 10,000 pounds out	
5.	Swab well, recover load oil, test, place well on product	tion.
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
11 / 1-11 11		
SIGNED COM	Assistant District	DATE August 29, 1966
		JAIE 377
/ pan (Superintendent	

CONDITIONS OF APPROVAL, IF ANY:

