Process Minerals and Natural Resources Process Minerals	Substit + Copies To Apprepriate District Other	State of New Mexico		Form C-103	
Substitute State	(6/5/8) For cli Dr., Hobbs, NM 87240		ital Resources	WELL APINO.	
SIATE FIEL X	S11 South Lust, Artesia, NM 87210	- 111		5. Indicate Type of Lease	
Stable Pagency Small Fr, MRT495 Stable Not Provided From the Stable Not Provided Colliptor Stable Not Inches Not Inches Not Provided Colliptor Stable Not Inches No	1000 Rio Biazos Rd., Aztec, NM 87410	1000 Rio Binzos Rd., Aztec, NM 87410 Supto Fo. NIM 975.05			
DISTRICTS FOR PROPERSIAN TO DRIFT OF PROPERSIAN TO DEPTH NOR PLEGRACK TO A DIFFER STARS WELL BY A DISTRICT ON PROPERTY. TO AND A DISTRICT OF PROPERTY. TO	TO THE PARTY OF TH			6. State Oil & Gas Lease No.	
1 type of Well Gas Well Other Stephens & Johnson Operating Co. S. Well No. Stephens & Johnson Operating Co. S. Well No. Stephens & Johnson Operating Co. 9. Pool name or Wildcat P. Jo. Box 2249 Wichita Falls, TX 76307-2249 9. Pool name or Wildcat P. Johnson Operating Co.	(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit Agreement Name:	
2. Name of Operator Stephens & Johnson Operating Co. 3. Address of Operator P.O. Box 2249 Wichita Falls, TX 76307-2249 4. Well Location Unit Letter E 1980 feet from the North line and 550 feet from the West line Section 21 Township 218 Range 37E NMPM County Lea 10. Elevation (Show whether DR. RKE, RT, GR. etc.) 3485 DF 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NoTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT TEMPORARILY ABANDON CHANGE PLANS COMPLETION OTHER: 12. Describe proposed or completed operations. (Clearly state all pertunent details, and give pertunent dates, including estimated day of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompliation 9-20-97 Perforated additional Blinebry zones 5610-5624, 5640-5648, 5738-5743, 5822-5828, 5936-5938, 5969-5976, 5981-5983, 5987-5993, 6000-6003, 6008-6012, 6020-6028, 6032-6036, 6040-6048, 6072-6092, 6107-6113, 6132-6137, 6230-6240, 6244-6258, 6262-6266. Acidized w/1500 gals Ferchek acid, lost pkr & RBP in hole w/parted type. Fished & milled pkr & type, could not fish RBP & left RBP & 6305'. Set CIBP & 6304'. POP. 12-05-97 Frac 5610-6266 perfs w/210,000 lbs. 20/40 sand & 90,000 gals gelled KCL water. POP. 12-05-97 Frac 5610-6266 perfs w/210,000 lbs. 20/40 sand & 90,000 gals gelled KCL water. POP.	1. Type of Well:			Weatherly Lease	
3. Address of Operator P.O. Box 2249 Wichita Falls, TX 76307-2249 9. Pool name or Wildcat Blinebry & Drinkard	2. Name of Operator			8. Well No.	
P.O. Box 2249 Wichita Falls, TX 76307-2249 Well Location Unit Letter E 1980 feet from the North line and 550 feet from the West line		perating Co.			
Unit Letter E 1980 feet from the North line and 550 feet from the West line Section 21 Township 21S Range 37E NMPM County Lea 10. Elevation (Show whether DR. RKB, RT. GR. ec.) 3.485 DF 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING PULL OR ALTER CASING MULTIPLE COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE COMPLETION Perforate additional Blinebry zones & MULTIPLE COMPLETION Perforate additional Blinebry zones & MULTIPLE Of HER: stimulate. Plug off Drinkard zone of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 9-20-97 Perforated additional Blinebry zones 5610-5624, 5640-5648, 5738-5743, 5822-5828, 5936-5938, 5969-5976, 5981-5983, 5987-5993, 6000-6003, 6008-6012, 6020-6028, 6032-6036, 6040-6048, 6072-6092, 6107-6113, 6132-6137, 6230-6240, 6244-6258, 626-6266. AcidIzed w/1500 gals Ferchek acid, lost pkr & RBP in hole w/parted tbg. Fished & milled pkr & tbg, could not fish RBP & left RBP & 6305'. Set CIBP & 6304'. POP. 11. Petroleum Engineer DATE 5-23-01 Type or print name Bob Gilmore TITLE Petroleum Engineer DATE 5-23-01 Type or print name Bob Gilmore TITLE Petroleum Engineer DATE 5-23-01 Type or print name Bob Gilmore TITLE Petroleum Engineer DATE 5-23-01 Type or print name Bob Gilmore TITLE Petroleum Engineer DATE 5-23-01	P.O. Box 2249 Wichita				
Section 21 Township 21S Range 37E NMPM County Lea 10. Elevation (Show whether DR. RKB, RT. GR. etc.) 3485 DF 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND ABANDONMENT COMPLETION CASING TEST AND COMPLETION CASING TEST AND COMPLETION OTHER: STIMULate, Plug off Drinkard zone 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated dat/ CIBP- of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 9-20-97 Perforated additional Blinebry zones 5610-5624, 5640-5648, 5738-5743, 5822-5828, 5936-5938, 5969-5976, 5981-5983, 5987-5993, 6000-6003, 6008-6012, 6020-6028, 6032-6036, 6040-6048, 6072-6092, 6107-6113, 6132-6137, 6230-6240, 6244-6258, 6262-6266. AcidIzed w/1500 gals Ferchek acid, lost pkr & RBP in hole w/parted thg. Fished & milled pkr & tbg, could not fish RBP & left RBP @ 6305'. Set CIBP @ 6304'. POP. 12-05-97 Frac 5610-6266 perfs w/210,000 lbs. 20/40 sand & 90,000 gals gelled KCL water. POP. Thereby certify that the information above is fact we complete to the best of my knowledge and belief. SIGNATURE TITLE Petroleum Engineer DATE 5-23-01. Type or prior name Bob Gilmore TITLE Petroleum Engineer DATE 5-23-01. Type or prior name Bob Gilmore TITLE Petroleum Engineer DATE 5-23-01. Type or prior name Bob Gilmore TITLE Petroleum Engineer DATE 5-23-01.	4. Well Location				
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3485 DF	Unit Letter E : 1980 feet from the North line and 550 feet from the West line				
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3485 DF	Section 21	Township 21S R	ange 37E	NMPM County Lea	
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO. PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT TOTHER: COMPLETION CEMENT JOB Perforate additional Blinebry zones & OTHER stimulate. Plug off Drinkard zone of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 9-20-97 Perforated additional Blinebry zones 5610-5624, 5640-5648, 5738-5743, 5822-5828, 5936-5938, 5969-5976, 5981-5983, 5987-5993, 6000-6003, 6008-6012, 6020-6028, 6032-6036, 6040-6048, 6072-6092, 6107-6113, 6132-6137, 6230-6240, 6244-6258, 6262-6266. Acidized w/1500 gals Ferchek acid, lost pkr & RBP in hole w/parted tbg. Fished & milled pkr & tbg, could not fish RBP & left RBP & 6305'. Set CIBP & 6304'. POP. 12-05-97 Frac 5610-6266 perfs w/210,000 lbs. 20/40 sand & 90,000 gals gelled KCI, water. POP. Thereby certify that the information above is now we complete to the best of my knowledge and belief. SIGNATURE: TITLE Petroleum Engineer DATE 5-23-01. Type or prant name Bob Gilmore Telephone No 940-723-2166 (This space for State ase)	10. Elevation (Show whether DR, RKB, RT, GR, etc.)				
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: Petrolate additional Blinebry zones & COMPLETION 12. Describe proposed or completed operations. (Clearly state all pertinent datas, including estimated data CIBP. of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 9-20-97 Perforated additional Blinebry zones 5610-5624, 5640-5648, 5738-5743, 5822-5828, 5936-5938, 5969-5976, 5981-5983, 5987-5993, 6000-6003, 6008-6012, 6020-6028, 6032-6036, 6040-6048, 6072-6092, 6107-6113, 6132-6137, 6230-6240, 6244-6258, 6262-6266. Actidized w/1500 gals Ferchek acid, lost pkr & RBP in hole w/parted tbg. Pished & milled pkr & tbg, could not fish RBP & left RBP & 6305'. Set CIBP & 6304'. POP. 12-05-97 Frac 5610-6266 perfs w/210,000 lbs. 20/40 sand & 90,000 gals gelled KCL water. POP. Thereby certify that the information above is the wat complete to the best of my knowledge and belief. SIGNATURE TITLE Petroleum Engineer DATE 5-23-01. Type or print name Bob Gilmore Telephone No 940-723-2166 (This space for State use)					
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB Perforate additional Blinebry zones & OTHER: stimulate. Plug off Drinkard zone Complete operations. (Clearly state all pertinent details, and give pertinent dates, including estimated dark of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 9-20-97 Perforated additional Blinebry zones 5610-5624, 5640-5648, 5738-5743, 5822-5828, 5936-5938, 5969-5976, 5981-5983, 5987-5993, 6000-6003, 6008-6012, 6020-6028, 6032-6036, 6040-6048, 6072-6092, 6107-6113, 6132-6137, 6230-6240, 6244-6258, 6262-6266. Acidized w/1500 gals Ferchek acid, lost pkr & RBP in hole w/parted tbg. Fished & milled pkr & tbg, could not fish RBP & left RBP @ 6305'. Set CIBP @ 6304'. POP. 12-05-97 Frac 5610-6266 perfs w/210,000 lbs. 20/40 sand & 90,000 gals gelled KCL water. POP. Thereby certify that the information above is fixe wat complete to the best of my knowledge and belief. SIGNATURE TITLE Petroleum Engineer DATE 5-23-01 Type or print name Bob Gilmore Telephone No 940-723-2166 (This space for State use)					
OTHER: COMPLETION CEMENT JOB Perforate additional Blinebry zones & OTHER: stimulate. Plug off Drinkard zone 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 9-20-97 Perforated additional Blinebry zones 5610-5624, 5640-5648, 5738-5743, 5822-5828, 5936-5938, 5969-5976, 5981-5983, 5987-5993, 6000-6003, 6008-6012, 6020-6028, 6032-6036, 6040-6048, 6072-6092, 6107-6113, 6132-6137, 6230-6240, 6244-6258, 6262-6266. Acidized w/1500 gals Ferchek acid, lost pkr & RBP in hole w/parted tbg. Fished & milled pkr & tbg, could not fish RBP & left RBP @ 6305'. Set CIBP @ 6304'. POP. 12-05-97 Frac 5610-6266 perfs w/210,000 lbs. 20/40 sand & 90,000 gals gelled KCL water. POP. Thereby certify that the information above is the set of my knowledge and belief. SIGNATURE TITLE Petroleum Engineer DATE 5-23-01 Type or print name Bob Gilmore TITLE Petroleum Engineer Telephone No 940-723-2166 TITLE DATE Type or print name Bob Gilmore TITLE DATE TITLE DATE					
OTHER: Perforate additional Blinebry zones & OTHER: stimulate. Plug off Drinkard zone Power of Starting any proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of Starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 9-20-97 Perforated additional Blinebry zones 5610-5624, 5640-5648, 5738-5743, 5822-5828, 5936-5938, 5969-5976, 5981-5983, 5987-5993, 6000-6003, 6008-6012, 6020-6028, 6032-6036, 6040-6048, 6072-6092, 6107-6113, 6132-6137, 6230-6240, 6244-6258, 6262-6266. Acidized w/1500 gals Ferchek acid, lost pkr & RBP in hole w/parted tbg. Fished & milled pkr & tbg, could not fish RBP & left RBP @ 6305'. Set CIBP @ 6304'. POP. 12-05-97 Frac 5610-6266 perfs w/210,000 lbs. 20/40 sand & 90,000 gals gelled KCL water. POP. Thereby certify that the information above is the war complete to the best of my knowledge and belief. SIGNATURE DATE 5-23-01 Type or print name Bob Gilmore Telephone No 940-723-2166 (This space for State use)					
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 9-20-97 Perforated additional Blinebry zones 5610-5624, 5640-5648, 5738-5743, 5822-5828, 5936-5938, 5969-5976, 5981-5983, 5987-5993, 6000-6003, 6008-6012, 6020-6028, 6032-6036, 6040-6048, 6072-6092, 6107-6113, 6132-6137, 6230-6240, 6244-6258, 6262-6266. Acidized w/1500 gals Ferchek acid, lost pkr & RBP in hole w/parted tbg. Fished & milled pkr & tbg, could not fish RBP & left RBP @ 6305'. Set CIBP @ 6304'. POP. 12-05-97 Frac 5610-6266 perfs w/210,000 lbs. 20/40 sand & 90,000 gals gelled KCL water. POP. Title Petroleum Engineer DATE 5-23-01 Type or priot name Bob Gilmore Telephone No.940-723-2166 (This space for State use)		COMPLETION		dditional Dlimahaa aasaa f	
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 9-20-97 Perforated additional Blinebry zones 5610-5624, 5640-5648, 5738-5743, 5822-5828, 5936-5938, 5969-5976, 5981-5983, 5987-5993, 6000-6003, 6008-6012, 6020-6028, 6032-6036, 6040-6048, 6072-6092, 6107-6113, 6132-6137, 6230-6240, 6244-6258, 6262-6266. Acidized w/1500 gals Ferchek acid, lost pkr & RBP in hole w/parted tbg. Fished & milled pkr & tbg, could not fish RBP & left RBP @ 6305'. Set CIBP @ 6304'. POP. 12-05-97 Frac 5610-6266 perfs w/210,000 lbs. 20/40 sand & 90,000 gals gelled KCL water. POP. Thereby certify that the information above is the water complete to the best of my knowledge and belief. SIGNATURE TITLE Petroleum Engineer DATE 5-23-01 Type or print name Bob Gilmore Telephone No 940-723-2166 (This space for State use)	OTHER: Stimulate, Plus off Drinkard zone X.				
5936-5938, 5969-5976, 5981-5983, 5987-5993, 6000-6003, 6008-6012, 6020-6028, 6032-6036, 6040-6048, 6072-6092, 6107-6113, 6132-6137, 6230-6240, 6244-6258, 6262-6266. Acidized w/1500 gals Ferchek acid, lost pkr & RBP in hole w/parted tbg. Fished & milled pkr & tbg, could not fish RBP & left RBP @ 6305'. Set CIBP @ 6304'. POP. 12-05-97 Frac 5610-6266 perfs w/210,000 lbs. 20/40 sand & 90,000 gals gelled KCL water. POP. Thereby certify that the information above is the vor complete to the best of my knowledge and belief. SIGNATURE TITLE Petroleum Engineer DATE 5-23-01 Type or print name Bob Gilmore Telephone No 940-723-2166 (This space for State use)	of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion				
Thereby certify that the information above is the unicomplete to the best of my knowledge and belief. SIGNATURE Type or print name Bob Gilmore TITLE Petroleum Engineer Telephone No.940-723-2166 (This space for State use) APPPROVED BY TITLE DATE DATE	5936-5938, 5969-5976, 5981-5983, 5987-5993, 6000-6003, 6008-6012, 6020-6028, 6032-6036, 6040-6048, 6072-6092, 6107-6113, 6132-6137, 6230-6240, 6244-6258, 6262-6266. Acidized w/1500 gals Ferchek acid, lost pkr & RBP in hole w/parted tbg. Fished & milled pkr &				
TITLE Petroleum Engineer DATE 5-23-01 Type or print name Bob Gilmore Telephone No.940-723-2166 (This space for State use) APPPROVED BY TITLE DATE DATE					
TITLE Petroleum Engineer DATE 5-23-01 Type or print name Bob Gilmore Telephone No.940-723-2166 (This space for State use) APPPROVED BY TITLE DATE DATE					
TITLE Petroleum Engineer DATE 5-23-01 Type or print name Bob Gilmore Telephone No.940-723-2166 (This space for State use) APPPROVED BY TITLE DATE DATE					
Type or print name Bob Gilmore Telephone No.940-723-2166 (This space for State use) APPPROVED BY TITLE DATE					
Type or print name Bob Gilmore Telephone No.940-723-2166 (This space for State use) APPPROVED BY TITLE DATE	SIGNATURE SALE SHOW TITLE Petroleum Engineer DATE 5-23-01				
(This space for State use) APPPROVED BY	Type or print name Bob Gilm				
APPPROVED BY TITLE DATE					
	APPPROVED BY	TITLE		DATE	